

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO.201119451E

Not Attached
den
17/2/20
4530
2/53
6 hrs.

M/S : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD #16-01
CITY HOUSE
Singapore 068877
TEL: 65073848 FAX: 65073849
ATTN: Motor Claim Department
Your Ref No: 19/FC/TP-034(12)
Claim Type: Third Party
Accident Date: 12/02/2020
TP Veh Reg No: SHC185P

Estimate No: EST0005335
Date: 13 Feb 2020
Policy No: MA006811
Veh Reg No: GBC3368E
Make/Model: NISSAN CABSTAR
Chasis No: 0JN1SC2P24
Engine No:
Reg. Date:

Estimate Repair Cost to Vehicle No :GBC3368E

Description	Quantity	List Price	Amount
		SS	SS
Net Price			
1 FRT WINDSCREEN MOULDING 77 X	1 PC	420.00 X	
2 FRT PANEL 304620 N/C	1 PC	1,580.90 X	
3 FRT PANEL "CABSTAR" PLATE 11 X	1 PC	38.00 X	
4 FRT GRILLE en	1 PC	461.90	
5 GRILLE CENTRE LOGO N/C	1 PC	60.00	
6 GRILLE CLIPS en	6 PC	33.00	
7 FRT BUMPER 7011 945.10	1 PC	1,155.10	
8 HEADLAMP N/C 12 C 473.40	2 PC	1,037.00 12 C	
9 RH HEADLAMP LOWER TRIM N/C 12 C 40.65	1 PC	81.30 12 C	
10 FRT RH CORNER PANEL 70 389.90	1 PC	436.30	
11 FRT RH DOOR PILLAR R X	1 PC	1,842.40 X	
12 FRT CABIN BRACKET L X	1 PC	502.40 X	
		7,648.30	
	Less 10%	764.83	6,883.27
Special Net			
13 ENGINE MOUNTING 7011	2 PC	183.20	
14 RADIATOR Butlers	1 PC	792.90	
15 RADIATOR FAN CLUTCH 7011	1 PC	533.00	
16 RADIATOR MOTOR COWLING en	2 PC	173.80	
17 RADIATOR FAN BLADE en	1 PC	260.90	
18 GEARBOX MOUNTING 7011	1 PC	97.90	
19 AIRCON LIQUID PIPE 7011 N/C	1 PC	229.50 X	
20 AIRCON DISCHARGE PIPE N/C	1 PC	249.50 X	
21 FRT WINDSCREEN GUM 7011	1 PC	60.00 40 X	
22 NUMBER PLATE 7011 N/C	1 PC	25.00 55 X	
23 RADIATOR COOLANTS en	1 PC	20.00	
24 FRT RH DOOR COMPANY STICKER en	1 PC	20.00	
		2,645.70	2,645.70
Labour			
25 WIRE CHECKING	1 UNIT	30.00 20	
26 REMOVE & REFIX FRT WINDSCREEN	1 UNIT	120.00 11 X	
27 REMOVE & REFIX DASHBOARD	1 UNIT	250.00 11 X	
28 REMOVE & REFIX 1 SET ENGINE MOUNTING	1 UNIT	180.00 50	
29 LABOUR CHARGE	1 UNIT	1,000.00 600	
30 SPRAY PAINTING	1 UNIT	900.00 700 600	
		2,480.00	2,480.00

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

M/S: MS FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD #16-01

CITY HOUSE

Singapore 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

Your Ref No: 19/FC/TP-034(12)

Claim Type: Third Party

Accident Date: 12/02/2020

TP Veh Reg No: SHC185P

Estimate No: EST0005335

Date: 13 Feb 2020

Policy No: MA006811

Veh Reg No: GBC3368E

Make/Model: NISSAN CABSTAR

Chassis No: 0

Engine No:

Reg. Date:

Estimate Repair Cost to Vehicle No :GBC3368E

Description	Quantity	List Price	Amount
		SS	SS
	Total		SS 12,008.97
	Add GST @ 7%		840.63
	Total Amount Payable		SS 12,849.60

TOTAL: SINGAPORE DOLLAR TWELVE THOUSAND EIGHT HUNDRED FORTY NINE AND CENTS SIXTY ONLY

For SME Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-2603.95
102
1-2163.54
S.N-2081.70
L-1270.00
S. S.N 180.00
5695.24
20
4526

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
 TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
 GST:201119451E RCB NO:201119451E

M/S : MS FIRST CAPITAL INSURANCE LIMITED
 36 ROBINSON ROAD #16-01

CITY HOUSE

Singapore 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

Your Ref No: 19/FC/TP-034(12)

Claim Type: Third Party

Accident Date: 12/02/2020

TP Veh Reg No: SHC185P

Estimate No: EST0005335

Date: 13 Mar 2020

Policy No: MA006811

Veh Reg No: GBC3368E

Make/Model: NISSAN CABSTAR

Chasis No: 0

Engine No:

Reg. Date:

Estimate Repair Cost to Vehicle No :GBC3368E

Description	Quantity	List Price	Amount
		<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair			
Special Net			
1 FRT RH DOOR COMPANY ADVERTISEMENT STICKER	1 PC	180.00	180.00
		180.00	180.00
Labour			
2 REPAIR WIRE HARNESS AND REPLACE SOCKETS	1 UNIT	150.00	150.00
		150.00	150.00
Total			S\$ 330.00
GST Amount			S\$ 23.10
Total Amount Payable			S\$ 353.10

For SME Motor Pte Ltd

AUTHORISED SIGNATURE

List 5303.50
 -10% 4773.15
 SN 2546.20
 LC 2500
 9819.35
 45 7.850
 =

12/03/2020