

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

*Not Attached
dhr
17/2/20
d/s
Oky.*

M/S : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD #16-01

CITY HOUSE

Singapore 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

Your Ref No: 19/FC/TP-034(12)

Claim Type: Third Party

Accident Date: 12/02/2020

TP Veh Reg No: SHC185P

Estimate No: EST0005335

Date: 13 Feb 2020

Policy No: MA006811

Veh Reg No: GBC3368E

Make/Model: NISSAN CABSTAR

Chasis No: 0

Engine No:

Reg. Date:

Estimate Repair Cost to Vehicle No :GBC3368E

Description	Quantity	List Price	Amount
Net Price		<u>SS</u>	<u>SS</u>
1 FRT WINDSCREEN MOULDING <i>neu ✓ 3</i>	1 PC	420.00	
2 FRT PANEL <i>body</i>	1 PC	1,580.90	
3 FRT PANEL "CABSTAR" PLATE <i>neu ✓</i>	1 PC	38.00	
4 FRT GRILLE <i>neu ✓</i>	1 PC	461.90	
5 GRILLE CENTRE LOGO <i>neu ✓</i>	1 PC	60.00	
6 GRILLE CLIPS <i>neu ✓</i>	6 PC	33.00	
7 FRT BUMPER <i>To.1 ✓</i>	1 PC	1,155.10	
8 HEADLAMP <i>neu o/s one 1pc</i>	2 PC	1,037.00	
9 RH HEADLAMP LOWER TRIM <i>neu o/s one 1pc</i>	1 PC	81.30	
10 FRT RH CORNER PANEL <i>neu ✓</i>	1 PC	436.30	
11 FRT RH DOOR PILLAR <i>neu ✓</i>	1 PC	1,842.40	
12 FRT CABIN BRACKET <i>neu ✓</i>	1 PC	502.40	
		7,648.30	
	Less 10%	764.83	6,883.27
Special Net			
13 ENGINE MOUNTING <i>neu ✓</i>	2 PC	183.20	
14 RADIATOR <i>?</i>	1 PC	792.90	
15 RADIATOR FAN CLUTCH <i>?</i>	1 PC	533.00	
16 RADIATOR MOTOR COWLING <i>neu ✓</i>	2 PC	173.80	
17 RADIATOR FAN BLADE <i>neu ✓</i>	1 PC	260.90	
18 GEARBOX MOUNTING <i>neu ✓</i>	1 PC	97.90	
19 AIRCON LIQUID PIPE <i>?</i>	1 PC	229.50	
20 AIRCON DISCHARGE PIPE <i>?</i>	1 PC	249.50	
21 FRT WINDSCREEN GUM <i>neu ✓</i>	1 PC	60.00	
22 NUMBER PLATE <i>neu ✓</i>	1 PC	25.00	
23 RADIATOR COOLANTS <i>neu ✓</i>	1 PC	20.00	
24 FRT RH DOOR COMPANY STICKER <i>neu ✓</i>	1 PC	20.00	
		2,645.70	2,645.70
Labour			
25 WIRE CHECKING	1 UNIT	30.00	
26 REMOVE & REFIX FRT WINDSCREEN	1 UNIT	120.00	
27 REMOVE & REFIX DASHBOARD	1 UNIT	250.00	
28 REMOVE & REFIX 1 SET ENGINE MOUNTING	1 UNIT	180.00	
29 LABOUR CHARGE	1 UNIT	1,000.00	
30 SPRAY PAINTING	1 UNIT	900.00	
		2,480.00	2,480.00

SME Motor Pte Ltd

1 Kaki Bukit Ave 6, #02-15 Autobay@KakiBukit Singapore 417883
TEL: 67476106 (6 lines) FAX: 67442368 Email: service@smemotor.com.sg
GST:201119451E RCB NO:201119451E

M/S : MS FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD #16-01

CITY HOUSE

Singapore 068877

TEL: 65073848

FAX: 65073849

ATTN: Motor Claim Department

Your Ref No: 19/FC/TP-034(12)

Claim Type: Third Party

Accident Date: 12/02/2020

TP Veh Reg No: SHC185P

Estimate No: EST0005335

Date: 13 Feb 2020

Policy No: MA006811

Veh Reg No: **GBC3368E**

Make/Model: NISSAN CABSTAR

Chasis No: 0

Engine No:

Reg. Date:

Estimate Repair Cost to Vehicle No :GBC3368E

Description	Quantity	List Price	Amount
		SS	SS
		Total	SS 12,008.97
		Add GST @ 7%	840.63
		Total Amount Payable	SS 12,849.60

TOTAL: SINGAPORE DOLLAR TWELVE THOUSAND EIGHT HUNDRED FORTY NINE AND CENTS SIXTY ONLY

For SME Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: