

Steve (LKK)  
83228813

W/L P/W/L  
14/2/20, 11.30am  
3 days

L/S  
Ry AL SJ



陳林摩哆私人有限公司  
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365  
Tel : 68585151 ( 24 Hours ) Fax : 68580877  
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SMN1364R  
Date of Accident : 16 January 2020

Messrs BIS Motoring Pte Ltd

Date : 13 February 2020

Estimate To Repair SLX5169X - KIA CARENS 1.7 DCT DIESEL 5DR FWD  
Chassis No : KNAHU815VJ7203667

S/No	Quantity	Description	Amount
<u>LIST ITEMS</u>			
01	1 pc	front bumper / OO	\$ 695.00
02	8 ps	front bumper clips @ \$4.50 / MC	\$ 36.00
03	1 pc	front bumper lower / CUT	\$ 49.00
04	1 pc	front bumper fog lamp o/s X	\$ 206.00
05	1 pc	front bumper fog lamp garnish o/s / CUT	\$ 119.00
06	2 ps	front bumper side retainers @ \$28.00 / DR	\$ 56.00
07	1 pc	n/s headlamp / CUT	\$ 1,558.00
08	1 pc	n/s headlamp bracket ?	\$ 20.00
09	1 pc	front bumper foam ?	\$ 68.00
10	1 pc	front bumper beam ?	\$ 389.00
11	1 pc	front bumper top inner garnish X	\$ 68.00
12	4 ps	front bumper top inner garnish clips @ \$4.50 X	\$ 18.00
13	1 pc	radiator grille with chrome outer / DR	\$ 428.00
14	1 pc	air duct n/s X	\$ 128.00
15	1 pc	front bumper emblem badge / MC	\$ 51.00
			\$ 3,889.00
Less 10 %			\$ 388.90
			\$ 3,500.10
<u>SPECIAL NETT ITEMS</u>			
16	1 pc	front number plate / DR	\$ 50.00
			\$ 50.00
<u>LABOUR &amp; MISC. CHARGES</u>			
01		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 500.00
02		Putty and spray painting of the affected portion.	\$ 600.00
03		To rust-proofing of the affected areas.	\$ 120.00
04		To check electrical lighting concerned.	\$ 80.00
			\$ 1,300.00
			\$ 4,850.10

30

309

259

30

30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: