

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jasmine Lok Kheng Kwei

Date: 19 Feb 2020

Preliminary Advice

Insured Vehicle No	: SMF4094S		
TP Vehicle No	: SHC7095U	Accident Date	: 10/02/2020
Make	: HYUNDAI I40	Assignment Date	: 17/02/2020
Date of Inspection	: 18/02/2020	Est. Duration of Repair	: 4 days
Inspection At	: Bifrost Auto Pte Ltd (sin Ming) (HQ) Blk 9 Sector C, #01-42 Sin Ming Industrial Estate Singapore 575644		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,445.76
Revised Amount	:S\$	5,686.56
Check Items (Estimated)	:S\$	3,317.36
Total	:S\$	9,003.92

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.