

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III20002687/KGS3Q2**Date:** 30/06/2020REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SKH3331C	<b>Insured Vehicle No :</b>	SHC8432Z
Date of Loss: 12/02/2020	Nature of Claim: TP	Claim No: MCT20020247

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKH3331C</b>		
Make & Model:	MERCEDES-BENZ C180K, 1.6 (A)	Engine No:	27491030012254
Reg. Date:	10/10/2012 (Man. Year: 2012)	Chassis No:	WDD2043312F975545
Colour:	White	Odometer:	60993 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40Z R18	Rear Tyre Size:	225/40Z R18
Front Left Side:	Pirelli 7 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 7 mm	Rear Right Side:	Pirelli 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	980.10	980.10	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	830.00	650.00	180.00	21.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>1,810.10</b>	<b>1,630.10</b>	<b>180.00</b>	<b>9.94</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,300.00</b>		
	<b>(S\$)</b>	1,810.10	1,300.00	510.10
<b>+ GST 7.00/7.00% (S\$)</b>	126.71	91.00	35.71	28.18
<b>Nett Amount (S\$)</b>	<b>1,936.81</b>	<b>1,391.00</b>	<b>545.81</b>	<b>28.18</b>
<b>+ Loss of Use (3.0 x S\$60.00/day) (S\$)</b>		180.00		
	<b>Nett Liability (S\$)</b>	<b>1,571.00</b>		
	<b>Global Sum Settlement (S\$)</b>	<b>1,550.00</b>		

INSPECTION

Date of Assignment:	05/03/2020	
Date Inspected:	05/03/2020 Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	3.0 days	

---

**Adjuster:** KENNETH KONG

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 22 May 2020)
<b>Parts:</b> 143	MERCEDES-BENZ C180K 1.6 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKH3331C)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH FENDER MOULDING	Necessary	98.00 FN	*98.00 FN
2	1		*REAR RH SPORT RIM	Dented	991.00 FN	*991.00 FN
					<b>Sub Total (\$\$)</b>	<b>1,089.00</b>
					<b>- Nett Item Discount on N Items 10.00/10.00% (\$\$)</b>	<b>108.90</b>
					<b>Total Parts (\$\$)</b>	<b>980.10</b>

F=Franchise part. N=NettItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE & REFIX REAR RH SPORT RIM	New	30.00	20.00
2	REMOVE & REFIX REAR RH FENDER ,REAR BUMPER & REALIGN THE SAME	New	200.00	150.00
3	PUTTY & RESPRAY ON REAR BUMPER ,REAR RH FENDER & DOOR	New	600.00	480.00
			<b>Gross Labour Cost (S\$)</b>	<b>830.00</b>
				<b>650.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >