

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SKH3331C
TP/India

M/S : INDIA INT'L INSURANCE PTE LTD

64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100

FAX: 62247743

ATTN: Motor Claim Department

WS Ref: TP/INDIA/YS

Claim Type: Third Party

Accident Date: 12/02/2020

TP Veh Reg No: SHC8432Z

Estimate No: ES2090213/YISHUN

Date: 05 Mar 2020

Policy No: 5103264389-01

Veh Reg No: SKH3331C

Make/Model: MERCEDES MERCEDES
BENZ C 180

Chassis No: WDD2043312F975545

Engine No: 27491030012254

Reg. Date: 10/10/2012

Estimate Repair Cost to Vehicle No :SKH3331C

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Net Price				
1 REAR RH FENDER MOULDING	98.00	1 PC	98.00	
2 REAR RH SPORT RIM	991.00	1 PC	991.00	
			1,089.00	
		Less 10%	108.90	980.10
Labour				
3 REMOVE & REFIX REAR RH SPORT RIM	30.00	1 LA	30.00	201
4 REMOVE & REFIX REAR RH FENDER,REAR BUMPER & REALIGN THE SAME	200.00	1 LA	200.00	1501
5 PUTTY & RESPRAY ON REAR BUMPER,REAR RH FENDER & DOOR	600.00	1 LA	600.00	4801
			830.00	830.00
Total				S\$ 1,810.10
Add GST @ 7%				126.71
Total Amount Payable				<u>S\$ 1,936.81</u>

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: