

ASS. REC. BY:

REF:

CS/CTI20002688/AT 83.52

Special Instruction:

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person):

Cecilia Low

of

CTI

Date/Time:

17/2/2020

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SMF1521X

Insured:

GBJ3196Y

at Workshop m/s

Dynamic Autowork

Tel:

98564815

of

8 Kaki Bukit Ave 4 #08-09

Policy No:

DMCVSN19114319000

Claim No:

SNM200200828

Sum Insured:

Excess:

Make of Veh:

D.O.A. 16/1/2020

(Agent's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

17/2

Person Contacted:

Michelle

Vehicle IN/OUT

Date/Time

Action/Instruction

Initials ()

SMF1521X-X

GBJ3196Y-NBA/CTI20002504/Y DOA: 16/1/2020

lump sum \$4200/- (red: 6625.36, 61%)

Nivitha (LKK Auto)

From: Cecilia Low <cecilia.low@sg.cntaiping.com>
Sent: Monday, 17 February 2020 3:55 PM
To: sur@lkkauto.com; admin-a@lkkauto.com; assignments@lkkauto.com
Cc: Dynamic Autowork
Subject: RE: SNM20D200828/GBJ3196Y/CECILIA - FW: SMF1521X (Pre-inspection) / Your vehicle : GBJ3196Y

Dear Sirs

Please proceed to conduct survey on Without Prejudice basis.
Thank you.

Cecilia Low (Ms)
Senior Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6530 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Dynamic Autowork [mailto:dynamicautowork@gmail.com]
Sent: Monday, 17 February 2020 2:55 PM
To: Cecilia Low <cecilia.low@sg.cntaiping.com>
Subject: Re: SNM20D200828/GBJ3196Y/CECILIA - FW: SMF1521X (Pre-inspection) / Your vehicle : GBJ3196Y

Dear Cecilia,

We refer to your email dated 17/02/2020.

Please arrange LKK to conduct the survey.

On Mon, Feb 17, 2020 at 2:47 PM Cecilia Low <cecilia.low@sg.cntaiping.com> wrote:

Without Prejudice

Vel Out

Dear Sirs

We refer to your email of even date.

We intend to conduct a Pre-Repair Survey of your client's vehicle jointly with your client/your motor workshop.

We propose to use one of the following motor surveyors to conduct the survey as a single joint expert.

LKK / LBS

Adrian Ling
Kelvin Ang
See Chew Seng
Mohd Fadhilah Bin Osman
Xing Quo Qiang
Kenneth Kong
Simon Ho
Chua Weijie
Marcus Chua
Henry Ng

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.

Thank you.

Cecilia Low (Ms)

Senior Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6530 | F: (65) 6222 1033

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Monday, 17 February 2020 1:20 PM
To: Cecilia Low <cecilia.low@sg.cntaiping.com>; dynamicautowork@gmail.com
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: SNM20D200828/GBJ3196Y/CECILIA - FW: SMF1521X (Pre-inspection) / Your vehicle : GBJ3196Y

Dear Cecilia,

Please conduct PRS for SMF1521X.

Note : officer in charge – Cecilia 63896530.

*** Kindly quote our reference number when replying.

Thank you,
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Dynamic Autowork <dynamicautowork@gmail.com>
Sent: Friday, February 14, 2020 4:26 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>; Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Ong Chin Kiat <chinkiat.ong@sg.cntaiping.com>
Subject: SMF1521X (Pre-inspection) / Your vehicle : GBJ3196Y

Dear person in charge,

Please refer to attach file and arrange for pre-inspection.

Hope we can do Direct Settle and please provide the surveyor firm or surveyor name list to conduct the joint pre-repair survey as a single joint expert

**** PLEASE ADVISE LIABILITY ****

--

Thank You.

Yours Sincerely,

Michelle

HP : 9856 4815

8 Kaki Bukit Avenue 4

#08-09Premier @ Kaki Bukit

Singapore (415875)

Tel : 6341 6789

Fax : 6341 6778

Thank You.

Yours Sincerely,

Michelle

HP : 9856 4815

8 Kaki Bukit Avenue 4

#08-09Premier @ Kaki Bukit

Singapore (415875)

Tel : 6341 6789

Fax : 6341 6778

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/01/2020 17:19
Date Of Accident	16/01/2020 14:00
Exact Location Of Accident	JURONG PIER CIRCUS
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMF1521X
Insured/Policyholder	
Name Of Registered Owner	ESTEEM LEASING PTE LTD
Co Reg No	2XXXXX215D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-67532112

Vehicle Particulars

Manufacturer	HONDA
Model	FREED HYBRID 1.5G AUTO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5110341793
Cover Note Number	

Driver

Name of Driver	CHANG CHAU YIN
NRIC No	SXXXX723A
Date Of Birth	22/07/1967
Occupation	OUTDOOR
Date Of Driving Pass	15/04/1996
Driving Experience	23 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96654938
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	417 TAMPINES STREET 41 #11-363
Postcode	520417
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	AFTER RAIN
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED;

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ3196Y
Vehicle Make/Model/Colour	TOYOTA / HIACE 2.8 DX AUTO
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415933
Name: _____
NRIC: _____
Tel: 67416697 Fax: 67492305
Email: vackb@singnet.com.sg

Accident Sketch Plan

SKETCH PLAN



A = SMF 1521X

B = GBJ 3196Y

Jurong Pier Circus

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to attach

DECLARATION

I/We declare that the above particulars are true in every respect.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4
Singapore 415935
Tel: 67416697 Fax: 67492305
Email: vackb@sinonet.com.sg

Accident Sketch Plan

On 16.01.2020 at about 14:00 hours at Jurong Pier Circus. I was stationary on lane 2 (along Slip Road of Jurong Pier Road towards Jalan Buroh, before entering the Jurong Pier Circus) as the front vehicles were waiting for the oncoming traffic to clear.

Suddenly I heard a loud bang from behind. When I alighted I realised vehicle (B) had collided onto rear portion of my vehicle (A).

Vehicle (A): SMF 1521X

Vehicle (B): GBJ 3196Y



Dynamic Autowork Pte.Ltd.

(ROC /GST Reg. No. 201436361C)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:dynamicautowork@gmail.com

DATE : 25.02.20

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : SMF1521X
MODEL : HONDA FREED
DATE OF ACCIDENT : 16.01.20
TIME OF ACCIDENT : 14:00HRS

Denise

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Rebond</i>	1	\$ 925.30	\$ 925.30
2	REAR BUMPER EXHAUST COVER GARNISH <i>new</i>	1	\$ 58.10	\$ 58.10
3	REAR BUMPER INNER GARNISH <i>new</i>	2	\$ 60.20	\$ 120.40
4	REAR BUMPER SIDE RETAINER (UPPER) <i>new</i>	2	\$ 39.70	\$ 79.40
5	REAR BUMPER SIDE RETAINER (LOWER) <i>new</i>	2	\$ 42.30	\$ 84.60
6	REAR FENDER INNER TRIM <i>new</i>	2	\$ 446.70	\$ 893.40
7	TAIL LAMP <i>new</i>	2	\$ 580.40	\$ 1,160.80
8	TAIL GATE <i>Rebond</i>	1	\$ 1,180.60	\$ 1,180.60
9	TAIL GATE LOGO <i>?</i>	1	\$ 59.20	\$ 59.20
10	TAIL GATE EMBLEM 'FREED' <i>new</i>	1	\$ 52.30	\$ 52.30
11	TAIL GATE EMBLEM 'HYBRIC' <i>new</i>	1	\$ 75.70	\$ 75.70
12	TAIL GATE OUTER MOULDING (CHROME) <i>new</i>	1	\$ 370.40	\$ 370.40
13	TAIL GATE DAMPER <i>new</i>	2	\$ 120.10	\$ 240.20
14	TAIL GATE STOPPER <i>new</i>	2	\$ 13.20	\$ 26.40
15	TAIL GATE WEATHER STRIP <i>new</i>	1	\$ 168.70	\$ 168.70
16	TAIL GATE INNER TRIM (LOWER) <i>new</i>	1	\$ 295.30	\$ 295.30
17	TAIL GATE TOP LOCK <i>Rebond</i>	1	\$ 189.50	\$ 189.50
18	TAILGATE LOWER LOCK <i>new</i>	1	\$ 26.70	\$ 26.70
19	TAILGATE WINDSCREEN MOULDING <i>new</i>	1	\$ 194.20	\$ 194.20
20	REAR END PANEL <i>Rebond</i>	1	\$ 623.70	\$ 623.70
21	REAR END PANEL TOP GARNISH <i>Rebond</i>	1	\$ 169.30	\$ 169.30

3717.90

2974.32

TOTAL PRICE \$ 6,994.20
LESS 20% \$ 1,398.84
SUB TOTAL PRICE \$ 5,595.36

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Noe New</i>	1	\$ 50.00	\$ 50.00

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SMF1521X
 MODEL : HONDA FREED
 DATE OF ACCIDENT : 16.01.20
 TIME OF ACCIDENT : 14:00HRS

2	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	30
3	REAR BUMPER EXHAUST COVER GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00	+
4	REAR BUMPER INNER GARNISH CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
5	TAILLAMP CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	+
6	TAIL GATE LAMP CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
7	TAIL GATE OUTER MOULDING CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00	+
8	TAIL GATE INNER TRIM CLIP (SET) <i>new</i>	1	\$ 60.00	\$ 60.00	+
9	TAIL GATE WINDSCREEN SEALANT <i>new</i>	1	\$ 80.00	\$ 80.00	30
10	TAILGATE WINDSCREEN INNER SHIELD	1	\$ 60.00	\$ 60.00	30
11	REAR FENDER INNER TRIM CLIP (SET) <i>new</i>	1	\$ 100.00	\$ 100.00	+
12	REAR END PANEL INSULATION SEAL <i>new</i>	1	\$ 150.00	\$ 150.00	60
13	REAR END PANEL TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 40.00	\$ 40.00	10
14	REVERSE SENSOR <i>new</i>	1	\$ 220.00	\$ 220.00	200
15	REVERSE CAMERA <i>new</i>	1	\$ 450.00	\$ 450.00	+
360			TOTAL	\$ 1,490.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, WELDING, CUTTING, GRAZING ADJUST, KNOCK STRAIGHTEN	\$ 1,200.00	800
2	TO PUTTY, SPRAY PAINT, POLISH, WAX	\$ 1,200.00	800
3	TO APPLY RUST PROOFING/ UNDER COAT	\$ 250.00	60
4	WIRING, BULB CHECKING	\$ 80.00	30
5	REMOVE AND REFIX UPHOLSTERY, CUSHION, SEAT TO FACILITATE REPAIR	\$ 350.00	60
6	TRANSFER TAILGATE MECHANISM	\$ 80.00	✓
7	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X
8	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
9	REMOVE AND REFIX REAR REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	40
10	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	40

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SMF1521X
 MODEL : HONDA FREED
 DATE OF ACCIDENT : 16.01.20
 TIME OF ACCIDENT : 14:00HRS

11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x
----	--	-----------	---

TOTAL \$ 3,740.00 2030

ESTIMATE REPORT

TOTAL PARTS COST : \$ 7,085.36
 TOTAL LABOUR COST : \$ 3,740.00
 TOTAL REPAIR COST : \$ 10,825.36

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
 PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

ABBY
 SERVICE ADVISOR
 ABBY
 HP : 9856 4815

Adrian Lj
 L/S 25/02/20

06 Days

Total: 5364.37
 L/S: 4.21c

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Feb 2020		18 Feb 2020 10:59 Edit Adj Rpt	S\$4,200.00 Edit Estimates	S\$4,200.00 View Rpt		Pending for Survey Report Cancel Case





































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	-, Co. Reg. No.: -								
Main Claimant:	ESTEEM LEASING PTE LTD , Co. Reg. No.: 201807215D								
Vehicle Reg. No.:	SMF1521X	Date of Loss:	16/01/2020 14:00 - :59 [14 Months and 18 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM20D200828	Policy/Cover Note No.:	DMCVSN19114819000						
Vehicle Reg. No. (Insured):	GBJ3196Y	Policy No. (Claimant):	5110341793						
		Excess:	S\$0.00						
Repairer:	- Not Applicable - (-)								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Cecilia Low - 63896530]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 27/02/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SMF1521X (SNM20D200828)
[GBJ3196Y]
TP
ESTEEM LEASING PTE LTD
Jan 16 2020 2:00PM
[-]

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	27/03/20 10:30	General View	 Load JPG	<input checked="" type="checkbox"/>
2	27/03/20 10:30	General View	 Load JPG	<input checked="" type="checkbox"/>
3	27/03/20 10:30	General View	 Load JPG	<input checked="" type="checkbox"/>
4	27/03/20 10:30	General View	 Load JPG	<input checked="" type="checkbox"/>
5	27/03/20 10:30	General View	 Load JPG	<input checked="" type="checkbox"/>
6	27/03/20 10:30	General View	 Load JPG	<input checked="" type="checkbox"/>
7	27/03/20 10:30	General View	 Load JPG	<input checked="" type="checkbox"/>
8	27/03/20 10:30	General View	 Load JPG	<input checked="" type="checkbox"/>
9	27/03/20 10:30	General View	 Load JPG	<input checked="" type="checkbox"/>
10	27/03/20 10:31	General View	 Load JPG	<input checked="" type="checkbox"/>
11	27/03/20 10:31	General View	 Load JPG	<input checked="" type="checkbox"/>
12	27/03/20 10:31	General View	 Load JPG	<input checked="" type="checkbox"/>
13	27/03/20 10:31	General View	 Load JPG	<input checked="" type="checkbox"/>
14	27/03/20 10:31	General View	 Load JPG	<input checked="" type="checkbox"/>
15	27/03/20 10:31	General View	 Load JPG	<input checked="" type="checkbox"/>
16	27/03/20 10:31	General View	 Load JPG	<input checked="" type="checkbox"/>
17	27/03/20 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
18	27/03/20 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
19	27/03/20 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
20	27/03/20 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
21	27/03/20 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
22	27/03/20 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
23	27/03/20 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
24	27/03/20 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
25	27/03/20 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
26	27/03/20 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
27	27/03/20 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
28	27/03/20 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	27/03/20 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	27/03/20 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	27/03/20 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	27/03/20 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	27/03/20 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	27/03/20 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	27/03/20 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	27/03/20 10:31	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
37	27/03/20 10:31	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	27/03/20 10:31	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	27/03/20 10:31	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	27/03/20 10:31	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	27/03/20 10:31	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	27/03/20 10:31	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	18/01/20 08:51	Accident Statement	Load HTM	
Photos/Images			3 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	18/01/20 08:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	18/01/20 08:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	18/01/20 08:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	18/01/20 08:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	18/01/20 08:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	18/01/20 08:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
7	18/01/20 08:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
8	18/01/20 08:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
9	18/01/20 08:50	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page ▼	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	18/01/20 08:50	Accident Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	18/01/20 08:50	Accident Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
3	18/01/20 08:50	Accident Sketch Plan	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST Reset Save Print
There are no document checklists configured.
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid #ccc; height: 100px; margin-top: 5px;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20002688/ATF3S2

Date: 01/04/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN19114819000
Claimant Vehicle No :	SMF1521X	Insured Vehicle No :	GBJ3196Y
Date of Loss:	16/01/2020	Nature of Claim:	TP
		Claim No:	SNM20D200828

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF1521X	Engine No:	LEB5608538
Make & Model:	HONDA FREED HYBRID, 1.5 G (A)	Chassis No:	GB71073749
Reg. Date:	29/10/2018 (Man. Year: 2018)	Odometer:	102161 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,085.36	3,334.32	3,751.04	52.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,740.00	2,030.00	1,710.00	45.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,825.36	5,364.32	5,461.04	50.45
Approved Total (Overridden) (S\$)		4,200.00		
(S\$)	10,825.36	4,200.00	6,625.36	61.20
+ GST 7.00/7.00% (S\$)	757.78	294.00	463.78	61.20
Nett Amount (S\$)	11,583.14	4,494.00	7,089.14	61.20

INSPECTION

Date of Assignment:	18/02/2020	DYNAMIC AUTOWORK PTE LTD 8 KAKI BUKIT AVE 4 #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875
Date Inspected:	25/02/2020 Inspected At:	
Estimated Period of Repair:	6.0 days	

4/1/2020

Adjuster Report

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Apr 2020)

Parts: M1-MPV HONDA FREED HYBRID 1.5 G (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMF1521X)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	925.30 FL	*925.30 FL
2	1		*REAR BUMPER EXHAUST COVER GARNISH	Not Necessary	58.10 FL	*- FL
3	2		*REAR BUMPER INNER GRNISH	Not Necessary	120.40 FL	*- FL
4	2		*REAR BUMPER SIDE RETAINER (UPPER)	Necessary	79.40 FL	*79.40 FL
5	2		*REAR BUMPER SIDE RETAINER (LOWER)	Not Necessary	84.60 FL	*- FL
6	2		*REAR FENDER INNER TRIM	Not Necessary	893.40 FL	*- FL
7	2		*TAIL LAMP	Not Necessary	1,160.80 FL	*- FL
8	1		*TAIL GATE	Dented	1,180.60 FL	*1,180.60 FL
9	1		*TAIL GATE LOGO	Necessary	59.20 FL	*59.20 FL
10	1		*TAIL GATE EMBLEM FREED	Necessary	52.30 FL	*52.30 FL
11	1		*TAIL GATE EMBLEM HYBRID	Necessary	75.70 FL	*75.70 FL
12	1		*TAIL GATE OUTER MOULDING (CHROME)	Not Necessary	370.40 FL	*- FL
13	2		*TAIL GATE DAMPER	Not Necessary	240.20 FL	*- FL
14	2		*TAIL GATE STOPPER	Not Necessary	26.40 FL	*- FL
15	1		*TAIL GATE WEATHERSTRIP	Cut	168.70 FL	*168.70 FL
16	1		*TAIL GATE INNER TRIM (LOWER)	Not Necessary	295.30 FL	*- FL
17	1		*TAIL GATE TOP LOCK	Damaged	189.50 FL	*189.50 FL
18	1		*TAILGATE LOWER LOCK	Not Necessary	26.70 FL	*- FL
19	1		*TAILGATE WINDSCREEN MOULDING	Necessary	194.20 FL	*194.20 FL
20	1		*REAR END PANEL	Dented	623.70 FL	*623.70 FL
21	1		*REAR END PANEL TOP GARNISH	Deformed	169.30 FL	*169.30 FL
22	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
23	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
24	1		*SET REAR BUMPER EXHAUST COVER GARNISH CLIP	Not Necessary	30.00 FS	*- FS
25	1		*SET REAR BUMPER INNER GARNISH CLIP	Not Necessary	50.00 FS	*- FS
26	1		*SET TAILLAMP CLIP	Not Necessary	40.00 FS	*- FS
27	1		*SET TAIL GATE LAMP CLIP	Not Necessary	50.00 FS	*- FS
28	1		*SET TAIL GATE OUTER MOULDING CLIP	Not Necessary	50.00 FS	*- FS
29	1		*SET TAIL GATE INNER TRIM CLIP	Not Necessary	60.00 FS	*- FS
30	1		*TAIL GATE WINDSCREEN SEALANT	Necessary	80.00 FS	*30.00 FS
31	1		*TAILGATE WINDSCREEN INNER SHIELD	Necessary	60.00 FS	*30.00 FS
32	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	100.00 FS	*- FS
33	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
34	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	40.00 FS	*10.00 FS
35	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
36	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,484.20	4,077.90
- List Item Discount on L Items 20.00/20.00% (S\$)	1,398.84	743.58
Total Parts (S\$)	7,085.36	3,334.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, WELDING, CUTTING, GRAZING ADJUST, KNOCK STRAIGHTEN.	New	1,200.00	800.00
2	TO PUTTY, SPRAY PAINT, POLISH, WAX.	New	1,200.00	800.00
3	TO APPLY RUST PROOFING / UNDER COAT.	New	250.00	60.00
4	WIRNING, BULB CHECKING.	New	80.00	30.00
5	REMOVE AND REFIX UPHOLSTERY, CUSHION, SEAT TO FACILITATE REPAIR.	New	350.00	60.00
6	TRANSFER TAILGATE MECHANISM.	New	80.00	80.00
7	CONDUCT WATER LEAKAGE TEST.	New	120.00	0.00
8	REMOVE AND REFIX TAILGATE WINDSCREEN.	New	120.00	120.00
9	REMOVE AND REFIX REAR REVERSE SENSOR AND DISTANCE SETTING.	New	80.00	40.00
10	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING.	New	80.00	40.00
11	TO CHECK DIAGNOSTIC OF VEHICLE MANAGEMENT / CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	New	180.00	0.00
Gross Labour Cost (S\$)			3,740.00	2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >