

22/03/2002

ASS. REC. BY:

REF: CS/SMO20002692/Aqf3

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Grace Teo of SMO Date/Time: 17.2.2020 4.00 p.m

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLA 2476A Insured: FBH 8106J

at Workshop m/s YAP Lee Motor Tel: 66441555

of 1 Kaki Bukit Bk 6 #01-22 Autobay

Policy No: Claim No: CMTD 2000539/SYH

Sum Insured: Excess:

Make of Veh: D.O.A. 2.2.20

(Client's Record)

CA / REV / REP. / REV 24 HRS H.O.D. Endorsement:

Date/Time: 17/2/20 5.00 p.m Person Contacted: Mr Chan Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate:
	SLA 2476A - CC31 LCR 1706 4380 / 4129392 17/02/2017
	FBH 8106J - X
19/02/20	3.59pm informed Shiang Yk, we are pending estimate from Negainv.
17/3/20	2.09pm revised to Shiang Yk by email.
	US \$1500, 4 days CRed \$2587.33, 63%.

ASSIGNMENT

25/03/10.

2010 May

From

Code

Estimated Cost

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop in/s

of

Insured

Policy No

Claims No

Sum Insured

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No

SLA 2476A.

at Regd

Type: ☒ M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Primo Mover /

Truck / Trailer

Make:

Toyota Altis

1598

Colour

Gold

A/C: Insured / Std / NI / NA

Sp Reading

243500

T/Radio: Insured / Std / NI / NA

Eng/No

C/No

MR0532EE106174152

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Good / Jammed / Leaked / Burnt or

Brake: ☒ Good / Jammed / Leaked / Burnt or

Modi: Nil / ☒ S/Rim / STD A/Rim or

Tyre Size: F:

195/65R15

R:

195/65R15

☒ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

D.O.I.

17/02/20

Survey held at

Ysp/see

Des. of Damages: Frt / Rear / ☒ O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

TP Sampo

MV : 14K

PV : 86K

Nett: 54K

RECEIVED 17 MAR 2020

Date/Time, File Pass in?



: Prel. Report

17/3 12:15



: Final Report

Date/Time, File Return in?

25

Days Of Repair: 4

Resurvey No. of Trip: 2

Survey Fee:

Transport:

3-PS

1000

400

200

100

50

Add Fee:



Site Insp: 15



Interview: 10



Tech. Insp: 10



Final Rep: 10

Report Format:

Lump Sum /

TP

1500

250



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: CMTD2000539/SYH

Date: 17th March 2020

Our Ref: CS/SMO20002692/Aqf3

Without Prejudice

The Motor Claims Department
Sompo Insurance

Attn: Grace

Dear Sirs/Mdm

PRELIMINARY ADVICE OF VEHICLE NO. SLA 2476A.


We thank you for the instruction on 17/02/2020.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 17/02/2020 at the premises of M/s YAP LEE MOTOR and have the following to report:-

Workshop Estimate Amount	: S\$ <u>3,387.33</u> .
Revised Estimate Amount	: S\$ <u>1,500.00 (Lump Sum)</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the n/s portion.



Comments/ Present Status:

Damages consistent.

Recommendation Days of Repair: 4 days.

We have NOT authorize repair.

Yours faithfully

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Monday, 17 February 2020 4:00 PM
To: Ruby Ong; Hwang, Shiang Yi; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'; 'SUR'
Cc: Ye, Yong Kang Melvin; Yap Lee Motor
Subject: CMTD2000539/SYH - LKK/ FBM8106J & SLA2476A ACC ON 02.02.20 [OUR REF. TCL.GCN.RO.50075.20.YLM]

Our Reference: CMTD2000539/SYH
Your Reference: TCL.GCN.ro.50075.20.ylm

Without Prejudice

EMAIL ONLY

Date: 17/02/2020

OUR Email: motorsurvey@sompo.com.sg

Attention:
M/S HIN TAT AUGUSTINE & PARTNERS

Dear Ruby,

ACCIDENT INVOLVING FBM8106J & SLA2476A ON 02.02.2020

We refer to your email reply of today.

We will appoint **LKK Auto** to conduct the survey.

Hi **LKK Auto**,

Please make the arrangement to survey for **SLA2476A** on a without prejudice and any admission of liability basis.

Please be informed that **Ms. Hwang Shiang Yi** is the handler of this case who can be contacted at 63295 205/
shiangyi.hwang@sompo.com.sg.

Please revert your report upon completion of survey to my colleague, **Ms. Shiang Yi**.

Thank you.

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147

Velu

For motor claims survey request, please email to motorsurvey@sompo.com.sg



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Ruby Ong <ruby@htapartners.com.sg>

Sent: Monday, February 17, 2020 3:24 PM

To: Teo, Grace <grace.teo@sompo.com.sg>; Hwang, Shiang Yi <shiangyi.hwang@sompo.com.sg>

Cc: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>; Yap Lee Motor

<yap_lee_motor@singnet.com.sg>

Subject: RE: CMTD2000539/SYH - PRI/ FBM8106J & SLA2476A ACC ON 02.02.20 [OUR REF. TCL.GCN.RO.50075.20.YLM]

Importance: High

WITHOUT PREJUDICE
SAVE AS TO COSTS

Dear Grace

We refer to your email of 11 February 2020 and the reminder on 13 February 2020.

Our client is agreeable to appoint **LKK Auto Consultants** from your list to conduct the joint pre-repair survey as a single joint expert for our client's vehicle no. **SLA 2476A**.

Please make the necessary arrangements with the contact person on the survey of our client's vehicle. The details are as follows :

Venue : **Yap Lee Motor**
1 Kaki Bukit Avenue 6
#01-26 Autobay@Kaki Bukit (417883)

Contact Person : **Mrs Chua / Shirley : 6844 1555**

In the event that the pre-repair survey was not conducted during the prescribed time or already conducted at your end previously, we reserve our client's right to claim for compensation for loss of use for your current request for re-survey.

Best regards,
Ruby Ong
Secretary

M/s Hin Tat Augustine & Partners
20 Upper Circular Road
#02-10/12 The Riverwalk
Singapore 058416
Tel : 6533 0212 ext 254
Fax : 6338 3536 / 6533 0313

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Thursday, 13 February 2020 12:34 PM
To: Ruby Ong <ruby@htapartners.com.sg>; Hwang, Shiang Yi <shiangyi.hwang@sompo.com.sg>
Cc: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Subject: CMTD2000539/SYH - PRI/ FBM8106J & SLA2476A ACC ON 02.02.20 [OUR REF. TCL.GCN.RO.50075.20.YLM]

Hi Ruby,

1st reminder

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @



or



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Teo, Grace

Sent: Tuesday, February 11, 2020 6:13 PM

To: 'Ruby Ong' <ruby@htapartners.com.sg>; Hwang, Shiang Yi <shiangyi.hwang@sompo.com.sg>

Cc: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: CMTD2000539/SYH - PRI/ FBM8106J & SLA2476A ACC ON 02.02.20 [OUR REF.

TCL.GCN.RO.50075.20.YLM]

Importance: High

Our Reference: CMTD2000539/SYH

Your Reference: TCL.GCN.ro.50075.20.ylm

Without Prejudice

EMAIL ONLY

Date: 11/02/2020

OUR Email: motorsurvey@sompo.com.sg

Attention:

M/S HIN TAT AUGUSTINE & PARTNERS

Dear Ruby,

ACCIDENT INVOLVING FBM8106J & SLA2476A ON 02.02.2020

We refer to your Notice of Accident dated 11/02/2020.

Please be informed that **Ms. Hwang Shiang Yi** is the handler of this case who can be contacted at 63295 205/
shiangyi.hwang@sompo.com.sg.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: Ruby Ong <ruby@htapartners.com.sg>

Sent: Tuesday, February 11, 2020 3:01 PM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Cc: Yap Lee Motor <yap_lee_motor@singnet.com.sg>

Subject: REQUEST FOR PRE-REPAIR SURVEY PROTOCOL FOR SLA 2476A [OUR REF. TCL.GCN.RO.50075.20.YLM]

Importance: High

Your ref: FBM 8106J

WITHOUT PREJUDICE

Our ref: TCL.GCN.ro.50075.20.ylm

11 February 2020

Sompo Insurance Pte Ltd

By Email Only

Motor Claims Department

50 Raffles Place #05-01/06

Singapore Land Tower

Singapore 048623

VERY URGENT

Dear Sir,

CLAIMANT: AC CAR RENTAL PTE. LTD.

ACCIDENT INVOLVING SLA 2476A & FMB 8106J ALONG CANBERRA WAY INTO CANBERRA STREET ON 2 FEBRUARY 2020 @ 1955RS

We are instructed by AC Car Rental Pte. Ltd. to notify you of a road traffic accident on 2 February 2020 at about 1955hrs along Canberra Way into Canberra Street involving our clients' vehicle registration number SLA 2476A and vehicle registration number FMB 8106J driven by your insured's driver at the material time.

As a result of the accident, our clients' vehicle has been damaged. Before our clients proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurers would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our clients shall proceed to repair the vehicle without reference to you.

Best regards,

Ruby Ong

Secretary

M/s Hin Tat Augustine & Partners

20 Upper Circular Road

#02-10/12 The Riverwalk

Singapore 058416

Tel : 6533 0212 ext 254

Fax : 6338 3536 / 6533 0313

www.htapartners.com.sg

Privileged/Confidential information is contained in this message. If you are not the addressee indicated in this message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email.

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Tuesday, 17 March 2020 2:09 PM
To: 'Teo, Grace'; 'Hwang, Shiang Yi'; assignments; SUR
Cc: 'Ye, Yong Kang Melvin'
Subject: RE: CMTD2000539/SYH - LKK/ FBM8106J & SLA2476A ACC ON 02.02.20 [OUR REF. TCL.GCN.RO.50075.20.YLM]
Attachments: CSSMO20002692Aqf3.pdf

Dear Shiang Yi,

Enclosed herewith preliminary advice of SLA 2476A.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAuto)
Sent: Wednesday, 19 February 2020 3:59 PM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; 'Hwang, Shiang Yi' <shiangyi.hwang@sompo.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>
Subject: RE: CMTD2000539/SYH - LKK/ FBM8106J & SLA2476A ACC ON 02.02.20 [OUR REF. TCL.GCN.RO.50075.20.YLM]

Dear Shiang Yi,

Please be informed that we have inspected the vehicle SLA 2476A on 17/02/2020.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Monday, 17 February 2020 5:27 PM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; 'Hwang, Shiang Yi' <shiangyi.hwang@sompo.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>
Subject: RE: CMTD2000539/SYH - LKK/ FBM8106J & SLA2476A ACC ON 02.02.20 [OUR REF. TCL.GCN.RO.50075.20.YLM]

Dear Grace,

Thank you for the assignment.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 19 February 2020 3:59 PM
To: 'Teo, Grace'; 'Hwang, Shiang Yi'; assignments; SUR
Cc: 'Ye, Yong Kang Melvin'
Subject: RE: CMTD2000539/SYH - LKK/ FBM8106J & SLA2476A ACC ON 02.02.20 [OUR REF. TCL.GCN.RO.50075.20.YLM]

Dear Shiang Yi,

Please be informed that we have inspected the vehicle SLA 2476A on 17/02/2020.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO) <admin-d@lkkauto.com>
Sent: Monday, 17 February 2020 5:27 PM
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; 'Hwang, Shiang Yi' <shiangyi.hwang@sompo.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>
Subject: RE: CMTD2000539/SYH - LKK/ FBM8106J & SLA2476A ACC ON 02.02.20 [OUR REF. TCL.GCN.RO.50075.20.YLM]

Dear Grace,

Thank you for the assignment.

Best Regards

Celine Fong

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]
Sent: Monday, 17 February 2020 4:00 PM
To: Ruby Ong; Hwang, Shiang Yi; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'; 'SUR'
Cc: Ye, Yong Kang Melvin; Yap Lee Motor
Subject: CMTD2000539/SYH - LKK/ FBM8106J & SLA2476A ACC ON 02.02.20 [OUR REF. TCL.GCN.RO.50075.20.YLM]

Our Reference: CMTD2000539/SYH

Your Reference: TCL.GCN.ro.50075.20.ylm

Find your perfect drive and
save up to \$22,500*



Find out more

*Terms and conditions apply.



► **SEARCH** Price Range Depreciation 2010 Vehicle Type [Advanced Search](#)

► Used Car Comparison

--- Comparing 4 Vehicles ---

Toyota Corolla Altis 1.6A

Toyota Corolla Altis 1.6A

Toyota Corolla Altis 1.6A

Toyota Corolla Altis 1.6A



 Clear All

[Back to search result](#)

CAR DETAILS

Price	\$15,800	\$16,800	\$17,500	\$17,800
Instalment	N.A.	\$5,909	\$4,114	\$2,523
Registration Date	05-Mar-2010	28-Apr-2010	09-Jun-2010	27-Jul-2010
Manufactured	2010	2010	2010	2010
Mileage	-	-	154,800 km	147,000 km
Transmission	Auto	Auto	Auto	Auto
Engine Cap	1,598 cc	1,598 cc	1,598 cc	1,598 cc
Road Tax	\$742 /yr	\$742 /yr	\$742 /yr	\$742 /yr
Power	80.0 kW (107 bhp)	80.0 kW (107 bhp)	80.0 kW (107 bhp)	80.0 kW (107 bhp)
Curb Weight	1,195 kg	1,195 kg	1,195 kg	1,195 kg
Features	Original Features.	-	Good Engine. Smooth Drive. Seats Are Still Very Well Maintained, Feels Like New. Good For COE Renewal. WhatsApp Me.	-
Accessories	-	-	Off White Paint, Most Reliable And Fuel Efficient Car.	-
Description	Very Well Maintained With Very Well Care Interior, Optional For 5 Years/10 Years COE Renewal.	Please Call For Viewing.		Trade In Welcome, Ba Loan All Available, Ints For Viewing, Viewing t Only.
COE	\$20,340	\$30,000	\$26,102	\$29,501
OMV	\$16,716	\$16,716	\$16,716	\$16,680
ARF	\$16,716	\$16,716	\$16,716	\$16,680
Depreciation	N.A.	N.A.	N.A.	N.A.
No. of Owners	2	1	2	2
Type of Vehicle	Sedan	Sedan	Sedan	Sedan
Category	PARF Car, Direct Owner Sale	PARF Car	PARF Car, Direct Owner Sale	PARF Car
Availability	Available	Available	Available	Available

SELLER INFORMATION

Seller	Direct Owner	SB Motoring Pte Ltd	Direct Owner	Boeki Auto Pte Ltd
Address	-	3 Ang Mo Kio Street 62 #06-06	-	49 Sungei Kadut Loop
Office Number	-	67476028	-	67555005
Contact Person	Jeff	Andy Ng / Margaret Yeo	Nizam	Boeki

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	097D
Vehicle Details	
Vehicle No.:	SLA2476A
Vehicle to be Exported:	Yes
Intended Deregistration Date:	19 Feb 2020
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Beige
Manufacturing Year:	2010
Engine No.:	3ZZ4994395
Chassis No.:	MR053ZEE106174152
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,716.00
Original Registration Date:	25 Mar 2010
First Registration Date:	25 Mar 2010
Transfer Count:	5
Actual ARF Paid:	\$16,716.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Mar 2020
PARF Rebate Amount:	\$8,358.00
Intended COE Rebate Details	
COE Expiry Date:	24 Mar 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$20,802.00
COE Rebate Amount:	\$201.00
Total Rebate Amount:	\$8,559.00

The information contained herein is correct as at 19 Feb 2020

OK

YAP LEE MOTOR

Reg. No. 52910085A

1 Kaki Bukit Ave 6 #01-26 Autobay@Kaki Bukit Singapore 417883
Tel : 6844 1555 Fax. 6844 1311 Email : yap_lee_motor@singnet.com.sg

Date: 18th February 2020

Sompo Insurance Singapore Pte. Ltd.
50 Raffles Place
#05-01/06
Singapore Land Tower
Singapore 048623

Your Reference: FBM 8106J

Owner Name: AC Car Rental Pte Ltd
Accident Date: 2nd February 2020

Xiao Chen

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

ESTIMATE COST OF REPAIRS FOR Toyota Altis 1.6 SLA 2476A

No.	Description	Unit	Unit Price	Amount
<u>Spare Parts - List Items</u>				
1	Rear Taillamps <i>cracked</i>	1	\$ 380.00	\$ 380.00
2	Rear Bumper <i>torn</i>	1	\$ 600.00	\$ 600.00
3	Rear Bumper side brackets <i>Mr 2</i>	1	\$ 97.00	\$ 97.00
4	Rear Bumper side retainers <i>RH MR</i>	1	\$ 131.00	\$ 131.00
5	Rear n/s fender <i>Repair</i>	1	\$ 981.60	\$ 981.60
				\$ 2,189.60
			Less 25%	\$ 987.27
			Total	\$ 1,202.33
<u>Special Nett Items</u>				
1	Rear bumper clip (1 set) <i>see</i>	1	\$ 35.00	\$ 35.00
2	Rear Reverse sensor (1 set) <i>ASP MR</i>	1	\$ 350.00	\$ 350.00
3	Rear Wheel Rim <i>1700</i>		Total	\$ 385.00

400

430

YAP LEE MOTOR

Reg. No. 52910085A

1 Kaki Bukit Ave 6 #01-26 Autobay@Kaki Bukit Singapore 417883

Tel : 6844 1555 Fax. 6844 1311 Email : yap_lee_motor@singnet.com.sg

Date: 18th February 2020

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place

#05-01/06

Singapore Land Tower

Singapore 048623

Your Reference: FBM 8106J

Owner Name: AC Car Rental Pte Ltd

Accident Date: 2nd February 2020

ESTIMATE COST OF REPAIRS FOR Toyota Altis 1.6 SLA 2476A

No.	Description	Unit Price	Amount
	<u>Labour</u>		
1	To remove, refit, replaced damaged lamps and check rear electrical wiring.	\$ 80.00	\$ 80.00 30
2	To remove and refit inner garnishes, inner trim to assist repair.	\$ 150.00	\$ 150.00 X
3	To remove and refit reverse sensor.	\$ 120.00	\$ 120.00 60
4	To apply undercoating on repaired and replaced panel	\$ 150.00	\$ 150.00 50
5	To provide labour charges, workmanship to dismantle above damaged parts, repair including cut and weld; re-align body structure and damaged consistent to the accident.	\$ 600.00	\$ 600.00 300
6	To respray painting include polishing and waxing on the changed body parts, repaired portions where consistent to the accident.	\$ 700.00	\$ 700.00 40
	Total		\$ 1,800.00 840
Spare Parts - List Items Total			\$ 1,202.33
Special Nett Items Total			\$ 385.00
Labour Total			\$ 1,800.00
Grand Total			\$ 3,387.33 4527.20

total: 1952.50
L/S: 1.5K

Adnan L
N/S 17/02/20 04 pages



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL			Ref : CS/SMO20002692/Aqf3n2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERS SINGAPORE 048623			Date : 19-03-2020	
			Code : SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FBM 8106J	Veh. Inspected	SLA 2476A	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2000539/SYH	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	17/02/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA ALTIS	c.c	1598	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	MR053ZEE106174152	Colour	GOLD	
Odometer	243500	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	BRIDGESTONE	6 mm	
L/H Front Tyre	195/65 R15	BRIDGESTONE	6 mm	
R/H Rear Tyre	195/65 R15	BRIDGESTONE	6 mm	
L/H Rear Tyre	195/65 R15	BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/02/2020	Inspection Date	17/02/2020	
Survey held at	YAP LEE MOTOR BLK 1 KAKI BUKIT AVE 6 #01-26 AUTOBAY@KAKI BUKIT SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 2476A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILLAMPS	CRACKED	380.00	380.00
1	REAR BUMPER	TORN	600.00	485.00
1	REAR BUMPER SIDE BRACKETS	NOT NECESSARY	97.00	-
2	REAR BUMPER SIDE RETAINERS	O/S NECESSARY	131.00	45.00
1	REAR N/S FENDER	TO REPAIR SEE LABOUR	981.60	-
	LESS 25% DISCOUNT		-547.40	-227.50
			1,642.20	682.50
SPECIAL NETT ITEMS				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	35.00	30.00
1	SET REAR REVERSE SENSOR (SN)	NOT NECESSARY	350.00	-
1	REAR WHEEL RIM (SN)	CUT	700.00	400.00
			1,085.00	430.00
LABOUR				
	TO REMOVE,REFIT,REPLACED DAMAGED LAMPS AND CHECK REAR ELECTRICAL WIRING.		80.00	30.00
	TO REMOVE AND REFIT INNER GARNISHES,INNER TRIM TO ASSIST REPAIR.	NOT NECESSARY	150.00	-
	TO REMOVE AND REFIT REVERSE SENSOR.		120.00	60.00
	TO APPLY UNDERCOATING ON REPAIRED AND REPLACED PANEL.		150.00	50.00
	TO PROVIDE LABOUR CHARGES,WORKMANSHIP TO DISMANTLE ABOVE DAMAGED PARTS,REPAIR INCLUDING CUT AND WELD;RE-ALIGN BODY STRUCTURE AND DAMAGED CONSISTENT TO THE ACCIDENT.INCLUSIVE OF THE REPAIR OF REAR N/S FENDER.		600.00	300.00
	TO RESPRAY PAINTING INCLUDE POLISHING AND WAXING ON THE CHANGED BODY PARTS,REPAIRED PORTIONS WHERE CONSISTENT TO THE ACCIDENT.		700.00	400.00
			1,800.00	840.00
GRAND TOTAL			4,527.20	1,952.50

Report Ref No. CS/SMO20002692/Aqf3n2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			1,500.00
---	--	--	----------

Report Ref No. CS/SMO20002692/Aqf3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.