

zheng
6265 0226

PBA195JJ.

To wing — \$45 — ~~40~~ (nett)

To wing do idac — \$45 X NN

R/L Front Fork Assy — \$590 — BT (LH/RH)

under Bracket IPC — \$385 — BT

Fork Central Bracket — \$280 — BT

Front Mudguard — \$245 — DR

Front Spoling Assy — \$695 (Rim) — BT/rf

Front Brake disc Assy — \$795 — BT (LH/RH)

Front Spoling short IPC — \$85 (Rim shaft) — BT

Air Hott Assy — \$75 X NN

Head light Assy — \$385 — BT

Head light wiskim — \$220 (fsm) — DR

Head light Bracket — \$185 — BT (mkt)

R/L Meter Bracket — \$170 — BT

Meter Assy — \$950 — DR

Volt Meter IPC — \$75 X NN

Headle Bar Assy — \$180 — BT

Compuing Assy — \$145 — BT (Rim)

Brake pump — \$210 X NN

金国摩托私人有限公司
KIM KOCK MOTOR PTE LTD
27A Jurong Port Road, #01-
Singapore 619101
Tel: 6265 0226 Fax: 6265 2511

MIRPLE ASSY — ~~\$85~~ / CH \$60 ✓

A-Pole Hodel ASSY — ~~\$58~~ — / DT (Handle bar bracket uppr)

Tank Repair (Painting) \$350 x R (~~\$200~~) Labour

AIR PIPE Pustem — ~~\$780~~ / DT \$650 ✓
(Handle) (EXL p/r)
CENTR

REAR PIPE (Blue Flame) — ~~\$1450~~ / DT \$1200 ✓

REAR Box & Bracket Repair — ~~\$80~~ x NN

Engin CAR ASSY — ~~\$180~~ / DT (Sink bar LH)

(L) SIDE stem 1 pc — ~~\$492~~ / OR

Labour. — ~~\$280~~ . 250 (Labour)

SIDE stem SWATH 1 pc \$78 . x NN

\$9199

2

Steve (LKK) wil Nil

83228813

18/2/20, 12:00pm

3 dys

L/S

M AL SJ

ckauto.com

金国摩哆私人有限公司
KIM KOCK MOTOR PTE LTD
Blk 27A, Jurong Port Road, #01-19,
Singapore 619101
Tel: 6265 0226 Fax: 6265 2588

P-7556

-19%

6800-40

NetH-40

L-450

7290.40

L/S-5832-32

= 5850

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: