

Co. Reg. No.: 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
Tel : 6636 9100 Fax : 6636 9113

Date : 14/02/2020

TO: FWD Singapore Pte Ltd
6 Temasek Boulevard
#18-01 Suntec Tower Four
Singapore 038986

Xiao Tong

Our Customer : Chua Kia Kong
Vehicle No : SGV7148M
Model : Mitsubishi Lancer 1.6A
Manufacture Year : 2007
Date of Accident : 14/02/2020
Total Estimate Repair Days : 14
Total Pages : 3

Attn : Motor Claims Department
Email : motorclaims.sg@fwd.com

Re: Repair Estimate For Third Party Claim against SLX3416X

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Bonnet <i>Dented</i>	1	\$810.00	\$810.00	✓
2	Bonnet lock <i>2pt</i>	1	\$158.00	\$158.00	✓
3	Bonnet weatherstrip - inner	1	\$68.00	\$68.00	+
4	Bonnet weatherstrip - outer <i>for</i>	1	\$68.00	\$68.00	+
5	Bonnet hinges <i>Best</i>	2	\$125.00	\$250.00	✓
6	Bonnet stand <i>new</i>	1	\$55.00	\$55.00	+
7	Bonnet stand clip <i>new</i>	1	\$10.00	\$10.00	+
8	Bonnet insulator <i>coupled</i>	1	\$175.00	\$175.00	✓
9	Headlamp RH <i>coupled</i>	1	\$658.00	\$658.00	✓
10	Headlamp LH <i>coupled</i>	1	\$658.00	\$658.00	✓
11	Headlamp top rubber RH <i>2pt</i>	1	\$45.00	\$45.00	+
12	Headlamp top rubber LH <i>for</i>	1	\$45.00	\$45.00	+
13	Front bumper <i>Dented</i>	1	\$729.00	\$729.00	✓
14	Front bumper side retainer RH <i>for</i>	1	\$45.00	\$45.00	✓
15	Front bumper side retainer LH <i>for</i>	1	\$45.00	\$45.00	✓
16	Front bumper reinforcement <i>Best</i>	1	\$313.00	\$313.00	✓
17	Front bumper centre beam <i>new</i>	1	\$189.00	\$189.00	+
18	Front number plate garnish <i>Dented</i>	1	\$128.00	\$128.00	✓
19	Front bumper lower grille <i>Dented</i>	1	\$180.00	\$180.00	✓
20	Front bumper garnish RH <i>for</i>	1	\$75.00	\$75.00	+
21	Front bumper garnish LH <i>for</i>	1	\$75.00	\$75.00	+
22	Front grille RH <i>Dented</i>	1	\$210.00	\$210.00	+
23	Front grille LH <i>Dented</i>	1	\$210.00	\$210.00	+
24	Front grille base <i>Dented</i>	1	\$286.00	\$286.00	✓
25	Front grille "Mitsubishi" logo <i>new</i>	1	\$58.00	\$58.00	✓
26	Support panel assy <i>Backend</i>	1	\$1,150.00	\$1,150.00	✓
27	Support stay panel <i>Best</i>	1	\$137.00	\$137.00	✓
28	Radiator <i>Dented</i>	1	\$1,294.00	\$1,294.00	✓
29	Radiator fan motor <i>new</i>	1	\$475.00	\$475.00	+
30	Radiator fan blade <i>new</i>	1	\$157.00	\$157.00	+
31	Radiator spare tank <i>new</i>	1	\$98.00	\$98.00	+
32	Radiator cowling <i>new</i>	1	\$266.00	\$266.00	+
33	Air-con condenser <i>Best</i>	1	\$914.00	\$914.00	✓
34	Air-condenser fan motor <i>new</i>	1	\$475.00	\$475.00	+

Premium Carz

Services Pte Ltd

Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel : 6636 9100 Fax : 6636 9113

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
35	Air-con condenser fan blade <i>new</i>	1	\$157.00	\$157.00	✓
36	Air filter housing <i>new</i>	1	\$473.00	\$473.00	✓
37	Air duct <i>new</i>	1	\$247.00	\$247.00	✓
38	Wiper washer tank <i>new</i>	1	\$257.00	\$257.00	✓
39	Wiper washer tank motor <i>new</i>	1	\$98.00	\$98.00	✓
40	Battery tray <i>new</i>	1		\$0.00	✓
41	Battery cover <i>new</i>	1		\$0.00	✓
42	Front chassis RH <i>new</i>	1	repair	repair	✓
43	Front fender RH <i>new</i>	1	\$596.00	\$596.00	✓
44	Front fender LH <i>new</i>	1	repair	repair	✓
45	Front fender indicator light RH <i>new</i>	1	\$67.00	\$67.00	✓
46	Front fender chrome RH <i>new</i>	1	\$55.00	\$55.00	✓
47	Front door RH <i>new</i>	1	repair	repair	✓
48	Rear bumper <i>new</i>	1	\$710.00	\$710.00	✓
49	Rear bumper centre bracket <i>new</i>	1	\$171.00	\$171.00	✓
50	Rear bumper bracket RH <i>new</i>	1	\$45.00	\$45.00	✓
51	Rear bumper bracket LH <i>new</i>	1	\$45.00	\$45.00	✓
52	Boot lid <i>new</i>	1	\$593.00	\$593.00	✓
53	Boot lid stopper <i>new</i>	2	\$55.00	\$110.00	✓
54	Boot lid lock <i>new</i>	1	\$61.00	\$61.00	✓
55	Boot lid lower catch <i>new</i>	1	\$28.00	\$28.00	✓
56	Boot lid "Mitsubishi" logo <i>new</i>	1	\$46.00	\$46.00	✓
57	Boot lid "Lancer" emblem <i>new</i>	1	\$43.00	\$43.00	✓
58	Boot lid "GLX" emblem <i>new</i>	1	\$33.00	\$33.00	✓
59	Boot lid weatherstrip <i>new</i>	1	\$169.00	\$169.00	✓
60	Boot lid hinge <i>new</i>	2	\$84.00	\$168.00	✓
61	Rear license plate garnish <i>new</i>	1	\$198.00	\$198.00	✓
62	Rear end panel <i>new</i>	1	\$423.00	\$423.00	✓
63	Rear end panel garnish <i>new</i>	1	\$150.00	\$150.00	✓
64	Tail lamp LH <i>new</i>	1	\$404.00	\$404.00	✓
65	Spare tyre panel <i>new</i>	1	repair	repair	✓
66	Spare tyre board <i>new</i>	1	\$156.00	\$156.00	✓
			Sub-Total	\$16,012.00	
			Less 10%	\$1,601.20	
			Sub Total 1	\$14,410.80	
<p>10373 9335.70</p>					
B.	Spare Parts (S/Nett)				
1	Front bumper clip <i>new</i>	10	\$5.00	\$50.00	30
2	Air duct clip <i>new</i>	3	\$5.00	\$15.00	✓
3	Bonnet insulator clip <i>new</i>	10	\$5.00	\$50.00	-30
4	Front grille clip <i>new</i>	6	\$5.00	\$30.00	10
5	Front fender inner shield clip <i>new</i>	10	\$5.00	\$50.00	✓
6	Front number plate w/casing <i>new</i>	1	\$70.00	\$70.00	✓
7	Coolant <i>new</i>	1	\$60.00	\$60.00	40
8	Horn (set) <i>new</i>	1	\$188.00	\$188.00	✓
9	Radiator top hose <i>new</i>	1	\$45.00	\$45.00	✓
10	Radiator bottom hose <i>new</i>	1	\$55.00	\$55.00	✓
11	Air-con liquid pipe <i>new</i>	1	\$150.00	\$150.00	✓
12	Air-con discharge pipe <i>new</i>	1	\$112.00	\$112.00	✓
13	Air-con suction pipe <i>new</i>	1	\$152.00	\$152.00	✓

Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel : 6636 9100 Fax : 6636 9113

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
14	Tail lamp clip <i>new</i>	4	\$5.00	\$20.00	+ +
15	Reverse sensor (set) new <i>new</i>	1	\$250.00	\$250.00	+ +
16	Rear number plate w/casing <i>new</i>	1	\$70.00	\$70.00	+
17	Rear bumper clip <i>new</i>	10	\$5.00	\$50.00	+ 30
18	Rear end panel garnish clip <i>new</i>	10	\$5.00	\$50.00	+
Sub Total 2				\$1,467.00	
Total for Parts				\$15,877.80	
C. Labour					
1	To check wiring and refocus headlamp.			\$120.00	30
2	Front - Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$1,200.00	1000
3	Front - Spray painting all affected parts & areas.			\$1,400.00	1000
4	Rear - Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$800.00	300
5	Rear - Spray painting all affected parts & areas.			\$1,000.00	400
6	To spray anti-rust undercoat.			\$120.00	60
7	To remove and refit rear seats, rear wheelhouse inner garnish, floor carpet & upholstery to facilitate repairs.			\$250.00	+
8	To remove and refit radiator and air-con condenser and to vacuum air-con system and charge up air-con gas.			\$350.00	120
Total Labour				\$5,240.00	
Total Repair Cost				\$21,117.80	

2910

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

total: 12515.70
L/S: A.31K (Nett Value)

Yours faithfully,

Aun Teng
f Premium Carz Services Pte Ltd

Surveyor's Details	
Name	Adrian Hng
Contact	96893735
Survey Date	17/02/20
Recommender	Authorize / Not Authorize
Before Paint	Yes / <input checked="" type="checkbox"/> No

n/s. 09 Days.