

96340429
SOL



QUOTE

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
068811
SINGAPORE

Date
17 Mar 2020

Expiry
24 Mar 2020

Quote Number
QU-2019706

Reference
E71T - RANGE ROVER
L405 -
SALGA2EEXDA109974

Exquisite Marques
200804960Z

Exquisite Marques Holding
Pte. Ltd.

Reg. No. 200804960Z
1010 Bukit Merah Lane 3
#01-119
SINGAPORE 159724
Ph: (65) 6542 1151
Fax: (65) 6543 1161

Accident Quote

Description	Quantity	Unit Price	Amount SGD
LABOUR: - Remove and replace left hand side cap and front left hand side door handle. — 100 - Remove and replace rear lower moulding left and right. — 250 - Remove and replace clip trim, moulding for front left door outside, both left and right upper door moulding, both left and right fender moulding, buffer, clip sill, screw, expansion nut and moulding for left and right lower outside door. — 250 - Remove and replace mirror housing left hand side, left mirror, motor, screw, left lamp, glass, insulator and screw. — 250 - Remove and replace regulator for left front window, screw and glass for left door. — 100 - Remove and replace left hinges for front door. — 50 - Remove and replace front left and right fender, moulding, hood, gas strut and hinge. — 500 - Remove and replace left hand side headlamp. — 250 - Remove and replace rear left door glass. — 100 - Remove and replace both left and right finisher. — 50 - Remove, clean and replace Range Rover badges. — 50 - Remove and replace tow hook. — 500 - Remove and replace rear body panel and cross member. — 1000 - Remove and replace both left and right rear door panel. — 500 - Remove and replace tail gate left and right, upper and lower, hinge. — 50 - Repair, knock and pull parts that can be repair. — 2000	1.00	29,000.00	29,000.00
LABOUR: - Smoothing out the surface for necessary parts that need to respray, - Respray all parts that needed to be respray.	1.00	6,000.00	6,000.00 2000
PARTS: LHS CAP - DOOR LOCKING MECHANISM LESS LOCK BARREL APERTURE, PRIMED	1.00	121.50	121.50
PARTS: FRONT LHS DOOR HANDLE	1.00	380.00	380.00

E 71 T

**Exquisite
Marques****QUOTE**

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
068811
SINGAPORE

Date
10 Mar 2020

Expiry
24 Mar 2020

Quote Number
QU-2019706

Reference
E71T - RANGE ROVER
L405 -
SALGA2EEXDA109974

Exquisite Marques
200804960Z

Exquisite Marques Holding
Pte. Ltd.
Reg. No. 200804960Z
1010 Bukit Merah Lane 3
#01-119
SINGAPORE 159724
Ph: (65) 6542 1151
Fax: (65) 6543 1161

Accident Quote

Description	Quantity	Unit Price	Amount SGD
LABOUR: -To remove, repair and replace the following items.	1.00	35,000.00	35,000.00
PARTS: LHS CAP - DOOR LOCKING MECHANISM LESS LOCK BARREL / CUT	1.00	121.50	121.50
PARTS: FRONT LHS DOOR HANDLE / CUT	1.00	380.00	380.00
PARTS: MOULDING LH & RH, LOWER (fwd only) / OR	2.00	380.00	760.00
PARTS: CLIP TRIM CLIP 8 X 0.8 - 1.2, REAR WHEELARCH MOULDING / MK	2.00	18.00	36.00
PARTS: MOULDING - DOOR OUTSIDE LH, FRONT DOOR / CUT	2.00 /	459.00	918.00
PARTS: MOULDING - DOOR OUTSIDE LH/RH UPPER / CUT	2.00	280.00	560.00
PARTS: MOULDING - FENDER LH/RH UPPER, PRIMED / CUT	2.00	180.00	360.00
PARTS: BUFFER - RUBBER MOTOR MOUNTING ATTACHES MOULDING / CM	2.00	18.00	36.00
PARTS: CLIP SILL / MK	8.00	15.00	120.00
PARTS: SCREW M5 X 20MM, SELF TAPPING, FENDER / MK	2.00	18.00	36.00
PARTS: CLIP CLIP LANTERN 8.2 X 0.65-1 + 2 PLASTIC / MK	8.00	18.00	144.00

Description	Quantity	Unit Price	Amount SGD
PARTS: NUT EXPANSION NUT 4.8 X 9.0 X 9.0 X 1.0 / MC	8.00	18.00	144.00
PARTS: SCREW 4.8 X 19MM, TORX / MC	8.00	15.00	120.00
PARTS: MOULDING - DOOR OUTSIDE LH/RH LOWER, PRIMED (LH) - BR 2.00 1.0	2.00	320.00	640.00
PARTS: MOULDING - DOOR OUTSIDE FRONT DOOR, LH/ RH LOWER, PRIMED (LH) / MC 2.00 1.0	2.00	380.00	760.00
PARTS: COVER - MIRROR HOUSING LH X	1.00	220.00	220.00
PARTS: MIRROR LH / BR	1.00	1,600.00	1,600.00
PARTS: MOTOR LH X	1.00	235.00	235.00
PARTS: SCREW M3 X 25MM, MOTOR MOUNTING / MC	1.00	18.00	18.00
PARTS: LAMP LH X	1.00	255.00	255.00
PARTS: GLASS CONVEX GLASS, LH X	1.00	567.00	567.00
PARTS: INSULATOR - SOUND LH / BR	1.00	75.00	75.00
PARTS: SCREW M6 X 16MM, TORX, MIRROR TO DOOR / MC	3.00	18.00	54.00
PARTS: REGULATOR - WINDOW LH, CONTAINS MOTOR ASSY / Janned	1.00	585.00	585.00
PARTS: SCREW M6 X 20MM, TORX, WINDOW REGULATOR / MC	1.00	15.00	15.00
PARTS: GLASS LH ?	1.00	570.00	570.00
PARTS: DOOR - FRONT - LESS HINGES LH, CATEGORY B / DD	1.00	4,076.47	4,076.47
PARTS: FENDER - FRONT RH/LH, CATEGORY B / DD	2.00	1,650.00	3,300.00
PARTS: MOULDING (Beet glass) ?	1.00	1,550.00	1,550.00
PARTS: HOOD CATEGORY B (Beet) / DD	1.00	4,250.00	4,250.00
PARTS: GAS STRUT X	2.00	121.50	243.00
PARTS: HINGE - HOOD LH/RH (RH) / BT 2.00 1.0	2.00	176.72	353.44

Description	Quantity	Unit Price	Amount SGD
PARTS: HEADLAMP LH / BR	1.00	4,700.00	4,700.00
PARTS: GLASS-REAR DOOR LH / CHT	1.00	481.95	481.95
PARTS: FINISHER LH / Duv growth (Black) / CHT	1.00 2.00	172.13	172.13
PARTS: BADGE (RANGE) / MK	1.00	183.60	183.60
PARTS: BADGE (ROVER) / MK	1.00	183.60	183.60
PARTS: TOW HOOK (Raw Edge m/L) / BT	1.00	3,500.00	3,500.00
PARTS: PANEL - BODY REAR CATEGORY A / DD	1.00	3,997.82	3,997.82
PARTS: CROSSMEMBER CATEGORY A / DD	1.00	3,800.00	3,800.00
PARTS: REAR DOOR PANEL LH/RH / DD	2.00	3,900.00	7,800.00
PARTS: HINGE - TAILGATE LH/RH, UPPER / BT	2.00	145.80	291.60
PARTS: HINGE - TAILGATE LH/RH, LOWER / BT	2.00	183.60	367.20

Additional parts may be required during the repair process which will be quoted and billed separately as required

- All parts required 2-3 weeks to order

Subtotal 83,580.31

TOTAL LOCAL SUPPLY OF GOODS AND SERVICES 7% 5,850.62

TOTAL SGD 89,430.93

Steve (LKK) 11/3/20, 12.30pm

P/P

Ry B/L SLJ

Labour & paint - ?
Repair days - ?

Terms

Bank Details:

Account Name: Exquisite Marques Holding Pte. Ltd.
Account No: 451-306-858-8
Bank Name: United Overseas Bank
Swift Code: UOVBSGSG
Bank Code: 7375
Branch Code: 001

PayNow:

UEN Code: 200804980Z
Reference: "Invoice Number"

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: