



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring
#08-1339 Singapore 470130
Tel: 9450 7920
zoomautowerks@gmail.com

not Allowed
llw
1/5 @2850/
Sdays.

Car Number: SJG4044S

Date: 19/02/2020

Model : HONDA CIVIC

Damaged Area: (Rear RH Portion)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

Parts / Material :

- | | | |
|----|----------------------------------|--------|
| 1 | Rear Bumper | 638.00 |
| 2 | Rear Bumper Retainer | |
| 3 | Rear Bumper Bracket | |
| 4 | Rear Bumper Reinforcement | |
| 5 | Rear Bumper Clips | 35.00 |
| 6 | BootLid | 610.90 |
| 7 | Bootlid Badge | 28.80 |
| 8 | Bootlid Badge (CIVIC) | 35.00 |
| 9 | Bootlid Badge (HYBRID) | 45.00 |
| 10 | Bootlid Lamp RH | |
| 11 | Bootlid Lamp Clips | |
| 12 | Bootlid Inner lock | |
| 13 | Bootlid Catch | |
| 14 | Bootlid weather Strip | |
| 15 | Rear Taillamp RH | 285.40 |
| 16 | Rear End Panel | 216.00 |
| 17 | Rear End Panel Top Garnish | |
| 18 | Rear End Panel Top Garnish Clips | |
| 19 | Rear Fender Inner Shield RH | 66.50 |
| 20 | Rear Fender Inner Shield Clips | |
| 21 | Rear Exhaust End Pipe | |
| 22 | Rear Exhaust Chrome Muffler | 120.00 |
| 23 | Rear Exhaust Pipe Mounting | |
| 24 | Rear Exhaust Heat Shield | |
| 25 | Spare Tyre Panel | |
| 26 | Spare Tyre Top Trim | |
| 27 | Spare Tyre Top Board | |

Quantity

11	Re/To. 1	\$	860.00	✓
11	\$60.00 X 2pcs	\$	120.00	X
11	\$40.00 X 2pcs	\$	80.00	X
25	\$78.00 X 2pcs	\$	156.00	X
	re	\$	60.00	✓
	re	\$	852.00	✓
	re	\$	75.00	✓
	re	\$	55.00	✓
	re	\$	68.00	✓
	11	\$	425.00	X
	11	\$	20.00	X
	11	\$	196.00	X
	11	\$	65.00	X
	11	\$	275.00	X
	re	\$	720.00	✓
	re	\$	725.00	✓
	11	\$	245.00	X
	11	\$	60.00	X
	re	\$	195.00	✓
	11	\$	60.00	X
	re	\$	1,150.00	X
	re	\$	175.00	✓
11	\$58.00 X 2pcs	\$	116.00	X
	11	\$	145.00	X
	11	\$	896.50	X
	11	\$	195.80	X
	11	\$	256.30	X

2180.60
1744.48

Parts : \$ 8,246.60

Less Parts 20% : \$ 1,649.32

Total Parts : \$ 6,597.28

Special Net Items :

- Reverse Sensor
Rear Number Plate With Garnish
Rear Exhaust Gum
Rear End Panel Sealant

re	\$	250.00	200
11	\$	80.00	X
11	\$	120.00	X
re	\$	80.00	50

Total S/N Parts : \$ 530.00

Labour :

- To Putty, Spray Paint on Rear Affected Accident Areas
To Remove & Renew Rear Affected Accident Areas
To Transfer All Bootlid Components to Facilitate Repairs

\$	1,200.00	800
\$	1,400.00	600
\$	150.00	60

To Transfer All Bootlid Interior Components to Facilitate Repairs
 To Check & Re-Connect all electrical wiring
 To Re-position & Install Reverse Sensor
 To Conduct Water Leakage Test
 To Re-Programme & Reset Diagnostic
 To Rust Proof Affected Areas

Repair	\$	150.00	X
	\$	50.00	20
	\$	150.00	20
17	\$	150.00	X
17	\$	250.00	X
	\$	100.00	60
Total Labour :		\$	3,600.00

TOTAL PARTS :	\$	6,597.28
TOTAL SPECIAL NET ITEM:	\$	530.00
TOTAL LABOUR :	\$	3,600.00
TOTAL REPAIR COST :	\$	<u>10,727.28</u>

P - 1744.48
 S.N - 250.00
 L - 1590.00

 3584.48
 202

 2867.58

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: