



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV No. AC2004545  
INV Date 25/06/2020  
Reference CC4/FCI20002768/Uea3q2  
Code FCI2



#### PROFESSIONAL SERVICE FEE

Vehicle No. SMH 644X  
Insured Veh. SHD 3606S  
Claim No. D20001012MFSH  
Policy No. D-20094922MFSH  
Accident Date 12/02/2020  
Inspection Date 26/02/2020

Description	Total
Third Party Express Settlement	350.00
<b>Subtotal</b>	<b>350.00</b>
<b>GST (7%)</b>	<b>24.50</b>
<b>Grand Total</b>	<b>374.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**Affiliated to Federation Internationale Des Experts En Automobile**

MS FIRST CAPITAL INSURANCE LTD	Ref : CC4/FCI20002768/Uea3q2
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877	Date : 25-06-2020
	Code : FCI2



**1. Policy Particulars :- THIRD PARTY CLAIM**

<b>Insured Veh.</b>	SHD 3606S	<b>Veh. Inspected</b>	SMH 644X
<b>Policy No.</b>	D-20094922MFSH	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	D20001012MFSH	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	KAREN TAN	<b>Assign Date</b>	26/02/2020

**2. Vehicle Particulars & Condition**

<b>Make &amp; Model</b>	HONDA JAZZ (A)	<b>c.c</b>	1318
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2019
<b>Chassis No.</b>	JHMGK3850KS200156	<b>Colour</b>	RED
<b>Odometer</b>	16681	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

**3. Conditions of Tyres**

	Size	Make	Balance
<b>R/H Front Tyre</b>	175/65 R15	DUNLOP	7 mm
<b>L/H Front Tyre</b>	175/65 R15	DUNLOP	7 mm
<b>R/H Rear Tyre</b>	175/65 R15	DUNLOP	7 mm
<b>L/H Rear Tyre</b>	175/65 R15	DUNLOP	7 mm

**4. Description of Damages**

	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.
--	---

**5. General Information**

<b>Accident Date</b>	12/02/2020	<b>Inspection Date</b>	26/02/2020
<b>Survey held at</b>	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		

**5a. Remarks**

	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--	--

**5b. Estimate Days of Repair**

	ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>4 Working Days</b>
--	-------------------------------------	-----------------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMH 644X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	MIRROR ASSY ,R (SN)	CRACKED	389.77	389.77
1	SKULLCAP R COVER (SN)	CRACKED	39.97	39.97
1	WHEEL ,DISK AL 15X7 (SN)	NOT NECESSARY	342.90	-
1	FACE ,FR BUMPER (SN)	CUT /DEFORMED	388.27	388.27
1	BEAM UPPER ,R.FR. BUMPER (SN)	NOT NECESSARY	21.30	-
1	SPACERR.FR.BUMPER (SN)	NOT NECESSARY	7.80	-
1	SPACERL.FR.BUMPER (SN)	NOT NECESSARY	7.80	-
19	CLIP ,BUMPER (SN)	NECESSARY	32.77	32.77
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	TAPE SETR .FR.DOOR (ADDITIONAL) (SN)	SCRATCHED	25.87	25.87
			1,306.45	896.65
<b>LABOUR</b>				
WHEEL ALIGNMENT X4.			180.00	180.00
INSPECT FR LIGHTING MECHANISMS & FOCUS.			180.00	120.00
STRAIGHTEN ALIGN BULKHEAD & WHEELHOUSE EXTENSION.			1,400.00	840.00
SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.			2,000.00	1,400.00
			3,760.00	2,540.00
<b>GRAND TOTAL</b>			<b>5,066.45</b>	<b>3,436.65</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>3,436.65</b>

Report Ref No. CC4/FCI20002768/Uea3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd




51 Ubi Ave 1 #01-25 Payco Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMH 644X

INSPECTION







**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R











**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R











**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Payco Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R








**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMH 644X

RE-INSPECTION





## LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMH 644X

RE-INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

