



**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

*p/p # 3436-61*  
*4 days*

# QUOTATION

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

<b>Customer</b>	: MS FIRST CAPITAL INSURANCE LIMITED 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877	<b>Document No.</b>	: SQT20000721	<b>Page</b>	1
<b>Registration No</b>	: SMH644X	<b>Date</b>	: 13. Feb 2020	<b>Customer No.</b>	: WZF002
<b>Chassis No</b>	: JHMGK3850KS200156	<b>Svc Advisor</b>	: YOU PO SOON	<b>Engine No</b>	: L13B14100040
<b>Model</b>	: JAZZ 1.3LXR CVT 19YM (EURO 6)	<b>Date   Time</b>	: 13. Feb 2020 10:51:02 AM	<b>Surveyor Name</b>	:
<b>Owner's Name</b>	: ELIJAH-JAMES KE RUSHAN	<b>Survey Date</b>	:	<b>Authorisation Date</b>	:
<b>Ins Policy No.</b>	:				
<b>Date of Accident</b>	: 12/2/2020				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST	
	TP DIRECT SETTLEMENT (J/NO. ) OWNER: ELIJAH-JAMES KE RUSHAN OWNER INSURER: TOKIO MARINE INSURANCE ACC DATE: 12-2-2020 SURVEYED BY: DATE: REF NO: TP INSURER: MS FIRST CAPITAL INSURANCE LIMITED TP VEH: SHD3606S							
76208-T5A-J32	MIRROR ASSY.R.	<i>one</i> 1	519.70	✓ 25	389.77	27.28	417.05	
76201-T5A-J31ZB	SKULLCAP.R. <i>cover</i>	<i>CRA</i> 1	53.30	✓ 25	39.97	2.80	42.77	
42700-T5S-M72	WHEEL,DISK AL 15X7	<i>nn</i> 1	457.20	X 25	342.90	24.00	366.90	
04711-T5A-J50ZZ	FACE,FR BUMPER	<i>cu, /re</i> 1	517.70	✓ 25	388.27	27.18	415.45	
71140-T5A-J50	BEAM UPPER,R.FR.BUMPER	<i>11</i> 1	28.40	X 25	21.30	1.49	22.79	
71193-T5A-000	SPACERR.FR BUMPER	<i>11</i> 1	10.40	X 25	7.80	0.55	8.35	
71198-T5A-000	SPACERL.FR BUMPER	<i>11</i> 1	10.40	X 25	7.80	0.55	8.35	
91505-TM8-003	CLIP,BUMPER	<i>111</i> 19	2.30	✓ 25	32.77	2.29	35.06	
					<b>Sum Item</b>	<b>1230.58</b>	<b>86.14</b>	<b>1,316.72</b>
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00	✓	180.00	12.60	192.60	
					<b>Sum Ext. Service</b>	<b>180.00</b>	<b>12.60</b>	<b>192.60</b>
BOSUN	SUNDRIES	<i>111</i> 1	50.00	<i>20</i>	50.00	3.50	53.50	
BML011	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00	<i>120</i>	180.00	12.60	192.60	
BKBH11S	STRAIGHTEN ALIGN BULKHEAD & WHEELHOUSE EXTENSION	<i>130</i> 1	1400.00	<i>140</i>	1400.00	98.00	1498.00	
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P)	<i>460</i> 1	2000.00	<i>1400</i>	2000.00	140.00	2140.00	
					<b>Sum Labor</b>	<b>3630.00</b>	<b>254.10</b>	<b>3,884.10</b>

Printed on 13/2/2020 6:36:34 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



**KAH MOTOR CO. SDN. BHD.**  
 (A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

# QUOTATION

GST Reg No.: M200050223  
 Company Ref. No.: S60FC1380G

<b>Customer</b>	: MS FIRST CAPITAL INSURANCE LIMITED 36 ROBINSON ROAD #16-01 CITY HOUSE SINGAPORE 068877	<b>Document No.</b>	: SQT20000721	<b>Page</b>	2
<b>Registration No</b>	: SMH644X	<b>Date</b>	: 13. Feb 2020	<b>Customer No.</b>	: WZF002
<b>Chassis No</b>	: JHMGK3850KS200156	<b>Svc Advisor</b>	: YOU PO SOON	<b>Engine No</b>	: L13B14100040
<b>Model</b>	: JAZZ 1.3LXR CVT 19YM (EURO 6)	<b>Date   Time</b>	: 13. Feb 2020 10:51:02 AM	<b>Surveyor Name</b>	:
<b>Owner's Name</b>	: ELIJAH-JAMES KE RUSHAN	<b>Survey Date</b>	:	<b>Authorisation Date</b>	:
<b>Ins Policy No.</b>	:				
<b>Date of Accident</b>	: 12/2/2020				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Survey By	<u>Marcus Lim</u>						
Date & Time	<u>26/2/20</u>						
Excess							
Status	<u>not default</u>						
Signature	<u>take place before paying - 4 days.</u>						
<b>Total Amount</b>					5,040.58	352.84	5,393.42
<b>Total (Inclusive of GST)</b>							<u>5,393.42</u>

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature: \_\_\_\_\_  
 Date: \_\_\_\_\_

Printed on 13/2/2020 6:36:34 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded.



**KAH MOTOR CO. SDN. BHD.**  
 (A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

# QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

**Customer** : MS FIRST CAPITAL INSURANCE LIMITED  
 36 ROBINSON ROAD  
 #16-01 CITY HOUSE  
 SINGAPORE 068877

**Registration No** : SMH644X

**Chassis No** : JHMGK3850KS200156

**Model** : JAZZ 1.3LXR CVT 19YM (EURO 6)

**Owner's Name** : ELIJAH-JAMES KE RUSHAN

**Ins Policy No.** :

**Date of Accident** :

**Document No.** : SQT20001359 **Page** 1

**Date** : 26. Mar 2020

**Customer No.** : WZF002

**Svc Advisor** : YOU PO SOON

**Engine No** : L13B14100040

**Date | Time** : 26. Mar 2020 5:44:54 PM

**Surveyor Name** :

**Survey Date** :

**Authorisation Date** :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
SUPPLEMENTARY PARTS AND LABOUR							
67324-T5A-003	TAPE SETR.FR.DOOR <i>ADD</i>	<i>SCR 1</i>	34.50	25	25.87	1.81	27.68
<b>Sum Item</b>					<b>25.87</b>	<b>1.81</b>	<b>27.68</b>

Survey By \_\_\_\_\_

Date & Time \_\_\_\_\_

Excess \_\_\_\_\_

Status \_\_\_\_\_

Signature \_\_\_\_\_

	<b>Total Amount</b>	25.87	1.81	27.68
	<b>Total (Inclusive of GST)</b>			<b>27.68</b>

Printed on 26/3/2020 5:46:05 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



26/3/2020  
 Attn: Marcus  
 WD = 4 Day.

Page 1/1

# SERVICE PRE-INVOICE

**KAH MOTOR CO. SDN. BHD.**  
 (A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223  
 Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022  
 255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

<b>Customer:</b>	CU0119955 / MS FIRST CAPITAL	<b>Document No:</b>	SVO20012894
<b>Chassis No:</b>	JHMGK3850KS200156	<b>Printed By:</b>	PSYOU
<b>License No:</b>	SMH644X	<b>Order Date:</b>	26. February 2020
<b>Mileage:</b>	16681	<b>Order Time:</b>	10:40:44 AM
<b>Engine No:</b>	L13B14100040	<b>Service Advisor:</b>	YOU PO SOON

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 74390 ) OWNER: ELIJAH-JAMES KE RUSHAN OWNER INSURER: TOKIO MARINE INSURANCE ACC DATE: 12-2-2020 SURVEYED BY: MARCUS CHUA DATE: 26/2/2020 REF NO: TP INSURER: MS FIRST CAPITAL INSURANCE LIMITED TP VEH: SHD3606S						
76208-T5A-J32	MIRROR ASSY,R.	1	519.70	25	389.77	27.28	417.05
04711-T5A-J50ZZ	FACE,FR.BUMPER	1	517.70	25	388.27	27.18	415.45
91505-TM8-003	CLIP,BUMPER	19	2.30	25	32.77	2.29	35.06
67324-T5A-003	TAPE SETR.FR.DOOR	1	34.50	25	25.87	1.81	27.68
76201-T5A-J31ZB	SKULLCAP,R.	1	53.30	25	39.97	2.80	42.77
	<b>SUM PARTS:</b>				<b>876.65</b>	<b>61.36</b>	<b>938.01</b>
BOSUN	0760 SUNDRIES	1	20.00		20.00	1.40	21.40
BML01I	EXT-YJ INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)	1	120.00		120.00	8.40	128.40
BKBH11S	EXT-YJ STRAIGHTEN ALIGN BULKHEAD & WHEELHOUSE EXTENSION INCLUDING FITTINGS ON ATTACHMENT ITEMS.	1	840.00		840.00	58.80	898.80
BP04R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(3P)	1	1,400.00		1,400.00	98.00	1,498.00
	<b>SUM LABOUR:</b>				<b>2,380.00</b>	<b>166.60</b>	<b>2,546.60</b>
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
	<b>SUM EXT SERVICE:</b>				<b>180.00</b>	<b>12.60</b>	<b>192.60</b>
	<b>TOTAL SGD</b>				<b>3,436.65</b>	<b>240.56</b>	<b>3,677.21</b>
	<b>Total Payable (SGD)</b>						<b>3,677.21</b>

GST Amount is calculated from individual line(s)