



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SMH644X
Chassis No : JHMGK3850KS200156
Model : JAZZ 1.3LXR CVT 19YM (EURO 6)
Owner's Name : ELIJAH-JAMES KE RUSHAN
Ins Policy No. :
Date of Accident : 12/2/2020

Document No. : SQT20000721 Page 1
Date : 13. Feb 2020
Customer No. : WZF002
Svc Advisor : YOU PO SOON
Engine No : L13B14100040
Date | Time : 13. Feb 2020 10:51:02 AM
Surveyor Name :
Survey Date :
Authorisation Date :

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST |
|-------------------|--|-----|-------------------------|--------|----------------|---------------|------------------|
| | TP DIRECT SETTLEMENT (J/NO:) OWNER: ELIJAH-JAMES KE RUSHAN OWNER INSURER: TOKIO MARINE INSURANCE ACC DATE: 12-2-2020 SURVEYED BY: DATE: REF NO: TP INSURER: MS FIRST CAPITAL INSURANCE LIMITED TP VEH: SHD3606S | | | | | | |
| 76208-T5A-J32 | MIRROR ASSY,R. | 1 | 519.70 | 25 | 389.77 | 27.28 | 417.05 |
| 76201-T5A-J31ZB | SKULLCAP,R. <i>cover</i> | 1 | 53.30 | 25 | 39.97 | 2.80 | 42.77 |
| 42700-T5S-M72 | WHEEL,DISK AL 15X7 | 1 | 457.20 | 25 | 342.90 | 24.00 | 366.90 |
| 04711-T5A-J50ZZ | FACE,FR.BUMPER | 1 | 517.70 | 25 | 388.27 | 27.18 | 415.45 |
| 71140-T5A-J50 | BEAM UPPER,R.FR.BUMPER | 1 | 28.40 | 25 | 21.30 | 1.49 | 22.79 |
| 71193-T5A-000 | SPACERR.FR.BUMPER | 1 | 10.40 | 25 | 7.80 | 0.55 | 8.35 |
| 71198-T5A-000 | SPACERL.FR.BUMPER | 1 | 10.40 | 25 | 7.80 | 0.55 | 8.35 |
| 91505-TM8-003 | CLIP,BUMPER | 19 | 2.30 | 25 | 32.77 | 2.29 | 35.06 |
| | | | Sum Item | | 1230.58 | 86.14 | 1,316.72 |
| BO-WHEEL ALIGN X4 | WHEEL ALIGNMENT X4 | 1 | 180.00 | | 180.00 | 12.60 | 192.60 |
| | | | Sum Ext. Service | | 180.00 | 12.60 | 192.60 |
| BOSUN | SUNDRIES | 1 | 50.00 | | 50.00 | 3.50 | 53.50 |
| BML011 | INSPECT FR LIGHTING MECHANISMS & FOCUS | 1 | 180.00 | | 180.00 | 12.60 | 192.60 |
| BKBH11S | STRAIGHTEN ALIGN BULKHEAD & WHEELHOUSE EXTENSION | 1 | 1400.00 | | 1400.00 | 98.00 | 1498.00 |
| BP04R | SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P) | 1 | 2000.00 | | 2000.00 | 140.00 | 2140.00 |
| | | | Sum Labor | | 3630.00 | 254.10 | 3,884.10 |

Printed on 13/2/2020 6:36:34 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SMH644X
Chassis No : JHMGK3850KS200156
Model : JAZZ 1.3LXR CVT 19YM (EURO 6)
Owner's Name : ELIJAH-JAMES KE RUSHAN
Ins Policy No. :
Date of Accident : 12/2/2020

Document No. : SQT20000721 **Page** 2
Date : 13. Feb 2020
Customer No. : WZF002
Svc Advisor : YOU PO SOON
Engine No : L13B14100040
Date | Time : 13. Feb 2020 10:51:02 AM
Surveyor Name :
Survey Date :
Authorisation Date :

| Item | Description | Qty | Unit Price | Disc % | Amount | 0% GST Amount | Amount incld GST | |
|-------------|--|-----|------------|--------|---------------------------------|---------------|------------------|-----------------|
| Survey By | <u>marcus hm</u> | | | | | | | |
| Date & Time | <u>26/2/20</u> | | | | | | | |
| Excess | | | | | | | | |
| Status | <u>not fault</u> | | | | | | | |
| Signature | <u>the job before painting 4 days.</u> | | | | | | | |
| | | | | | Total Amount | 5,040.58 | 352.84 | 5,393.42 |
| | | | | | Total (Inclusive of GST) | | | 5,393.42 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Printed on 13/2/2020 6:36:34 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.