

Attn: Adrian

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 67484422 / 67454422 Fax : 6747- 6720 REG NO 200501102H

AIG ASIA PACIFIC INSURANCE PTE LTD

Charts Building
78 Shenton Way #07-16
Singapore 079120
Tel : 6419 - 3000
Fax 6835 - 7416

Khaachan

Quotation
DATE : 18.02.2020
VEH NO : SDQ3826C
MODEL : Nissan Sunny
D O A : 14.02 2020
YR REF : SMJ2231E

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SDQ3826C (NISSAN SUNNY)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>Distorted</i>	1	433.50 ✓
2	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
3	Rear Bumper Side Holder - LH & RH <i>new</i>	2	70.40 ✓
4	Rear Bumper Sponge <i>new</i>	1	133.80 ✓
5	Rear Bumper Side Bracket - LH & RH <i>LH Distorted</i>	2	183.40 91.70 ✓
6	Rear Bumper Chrome Moulding <i>new</i>	1	168.60 ✓
7	Rear End Panel <i>Distorted</i>	1	376.20 ✓
8	Rear End Panel Top Garnish <i>Reform</i>	1	69.60 ✓
9	Rear End Panel Inner Trim <i>torn</i>	1	131.10 ✓
10	Tail Lamp - LH & RH <i>LH smashed, RH cut</i>	2	526.40 ✓
11	Tail Lamp Panel - LH <i>Distorted</i>	1	171.40 ✓
12	Tail Lamp Lower Bracket - LH <i>smashed</i>	1	38.20 ✓
13	Bootlid <i>Buckled</i>	1	655.00 ✓
14	Bootlid Lock <i>and</i>	1	43.30 ✓
15	Bootlid Weatherstripe <i>cut</i>	1	29.90 ✓
16	Bootlid Hinge <i>new</i>	2	153.20 +
17	Bootlid Lower Chrome Moulding <i>new</i>	1	173.80 +
18	Rear Fender - LH <i>Distorted</i>	1	894.80 ✓
19	Rear Fender Inner Trim Board - LH <i>crushed</i>	1	212.40 ✓
20	Rear Fender Inner Trim Board Clips - LH <i>new</i>	1 set	30.00 ✓
21	Rear Fender Inner Shield - LH <i>crushed</i>	1	51.20 +
22	Rear Fender Inner Shield Clips - LH	1 set	10.00 +
23	Rear Fender Wheel House Panel - LH <i>crushed</i>	1	599.10 +
24	Rear Fender Air Vent - LH <i>new</i>	1	54.40 +
25	Spare Tyre Panel <i>crushed</i>	1	771.40 +
26	Spare Tyre Panel Top Cover <i>torn</i>	1	197.80 ✓
27	Rear Chassis Member - LH crushed DM	1	258.90 ✓
28	Rear Windscreen Moulding <i>new</i>	1	130.90 ✓

RE: ESTIMATE FOR ACCIDENT REPAIR SDQ3826C (NISSAN SUNNY)

29	Rear Door - LH	1	960.10	X
30	Rear Door Lock - LH	1	158.80	X
31	Nissan Logo	1	33.20	✓
32	Sunny Emblem	1	56.20	✓
33	Ex Saloon Emblem	1	57.10	✓
34	CVTC Emblem	1	49.40	✓
35	E-throttle Emblem	1	46.50	✓
			<hr/>	
			7,960.00	
			(1,592.00)	
			<hr/>	
			\$ 6,368.00	

4936.10
4442.49

S/NETT ITEMS

1	Reverse Sensor	1	\$ 280.00	200
2	Spare Tyre Panel Insulator Pad	1	\$ 280.00	200
3	Rear Windscreen Sealant	1	\$ 60.00	✓
			<hr/>	
			\$ 620.00	
			<hr/>	
			\$ 6,988.00	

Total Parts

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$ 2,200.00	1500
2	To putty & spray up paint works	\$ 1,800.00	1200
3	To check wiring	\$ 100.00	30
4	To remove reverse sensor	\$ 100.00	50
5	To remove upholstery and rear seat	\$ 380.00	100
6	To remove fuel tank	\$ 150.00	80
7	To remove rear windscreen	\$ 180.00	120
		<hr/>	
		\$ 4,910.00	
		<hr/>	
		\$ 11,898.00	

3080

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is not allowed
- No illegal modification must be resurveyed and is subject to final approval from insurance

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

Acknowledged by Repairer
Signature:
Date:

Total: 7982.49
H/S: 5716 (Nett Value)
08 Days.