

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Feb 2020 Edit Reg		18 Feb 2020 00:00 Edit Adj Rpt	S\$2,050.00 Edit Estimates	S\$2,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD. , Co. Reg. No.: 199803778Z									
Main Claimant: KOH WAYNE , ID: S7700543I									
Vehicle Reg. No.: SLK8907G		Date of Loss: 16/02/2020 00:00 - :59 [105 Months and 13 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 4412012098SG		Policy/Cover Note No.: 0999993925 (Comprehensive)							
Vehicle Reg. No. (Insured): SLC565D		Policy No. (Claimant):							
		Excess:							
Repairer: COMPLETE VMS PTE LTD (HQ) 176 Sin Ming Drive #03-14 Sin Ming Autocare Complex, 575721 Sin Ming - Tel: 6455 0012									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 27/02/2020]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG_EXPRESS (03/06/2020): Alert - Adj Mandate Approved (S\$2560.95) - SLK8907G - Claim Handler: MdNoor, Nor... - AIG_SG (19/02/2020): Request to upload TP GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLK8907G (4412012098SG)
[SLC565D]**

TP

KOH WAYNE

Feb 16 2020 12:00AM

**[DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD]
COMPLETE VMS PTE LTD**

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼	
Letters/Correspondences				
			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	1	Edit
Photos/Images				
			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	14/05/20 17:30	General View	1	Load JPG ☒
2	14/05/20 17:30	General View	1	Load JPG ☒
3	14/05/20 17:30	General View	1	Load JPG ☒
4	14/05/20 17:30	General View	1	Load JPG ☒
5	14/05/20 17:30	General View	1	Load JPG ☒
6	14/05/20 17:30	General View	1	Load JPG ☒
7	14/05/20 17:30	General View	1	Load JPG ☒
8	14/05/20 17:30	General View	1	Load JPG ☒
9	14/05/20 17:30	General View	1	Load JPG ☒
10	14/05/20 17:33	Reinspection Photo	1	Load JPG ☒
11	14/05/20 17:33	Reinspection Photo	1	Load JPG ☒
12	14/05/20 17:33	Reinspection Photo	1	Load JPG ☒
13	14/05/20 17:33	Reinspection Photo	1	Load JPG ☒
14	14/05/20 17:33	Reinspection Photo	1	Load JPG ☒
15	14/05/20 17:33	Reinspection Photo	1	Load JPG ☒
16	14/05/20 17:33	Reinspection Photo	1	Load JPG ☒
17	14/05/20 17:33	Reinspection Photo	1	Load JPG ☒
18	14/05/20 17:33	Reinspection Photo	1	Load JPG ☒
Documentation				
			1 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	18/02/20 15:58	ACKNOWLEDGEMENT EMAIL TO AIG DD18022020	1	Load PDF
2	18/02/20 15:58	EMAIL FROM AIG DD18022020	1	Load PDF
3	19/02/20 15:43	TP ESTIMATE-MARKED	1	Load PDF
4	19/02/20 15:43	TP GIA REPORT	1	Load PDF
5	14/05/20 10:01	LETTER TO OI	1	Load PDF
6	14/05/20 17:35	LOD	1	Load PDF
7	14/05/20 17:35	LTA SEARCH FEE	1	Load PDF
8	22/06/20 12:55	Authorisation to Act	1	Load PDF
9	22/06/20 12:55	Release Voucher	1	Load PDF
10	22/06/20 12:55	WORKSHOP INVOICE	1	Load PDF
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail Print
1	19/02/20 13:58	OI GIA REPORT	1	Load PDF

Documents Checklist

DOCUMENTS CHECKLIST			Reset Save Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLC565D (Insd veh)	Model:	TOYOTA PRADO 2.7 (A)
	SLK8907G (TP veh)		
Date of Accident:	16/02/2020		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:\$	9,341.07	
Final Repair Cost	:\$	2,193.50	
Loss of Use	:\$	300.00	3.00 days at \$100.00 per day
Rental (if any)	:\$		days
LTA / GIA Search Fee	:\$	7.45	
Others:	:\$		
	:\$		
Final Settlement Sum	:\$	2,500.95	
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	COMPLETE VMS PTE LTD	:\$	2,500.95
2)		:\$	
3)		:\$	

NUR SHAQILAH BTE ABDOL WAHAB

22 Jun
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20002777/KDS3S2**Date:** 22/06/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993925
Claimant Vehicle No :	SLK8907G	Insured Vehicle No :	SLC565D
Date of Loss:	16/02/2020	Nature of Claim:	TP
		Claim No:	4412012098SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLK8907G	Engine No:	2TR0841144
Make & Model:	TOYOTA PRADO, 2.7 (A)	Chassis No:	TRJ1500002880
Reg. Date:	03/05/2011 (Man. Year: 2009)	Odometer:	154262 km
Colour:	Metallic Black		
Engine Capacity:	2693 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	275/60 R18	Rear Tyre Size:	275/60 R18
Front Left Side:	Falken 6 mm	Rear Left Side:	Michelin 4 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Michelin 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,099.97	2,134.25	3,965.72	65.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,630.00	500.00	2,130.00	80.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,729.97	2,634.25	6,095.72	69.83
Approved Total (Overridden) (S\$)		2,050.00		
(S\$)	8,729.97	2,050.00	6,679.97	76.52
+ GST 7.00/7.00% (S\$)	611.10	143.50	467.60	76.52
Nett Amount (S\$)	9,341.07	2,193.50	7,147.57	76.52
+ Loss of Use (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,500.95		

INSPECTION

Date of Assignment:	18/02/2020	COMPLETE VMS PTE LTD (HQ)
Date Inspected:	18/02/2020 Inspected At:	176 Sin Ming Drive #03-14 Sin Ming Autocare Complex
Estimated Period of Repair:	2.0 days	Singapore 575721

Adjuster: KENNETH KONG**Manager:** CHAN JIA LE

6/22/2020

Adjuster Report

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Cracked	1,625.00 FL	*1,625.00 FL
2	1		*REAR BUMPER TOP GARNISH	Dented	650.00 FL	*650.00 FL
3	2		*REAR BUMPER REFLECTOR	Serviceable	288.00 FL	*- FL
4	2		*REAR BUMPER REFLECTOR CHROME GARNISH	Serviceable	618.80 FL	*- FL
5	6		*REAR BUMPER CLIP	Necessary	21.00 FL	*21.00 FL
6	1		*REAR BUMPER BEAM	Repair	522.00 FL	*- FL
7	2		*REAR BUMPER BRACKET	Repair	422.00 FL	*- FL
8	1		*REAR BUMPER SPONGE	Cracked	283.00 FL	*283.00 FL
9	1		*TAIL GATE	Repair	2,384.30 FL	*- FL
10	1		*TAIL GATE LOCK	Repair	453.20 FL	*- FL
11	1		*TAIL GATE WINDSCREEN GLASS MOULDING	Serviceable	231.00 FL	*- FL
12	1		*TOYOTA LOGO ON GRILLE	Not Necessary	105.00 FL	*- FL
13	1		*TX EMBLEM	Not Necessary	70.00 FL	*- FL
14	1		*TAIL GATE W/SCREEN GLASS SEALANT	Not Necessary	65.00 FS	*- FS
15	1		*REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	8,018.30	2,779.00
- List Item Discount on L Items 25.00/25.00% (\$)	1,918.33	644.75
Total Parts (\$)	6,099.97	2,134.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REINSTALL TAIL GATE W/SCREEN GLASS.	New	180.00	0.00
2	TRANSFER TAILGATE COMPONENT TO NEW GATE.	New	150.00	0.00
3	RUST PROOFING TREATMENT.	New	100.00	0.00
4	SPRAY PAINT DAMAGED AREA AFFECTED.	New	1,100.00	250.00
5	TO KNOCK AND STRAIGHTEN REAR END PANEL, REAR CHASSIS FRAMES, AND CHANGE ALL NECESSARY PARTS.	New	1,100.00	250.00
Gross Labour Cost (\$\$)			2,630.00	500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >