

Not Withstand
11 Rep & ?
Resurvey After Painting
2 days

Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

KOH WAYNE
57 MIMOSA VIEW
SINGAPORE 805637

Attention : THE OWNER
Contact : 97598832

Estimate : ES006936

Date : 17/02/2020
Vehicle Num. : SLK8907G
Make/Model : TOYOTA PRADO 2.7TX A-2011
Chassis/Eng# : TRJ1500002880/2TR0841144
Accident Date : 16/02/2020
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

1.	1	LIST ITEMS :		
2.	1	REAR BUMPER		
3.	2	REAR BUMPER TOP GARNISH		
4.	2	REAR BUMPER REFLECTOR		
5.	6	REAR BUMPER REFLECTOR CHROME GARNISH		
6.	1	REAR BUMPER CLIP		
7.	1	REAR BUMPER BEAM		
8.	2	REAR BUMPER BRACKET		
9.	1	REAR BUMPER SPONGE		
10.	1	TAIL GATE		
11.	1	TAIL GATE LOCK		
12.	1	TAIL GATE W/SCREEN GLASS MOULDING		
13.	1	TOYOTA LOGO ON GRILLE		
13.	1	TX EMBLEM		

<i>Net / cmf</i>	1,625.00	✓
<i>Net</i>	650.00	✓
<i>Sm</i>	144.00	288.00 X
	309.40	618.80 X
	3.50	21.00 ✓
		522.00 ?
	211.00	422.00 ?
		283.00 ?
<i>R</i>	2,384.30	X
<i>R</i>	453.20	X
<i>Sm</i>	231.00	X
<i>nn</i>	105.00	X
<i>nn</i>	70.00	X

List Total S\$:
25.00% Discount S\$:

7,673.30
1,918.33
5,754.97

SPECIAL NETT ITEMS :
1. 1 TAIL GATE W/SCREEN GLASS SEALANT

Special Nett Total S\$:

nn 65.00 X
65.00

LABOUR :
REMOVE & REINSTALL TAIL GATE W/SCREEN GLASS
TRANSFER TAILGATE COMPONENT TO NEW GATE
RUST PROOFING TREATMENT
SPRAY PAINT DAMAGED AREA AFFECTED

nn 180.00 X
nn 150.00 X
nn 100.00 X
1,100.00 *2501*

LKK Auto Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

CONTINUE / ...



Email : darren@completevms.com.sg ()
lily@completevms.com.sg ()
lihui@completevms.com.sg ()

KOH WAYNE
57 MIMOSA VIEW
SINGAPORE 805637

Attention : THE OWNER
Contact : 97598832

Estimate : ES006936

Date : 17/02/2020
Vehicle Num. : SLK8907G
Make/Model : TOYOTA PRADO 2.7TX A-2011
Chassis/Eng# : TRJ1500002880/2TR0841144
Accident Date : 16/02/2020
Claim No. :
Reference :
Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
		TO KNOCK AND STRAIGHTEN REAR END PANEL, REAR CHASSIS FRAMES, AND CHANGE ALL NECESSARY PARTS		1,100.00 ²⁵⁰
		Labour Total S\$:		2,630.00

Total S\$: 8,449.97
=====