

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

13-Feb-20

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHB 8806 J

1 pc	Front bumper	\$	531.00	XR
1 pc	Front bumper emblem	\$	44.00	XNN
1 pc	Front o/s wheel cover	\$	246.00	/SCR
1 pc	Front bumper o/s side retainer	\$	16.00	?
1 pc	Front o/s fender	\$	384.00	X R
1 pc	Front o/s fender inner shield	\$	120.00	/TN
		\$	1,341.00	
		Less 10%	\$	134.10
			\$	1,206.90

S/NETT

1 pc	Front bumper clips	\$	48.00	X A SVC
1 pc	Front o/s fender sticker	\$	30.00	/NEC
1 set	Front o/s fender inner shield clips	\$	28.00	/NEC
Sundry		\$	50.00	XNN
To check front o/s wheel alignment		\$	80.00	XNN
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc.		\$	650.00 360	
To putty and spray painting on front bumper, front o/s fender		\$	400.00 360	
To apply rustproofing on the repaired and replaced panels.		\$	120.00 50	
		\$	2,612.90	

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

NAZ LKK
14/2/2020 1730
LIS
3 DAYS
CHECK ITEM PHOTO
AFTER REPAIR PHOTO

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: