

GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2

#01-255 Singapore 569536

Tel No: (65) 6482 5168

Fax No. (65) 6482 4452

Co.reg no. 200808259H

Reference No: 130220**Date: 13.02.2020****Wong Loke Tsai****245 Balestier Road #05-01****Singapore 329929****Toyota Wish 1.8 Auto****Estimated Repair Cost for Vehicle Reg. No: SV 8838 G****REPLACEMENT OF DAMAGED PANELS / PARTS**

1 Pc. Front RH Head Lamp	X		710.00
1 Pc. Front Bumper	MC / BR		880.00 645/
2 Pcs. Front Bumper Side Retainer	/ BR	@ 158.00 60	316.00 170/
10 Pcs. Front Bumper Clips	/ MC	@ 6.00	60.00 30/
1 Pc. Front Bumper Spoiler	X ? / BR		499.00 300/
2 Pcs. RH/LH Local Spoiler	/ BR	@ 410.00 30	820.00 700/
20 Pcs. Local Spoiler Clips	/ MC	@ 5.00	100.00 40/
2 Set Local Spoiler Seal	/ MC	@ 80.00 50	160.00 100/
1 Pc. Rear Bumper	/ BR		740.50 577/
2 Pcs. Rear Bumper Retainer	/ BR	@ 158.00 70	316.00 140/
10 Pcs. Rear Bumper Clips	/ MC	@ 6.00	60.00 30/
1 Pc. Rear Bumper Spoiler	X		499.00
1 Pc. Rear LH Door	/ 00		1,280.00 1122/
1 Pc. LH Front Door Side Mirror	/ cut / jammed		391.00 /
1 Pc. Front LH Fender	/ 00		454.00 /
10 Pcs. Front LH Fender Dust Garnish Clips	X @ 6.00		60.00
1 Pc. Front LH Fender Dust Garnish	X		199.00
1 Pc. Front RH Absorber	?		398.50 /
1 Pc. Front RH Absorber Mounting	?		199.80 /
1 Pc. Front RH Absorber Plate	X		75.40
1 Pc. Front RH Absorber Bearing	X		62.30
1 Pc. Front RH Knuckle Arm	?		425.00 /
1 Pc. Front RH Knuckle Hup	X ?		310.00 241/
1 Pc. Front RH Wheel Bearing	?		210.00 /
1 Pc. Front RH Lower Arm	X X		382.00
1 Pc. Front RH Ball Joint	? X		178.00

GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2

#01-255 Singapore 569536

Tel No: (65) 6482 5168

Fax No. (65) 6482 4452

Co.reg no. 200808259H

1 Pc. Front RH Stay Linkage X	165.30
1 Pc. Steering Rack Assy. 2x (Tie rod only) - DT	1,890.00 200 ✓
1 Pc. Sport Rim ✓ cut	580.00 300 ✓
1 PC. Tyre 205 x 55 x 16 ✓ TN (50%)	290.00 145 ✓

Total (Panels / Parts): 12,710.80 (SGD)**LABOR CHARGES**

To check wiring.	120.00 30
To knocking, straightening repair & renew all accident damage affected area.	1,300.00 1000
To remove & renew tyre, sport rim & balancing.	100.00 30
To remove & refit, renew & repair all undercarriage Damage affected area.	800.00 150
To remove & renew wheel hup & bearing (Press in)	120.00 20
To check & adjust camber, castor, computer wheel Alignment.	180.00 60
To respray painting on all accident damage affected area.	1,900.00 1600
To rust proof all accident affected area.	200.00 50

Total (Labor Charges): 4,720.00 (SGD)

2940

GOH LEE HWA AUTOMOBILE PTE LTD

Block 5033 Ang Mo Kio Industrial Park 2

#01-255 Singapore 569536

Tel No: (65) 6482 5168

Fax No. (65) 6482 4452

Co.reg no. 200808259H

TOTAL COST SUMMARY

PANELS / PARTS	12,710.80
LABOR CHARGES	4,720.00
Grand Total:	<u>17,430.80 (SGD)</u>

We shall be glad if you can forward the payment at your early convenience.

Cheque should be crossed and make payable to 'GOH LEE HWA AUTOMOBILE PTE LTD'

Alfred Quah

GOH LEE HWA AUTOMOBILE PTE LTD

Steve (LKK)
8322 8813
Stevechen@lkkauto.com
17/2/20, 12:10 pm
WL ML
L/S
M L C M
11 dys

Stevechen@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: