

22/03/2021

ASS. REC. BY:

REF:

CS/8MO20002787/USF3

Special Instruction:

Surveyor: MARCUS

ASSIGNMENT (Office)

From (Person): Grace Teo

of

SMD

Date/Time: 18/2/2020

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SH 2715RInsured: SGC 959Kat Workshop m/s Abidin ServiceTel: 6713 9400of No. 17 Kaki Bukit Rd 4 #01-60

Policy No:

Claim No:

OMTD2000748/SYH

Sum Insured:

Excess:

D.O.A.

17/2/2020

Make of Veh:

(Client's Record)

19/2/2020

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS

Date/Time:

18/2

Person Contacted:

SharifahVehicle IN / OUT

Date/Time	Action/Instruction
	Tsheng (✓)
	Handler: Huang Sheng Yi
	SH 2715R - <u>NA/IN/1009853/CH4</u> <u>DOA: 3/6/2019</u>
	SGC 959K - X

ASSIGNMENT

From: _____ Date: 19/2

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SH 271SR

at Workshop m/s Abwin Service

of No. 17 Kaki Bukit Rd 4 #01-60

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

After lunch

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SH 271SR Yr Regn: 14/11/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Toyota prius taxi C.C. 1798

Colour yellow / black A/C: Insured / Std / NI / NA

Sp. Reading 592740 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKN 364 601 907 562

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kapser

Front 6 mm Rear 6 mm

R/Bal. 6 mm L/Bal. 6 mm

D.O.A. 17/2/20 D.O.I. 19/2/20

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & L.P.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

coe 13-1-2023 Sol 2yrs/1mth.

LTA 24690 part 60% 48.2

new car 140k. per year 12000 x 3 = 52200

lost car and first car is malaysia sale not apply vehicle tow out already.

submit.

Our owner withdrawn claim, vehicle has not out in for repair

RECEIVED 28 FEB 2020

Date/Time, File Pass to?

☒ : Prel. Report

08/02/20

☐ : Final Report

1) Type: SP

Date/Time, File Return to?

2) _____

Days Of Repair: 13

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee: 450

Transportation: _____

S + RS, _____

Photos _____

Others _____

TOTAL _____

Report Format: Prel.

Lump Sum / I.B.I. (\$) _____

Nivitha (LKK Auto)

From: Teo, Grace <grace.teo@sompo.com.sg>
Sent: Tuesday, 18 February 2020 10:47 AM
To: AbwinM9 - Sharifah; Hwang, Shiang Yi; 'admin-d@lkkauto.com'; 'assignments@lkkauto.com'; 'SUR'
Cc: Ye, Yong Kang Melvin
Subject: CMTD2000748/SYH - LKK/ SGC959K(NR), SH2715R, JSK396, & BEW5799 on 17/02/2020
Attachments: SAS2751310.PDF

Our Reference: CMTD2000748/SYH
Your Reference: SH2715R

Without Prejudice
EMAIL ONLY

Date: 18/02/2020

OUR Email: motorsurvey@sompo.com.sg

Attention:
M/S ABWIN SERVICE PTE LTD

Dear Sharifah,

ACCIDENT INVOLVING SGC959K & SH2715R ON 17.02.2020

We refer to your email reply of 17.02.20.

We will appoint **LKK Auto** to conduct the survey.

Hi **LKK Auto**,

Please make the arrangement to survey for **SH2715R** on a without prejudice and any admission of liability basis.

Please be informed that **Ms. Hwang Shiang Yi** is the handler of this case who can be contacted at 63295 205/ shiangyi.hwang@sompo.com.sg.

Please revert your report upon completion of survey to my colleague, **Ms. Shiang Yi**.

Thank you.

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147

Survey on 19/2/2020

For motor claims survey request, please email to motorsurvey@sompo.com.sg



A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG



¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: AbwinM9 - Sharifah <sharifah@abwinm9.com>

Sent: Monday, February 17, 2020 5:38 PM

To: Teo, Grace <grace.teo@sompo.com.sg>; Hwang, Shiang Yi <shiangyi.hwang@sompo.com.sg>

Cc: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: RE: CMTD2000748/SYH - PRI/SGC959K(NR), SH2715R, JSK396, & BEW5799 on 17/02/2020

WITHOUT PREJUDICE

Hi Grace

Please assist to appoint LKK Auto for the PRI.

Thank you.

Sharifah (Ms)

Claims Executive

DID +65 6713 9408 **M** +65 9848 2243



Abwin Service Pte Ltd

T +65 6713 9400 | **F** +65 6713 9415

No. 17 Kaki Bukit Road 4

#01-60 Bartley Biz Centre Singapore 417809



From: Teo, Grace [mailto:grace.teo@sompo.com.sg]
Sent: Monday, 17 February, 2020 5:16 PM
To: AbwinM9 - Sharifah <sharifah@abwinm9.com>; Hwang, Shiang Yi <shiangyi.hwang@sompo.com.sg>
Cc: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>
Subject: CMTD2000748/SYH - PRI/ SGC959K(NR), SH2715R, JSK396, & BEW5799 on 17/02/2020

Our Reference: CMTD2000748/SYH

Your Reference: SH2715R

Without Prejudice

EMAIL ONLY

Date: 17/02/2020

OUR Email: motorsurvey@sompo.com.sg

Attention:

M/S ABWIN SERVICE PTE LTD

Dear Sharifah,

ACCIDENT INVOLVING SGC959K & SH2715R ON 17.02.2020

We refer to your Notice of Accident dated 17/02/2020.

Please be informed that **Ms. Hwang Shiang Yi** is the handler of this case who can be contacted at 63295 205/ shiangyi.hwang@sompo.com.sg.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards
Grace Teo
Claims Division
D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | Facebook: www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: AbwinM9 - Sharifah <sharifah@abwinm9.com>

Sent: Monday, February 17, 2020 4:44 PM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Subject: PRI - Accident Involving JSK396, SH2715R, SGC959K & BEW5799 on 17/02/2020

WITHOUT PREJUDICE

Dear Sir / Mdm

We have been appointed by **MR ONG KEOK CHING**, the registered owner of vehicle no. **SH2715R** to claim damages against you (SGC959K) in connection with a road traffic accident involving JSK396, SH2715R, SGC959K & BEW5799 on 17/02/2020 at around 1000hrs along PIE TOWARDS CHANGI.

Please arrange for your surveyor to conduct the Pre-repair Inspection **soonest** at our premises (vehicle is already in our workshop):

Workshop Location:

Abwin Service Pte Ltd

No. 17 Kaki Bukit Road 4

#01-60 Bartley Biz Centre Singapore 417809

Please note that if you fail to arrange the pre-repair inspection within the next two (2) working days excluding any intervening Saturday, Sunday and/or Public Holiday, our workshop will commence the repair works without any further notice or reference to you.

Thank you.

Sharifah (Ms)

Claims Executive

DID +65 6713 9408 **M** +65 9848 2243



Abwin Service Pte Ltd

T +65 6713 9400 | **F** +65 6713 9415

No. 17 Kaki Bukit Road 4

#01-60 Bartley Biz Centre Singapore 417809



Shirley Hiew (LKK Auto)

From: AbwinM9 - Sharifah <sharifah@abwinm9.com>
Sent: Thursday, 27 February 2020 3:53 pm
To: SUR
Subject: RE: CMTD2000748/SYH - LKK/ SGC959K(NR), SH2715R, JSK396, & BEW5799 on 17/02/2020
Attachments: estimate SH2715R.pdf

WITHOUT PREJUDICE

Dear Sir / Mdm

As spoken,

Strictly on a without admission of liability, we have received instructions from our insured to withdraw the claim.

Please see attached repair estimate with the list prices indicated as requested.

Thank you.

Sharifah (Ms)
Claims Executive
DID +65 6713 9408 **M** +65 9848 2243



Abwin Service Pte Ltd
T +65 6713 9400 | **F** +65 6713 9415
No. 17 Kaki Bukit Road 4
#01-60 Bartley Biz Centre Singapore 417809



From: Hwang, Shiang Yi [mailto:shiangyi.hwang@sompo.com.sg]
Sent: Friday, 21 February, 2020 11:01 AM
To: AbwinM9 - Sharifah <sharifah@abwinm9.com>
Subject: RE: LIABILITY - RE: CMTD2000748/SYH - LKK/ SGC959K(NR), SH2715R, JSK396, & BEW5799 on 17/02/2020

Without Prejudice

Dear Sharifah,

Cause of loss: BEW5799 ->SGC959K(OI)->SH2715R(NTUC)->JSK396

Refer to the above matter, this accident involving 4 cars chain collision.
There are 2 Malaysia vehicles in the chain therefore BOLA does not apply.

Please re-direct your client's claim to the Insurer of BEW5799.

Best Regards

Hwang Shiang Yi

Claims Division

D: 6329 5205 | T: 6461 6555 | F: 6221 3147



SOMPO
INSURANCE

A Century of Trust

Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: AbwinM9 - Sharifah <sharifah@abwinm9.com>

Sent: Wednesday, 19 February, 2020 11:41 AM

To: Teo, Grace <grace.teo@sompo.com.sg>; Hwang, Shiang Yi <shiangyi.hwang@sompo.com.sg>; Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: LIABILITY - RE: CMTD2000748/SYH - LKK/ SGC959K(NR), SH2715R, JSK396, & BEW5799 on 17/02/2020

Importance: High

WITHOUT PREJUDICE

Dear Sir / Mdm

We refer to the above case.

Please advise on liability soonest.

Thank you.

Sharifah (Ms)

Claims Executive

DID +65 6713 9408 **M** +65 9848 2243

Abwin Service Pte Ltd

T +65 6713 9400 | F +65 6713 9415

No. 17 Kaki Bukit Road 4

#01-60 Bartley Biz Centre Singapore 417809



From: Teo, Grace [mailto:grace.teo@sompo.com.sg]

Sent: Tuesday, 18 February, 2020 10:47 AM

To: AbwinM9 - Sharifah <sharifah@abwinm9.com>; Hwang, Shiang Yi <shiangyi.hwang@sompo.com.sg>; 'admin-d@lkkauto.com' <admin-d@lkkauto.com>; 'assignments@lkkauto.com' <assignments@lkkauto.com>; 'SUR' <sur@lkkauto.com>

Cc: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: CMTD2000748/SYH - LKK/ SGC959K(NR), SH2715R, JSK396, & BEW5799 on 17/02/2020

Our Reference: CMTD2000748/SYH

Your Reference: SH2715R

Without Prejudice

EMAIL ONLY

Date: 18/02/2020

OUR Email: motorsurvey@sompo.com.sg

Attention:

M/S ABWIN SERVICE PTE LTD

Dear Sharifah,

ACCIDENT INVOLVING SGC959K & SH2715R ON 17.02.2020

We refer to your email reply of 17.02.20.

We will appoint **LKK Auto** to conduct the survey.

Hi **LKK Auto**,

Please make the arrangement to survey for **SH2715R** on a without prejudice and any admission of liability basis.

Please be informed that **Ms. Hwang Shiang Yi** is the handler of this case who can be contacted at 63295 205/
shiangyi.hwang@sompo.com.sg.

Please revert your report upon completion of survey to my colleague, Ms. Shiang Yi.

Thank you.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: AbwinM9 - Sharifah <sharifah@abwinm9.com>

Sent: Monday, February 17, 2020 5:38 PM

To: Teo, Grace <grace.teo@sompo.com.sg>; Hwang, Shiang Yi <shiangyi.hwang@sompo.com.sg>

Cc: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: RE: CMTD2000748/SYH - PRI/ SGC959K(NR), SH2715R, JSK396, & BEW5799 on 17/02/2020

WITHOUT PREJUDICE

Hi Grace

Please assist to appoint LKK Auto for the PRI.

Thank you.

Sharifah (Ms)

Claims Executive

DID +65 6713 9408 M +65 9848 2243



Abwin Service Pte Ltd

T +65 6713 9400 | F +65 6713 9415

No. 17 Kaki Bukit Road 4

#01-60 Bartley Biz Centre Singapore 417809



From: Teo, Grace [<mailto:grace.teo@sompo.com.sg>]

Sent: Monday, 17 February, 2020 5:16 PM

To: AbwinM9 - Sharifah <sharifah@abwinm9.com>; Hwang, Shiang Yi <shiangyi.hwang@sompo.com.sg>

Cc: Ye, Yong Kang Melvin <melvin.ye@sompo.com.sg>

Subject: CMTD2000748/SYH - PRI/ SGC959K(NR), SH2715R, JSK396, & BEW5799 on 17/02/2020

Our Reference: CMTD2000748/SYH

Your Reference: SH2715R

Without Prejudice

EMAIL ONLY

Date: 17/02/2020

OUR Email: motorsurvey@sompo.com.sg

Attention:

M/S ABWIN SERVICE PTE LTD

Dear Sharifah,

ACCIDENT INVOLVING SGC959K & SH2715R ON 17.02.2020

We refer to your Notice of Accident dated 17/02/2020.

Please be informed that **Ms. Hwang Shiang Yi** is the handler of this case who can be contacted at 63295 205/
shiangyi.hwang@sompo.com.sg.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Pre-Repair Survey

	Motor Surveyor	Surveyor	Selection (Indicate as tick)
1	Raleigh Services	Andrew Ow Yong	
		Vincent Ng	
2	LKK Auto Consultants	Kenneth Kong (North area)	
		Marcus Chua (East area)	
		Mohd Rasul (West area)	
		Mohd Taufikh (West area)	
3	Priority Services	Jimmy Lee	
		Lawrence Ng	
		Jeffrey Ong	

Please let us know within **two (2) working days** whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select up to two of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Best Regards

Grace Teo

Claims Division

D: 6329 5170 | T: 6461 6555 | F: 6221 3147

For motor claims survey request, please email to motorsurvey@sompo.com.sg



Sompo Insurance Singapore Pte. Ltd.

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Quick & Easy Claims Submission¹ & Product Purchase² via Sompo SG

Download now @  or 

¹ For Travel, Personal Accident & Home Insurance | ² For Travel, Personal Accident, Home & Private Motor Insurance

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy

From: AbwinM9 - Sharifah <sharifah@abwinm9.com>

Sent: Monday, February 17, 2020 4:44 PM

To: Claims - Motor Survey <MotorSurvey@sompo.com.sg>

Subject: PRI - Accident Involving JSK396, SH2715R, SGC959K & BEW5799 on 17/02/2020

WITHOUT PREJUDICE

Dear Sir / Mdm

We have been appointed by **MR ONG KEOK CHING**, the registered owner of vehicle no. **SH2715R** to claim damages against you (SGC959K) in connection with a road traffic accident involving JSK396, SH2715R, SGC959K & BEW5799 on 17/02/2020 at around 1000hrs along PIE TOWARDS CHANGI.

Please arrange for your surveyor to conduct the Pre-repair Inspection **soonest** at our premises (vehicle is already in our workshop):

Workshop Location:

Abwin Service Pte Ltd

No. 17 Kaki Bukit Road 4

#01-60 Bartley Biz Centre Singapore 417809

Please note that if you fail to arrange the pre-repair inspection within the next two (2) working days excluding any intervening Saturday, Sunday and/or Public Holiday, our workshop will commence the repair works without any further notice or reference to you.

Thank you.

Sharifah (Ms)

Claims Executive

DID +65 6713 9408 **M** +65 9848 2243



Abwin Service Pte Ltd

T +65 6713 9400 | **F** +65 6713 9415

No. 17 Kaki Bukit Road 4

#01-60 Bartley Biz Centre Singapore 417809



Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto)
Sent: Thursday, 20 February 2020 3:22 pm
To: 'Hwang, Shiang Yi'
Cc: 'Ye, Yong Kang Melvin'; assignments; SUR; 'Teo, Grace'
Subject: RE: CMTD2000748/SYH - LKK/ SGC959K(NR), SH2715R, JSK396, & BEW5799 on 17/02/2020

Dear Shiang Yi,

Please be informed that we have inspected the vehicle SH 2715R on 19/02/2020.

We are pending estimate from repairer.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Tuesday, 18 February 2020 2:09 pm
To: 'Teo, Grace' <grace.teo@sompo.com.sg>; 'Hwang, Shiang Yi' <shiangyi.hwang@sompo.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: 'Ye, Yong Kang Melvin' <melvin.ye@sompo.com.sg>
Subject: RE: CMTD2000748/SYH - LKK/ SGC959K(NR), SH2715R, JSK396, & BEW5799 on 17/02/2020

Dear Grace,

Thank you for the assignment.

Please be informed that repairer arrange the survey on 19.02.2020.

Best Regards

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	17/02/2020 12:20
Date Of Accident	17/02/2020 10:00
Exact Location Of Accident	PIE TOWARDS CHANGI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH2715R
Insured/Policyholder	
Name Of Registered Owner	ONG KEOK CHING
NRIC No	SXXXX789J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96251213
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5069632798-05
Cover Note Number	

Driver

Name of Driver	CHUN WAH KEE
NRIC No	SXXXX430I
Date Of Birth	24/08/1959
Occupation	OUTDOOR
Date Of Driving Pass	12/01/1979
Driving Experience	41 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-82684719
Fax Number	
Contact Number	
Email Address	NOEMAIL

Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number JSK396
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number BEW5799
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name CHRISTINE TEH
Approximate Age
Injuries Sustain
Injured person in which vehicle? SH2715R
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

DETAILS OF INJURED PERSON 2

Name CHUN WAH KEE
Approximate Age
Injuries Sustain
Injured person in which vehicle? SH2715R
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO

Accident Sketch Plan

SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



SINGAPORE POLICE FORCE



T/20200217/2026

1 of 4

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

Report No. T/20200217/2026

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 17/02/2020 11:53		Vide Report No.: E/20200217/0076		Station Diary No.: 86	
Informant's Particulars					
Name of Informant: CHUN WAH KEE			Address: APT BLK 672B KLANG LANE #06-79 SINGAPORE 212672		
ID Type / ID No.: NRIC NO / S1348430I			Contact No.: Home/Office: Mobile: 82684719		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 60	Date of Birth: 24/08/1959	Type of Informant: Driver		
Race: Chinese			Language:		Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 3 Date of Expiry:		

General Information of the Accident				
Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 17/02/2020 10:00	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY TOWARDS CHANGI, 18.2KM				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: One Way		Traffic Control: Not Controlled	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
4 BEW5799	Car	PROTON	WIRA	White	Seriously Damaged	0
1 JSK396	Car	MERCEDES BENZ	180K	Blue	Slightly Damaged	2
3 SGC959K	Car	PEUGEOT		Black	Seriously Damaged	0
2 SH2715R	Car	TOYOTA	PRIUS	Black	Seriously Damaged	1



**SINGAPORE
POLICE FORCE**



T/20200217/2026

3 of 4

Report No. T/20200217/2026

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

CONTINUATION OF REPORT

and TP had attended to this accident vide E/20200217/0076. No ambulance was activated to scene.

After this accident, I asked my passenger who informed me that she was feeling giddy, and I advised her to seek medical attention afterwards. For myself, I was feeling dazed due to the high impact from the accident, and I would be seeking medical attention afterwards too.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Singapore NRIC
Owner ID:	789J

Vehicle Details

Vehicle No.:	SH2715R
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Feb 2020
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (YELLOW TOP)
Primary Colour:	Black
Secondary Colour:	Yellow
Manufacturing Year:	2014
Engine No.:	2ZRR754870
Chassis No.:	JTDKN36U601907562
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$32,920.00
Original Registration Date:	14 Jan 2015
First Registration Date:	14 Jan 2015
Transfer Count:	0
Actual ARF Paid:	\$8,088.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Jan 2023
PARF Rebate Amount:	\$5,661.00

Intended COE Rebate Details

COE Expiry Date:	13 Jan 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$52,486.00
COE Rebate Amount:	\$19,029.00
Total Rebate Amount:	\$24,690.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

Transfer of ownership or deregistration is not allowed for this vehicle.

The information contained herein is correct as at 19 Feb 2020

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 789J

Vehicle Details

Vehicle No.: SH2715R

Vehicle to be Exported: No

Intended Deregistration Date: 13 Jan 2023

Vehicle Make: TOYOTA

Vehicle Model: PRIUS TAXI (YELLOW TOP)

Primary Colour: Black

Secondary Colour: Yellow

Manufacturing Year: 2014

Engine No.: 2ZRR754870

Chassis No.: JTDKN36U601907562

Maximum Power Output: 100.0 kW (134 bhp)

Open Market Value: \$32,920.00

Original Registration Date: 14 Jan 2015

First Registration Date: 14 Jan 2015

Transfer Count: 0

Actual ARF Paid: \$8,088.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 13 Jan 2023

PARF Rebate Amount: \$4,852.00

Intended COE Rebate Details

COE Expiry Date: 13 Jan 2023

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 8

PQP Paid: \$52,486.00

COE Rebate Amount: \$0.00

Total Rebate Amount: \$4,852.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

Transfer of ownership or deregistration is not allowed for this vehicle.

The information contained herein is correct as at 19 Feb 2020

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

PREFERENTIAL RATES ON THE BMW FLEET
FROM THE SINGAPORE AIRSHOW

Register your interest



Toyota

Min Price

to

No Max

Depreciation

Vehicle Type

Category



Home » New Cars » New Car Brands » Toyota » Toyota Prius Hybrid

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Toyota Prius Hybrid

Select Another Make

Select

Overview

Pricing

Photos

Research

Reviews

Specs

Features

Similar

Accessories

Add to Shortlist

Submit a Review

Report Error

Share

Toyota Prius Hybrid Price Graph



Toyota Prius Hybrid Price History

New Car Dealer Details

Distributor Borneo Motors

Hotline 66311188 / 66311188

Pricelist 07-Feb Pricelist Select Another Date

» View all Toyota cars

Featured Merchants



Related Articles

Toyota recalls over 4,000
Prius cars in SingaporeToyota recalls one million
Prius and C-HR models

Date Updated 07-Feb-2020

Submodel Pricing Information

1.8 (A)

View Loan Breakdown

Current price	\$150,888 ▼
② Depreciation	\$13,800 /yr
② Down Payment	\$60,355 (Maximum 60% loan)
② Installment	\$1,288 /mth
COE quota premium	\$32,889 (Category B COE)
② Road tax	\$1,120 /yr
② OMV	\$31,008
② ARF	\$25,411 (after VES rebate)
② VES	\$10,000 (Rebate)
② Total basic cost	\$98,330
② Premium	53%
Previous recorded price	\$155,888
Highest recorded price	\$157,988 (past 6 mths)
Lowest recorded price	\$150,888 (past 6 mths)
» View full price history	

Date Updated 07-Feb-2020

New Car Dealer Details

Showrooms

Borneo Motors (Toyota)
33 Leng Kee Road S(159102)
Tel: 66311188
Fax: 64794562

Borneo Motors (Toyota)
17 Ubi Road 4 S(408611)
Tel: 66311188
Fax: 67411138

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
 #L1-60 BARTLEY BIZ CENTRE SINGAPORE 417809
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000277**

TO : SOMPO INSURANCE SINGAPORE PTE LTD
ATTN : MOTOR CLAIM DEPARTMENT

SH2715R
ONG KEOK CHING
 BLK 49 DORSET ROAD
 #13-118
 SINGAPORE 210049
 CONTACT NO : 96251213

DATE : 19-FEB-2020
 MAKE : TOYOTA
 MODEL : PRIUS TAXI (YELLOW TOP)
 CHASSIS NO : 2ZRR754870
 ENGINE NO : 2014
 SERVICE ADVISOR : SHARIFAH
 PAGE : 1 OF 5

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
-----	-------------	---------------------	--------------------

LIST ITEM

1	REAR BUMPER 715 /	0.00	489.20
1	REAR BUMPER SIDE RETAINER LH 111 /	0.00	102.70
1	REAR BUMPER SIDE RETAINER RH 301 /	0.00	102.70
1	REAR BUMPER LOWER GARNISH LH 215 /	0.00	289.70
1	REAR BUMPER LOWER GARNISH RH 215 /	0.00	289.70
1	REAR BUMPER LOWER GARNISH (CENTRE) 715 /	0.00	312.70
1	REAR BUMPER LOWER GARNISH SIDE RETAINER LH ?	0.00	x
1	REAR BUMPER LOWER GARNISH SIDE RETAINER RH ?	0.00	x
1	REAR BUMPER REINFORCEMENT ?	0.00	295.87
1	TAIL LAMP LH ?	0.00	601.53
1	TAIL LAMP RH ?	0.00	601.53
1	TAIL LAMP BRACKET LH 112	0.00	50.79
1	TAIL LAMP BRACKET RH 112	0.00	50.79
1	BOOT LID 100/31 /	0.00	921.70
1	BOOT LID EMBLEM 111 /	0.00	60.90
1	BOOT LID EMBLEM "PRIUS" 111 /	0.00	63.70
1	BOOT LID EMBLEM "HYBRID" 111 /	0.00	45.17
1	BOOT LID EMBLEM "TOYOTA" 111 /	0.00	59.67
1	BOOT LID RUBBER STOPPER LH 112	0.00	35.90
1	BOOT LID LOCK 111 /	0.00	411.67
1	REAR END PANEL 301/300 /	0.00	678.40
1	REAR END PANEL TOP GARNISH ?	0.00	192.70
1	REAR BUMPER TOP RUBBER ?	0.00	x
1	REAR END PANEL LOWER COVER ?	0.00	497.60
1	REAR EXTENSION PANEL ?	0.00	
1	TRUNK WEATHERSTRIP ?	0.00	392.96
1	SPARE TYRE TOP BOARD 112	0.00	715.80
1	SPARE TYRE TOOLS COMPARTMENT ?	0.00	298.50

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000277**

TO : SOMPO INSURANCE SINGAPORE PTE LTD
ATTN : MOTOR CLAIM DEPARTMENT

SH2715R
ONG KEOK CHING
 BLK 49 DORSET ROAD
 #13-118
 SINGAPORE 210049
 CONTACT NO : 96251213

DATE : 19-FEB-2020
 MAKE : TOYOTA
 MODEL : PRIUS TAXI (YELLOW TOP)
 CHASSIS NO : 2ZRR754870
 ENGINE NO : 2014
 SERVICE ADVISOR : SHARIFAH
 PAGE : 2 OF 5

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1	EXHAUST SILENCER BOX <i>SH ✓</i>	0.00	
1	EXHAUST TAIL PIPE <i>?</i>	0.00	422.67
1	EXHAUST MID PIPE <i>?</i>	0.00	3628.10
1	ALUMINIUM HEAT RESISTANCE PROTECTOR <i>?</i>	0.00	137.80
1	REAR SUSPENSION RH <i>tax?</i>	0.00	171.02
1	FRONT BUMPER <i>Dis ✓</i>	0.00	496.50
1	FRONT BUMPER EMBLEM <i>cm ✓</i>	0.00	72.60
1	FRONT BUMPER SIDE RETAINER LH <i>set ✓</i>	0.00	87.20
1	FRONT BUMPER SIDE RETAINER RH <i>set ✓</i>	0.00	87.20
1	FRONT BUMPER GRILLE <i>cm ✓</i>	0.00	323.70
1	FRONT BUMPER REINFORCEMENT <i>?</i>	0.00	377.60
1	FRONT BUMPER REINFORCEMENT BRACKET LH <i>?</i>	0.00	267.70
1	FRONT BUMPER REINFORCEMENT BRACKET RH <i>?</i>	0.00	267.70
1	TOWING COVER LH <i>tw, ✓</i>	0.00	34.70
1	TOWING COVER RH <i>tw, ✓</i>	0.00	34.70
1	FOG LAMP LH <i>?</i>	0.00	233.60
1	FOG LAMP RH <i>?</i>	0.00	233.60
1	SIGNAL LAMP LH <i>?</i>	0.00	400.79
1	SIGNAL LAMP RH <i>?</i>	0.00	400.79
1	HEAD LAMP LH <i>?</i>	0.00	962.50
1	HEAD LAMP RH <i>cm ✓</i>	0.00	962.50
1	HEAD LAMP PANEL LH <i>set ✓</i>	0.00	81.70
1	HEAD LAMP PANEL RH <i>set ✓</i>	0.00	81.70
1	FRONT GRILLE <i>cm ✓</i>	0.00	397.63
1	SUPPORT PANEL <i>set ✓</i>	0.00	1562.30
1	SUPPORT PANEL TOP COVER <i>?</i>	0.00	180.70
1	ENGINE LOWER COVER <i>?</i>	0.00	423.75
1	BONNET <i>set / meged ✓</i>	0.00	798.17
1	BONNET HINGE LH <i>set ✓</i>	0.00	65.70

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4

#01-60 BARTLEY BIZ CENTRE SINGAPORE 417809

Tel: 67139400 Fax: 67139415

Email: servicecentre@abwinm9.com Website: www.abwinm9.com

Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000277**
TO : SOMPO INSURANCE SINGAPORE PTE LTD
ATTN : MOTOR CLAIM DEPARTMENT
SH2715R**ONG KEOK CHING**

BLK 49 DORSET ROAD

#13-118

SINGAPORE 210049

CONTACT NO : 96251213

DATE	:	19-FEB-2020
MAKE	:	TOYOTA
MODEL	:	PRIUS TAXI (YELLOW TOP)
CHASSIS NO	:	2ZRR754870
ENGINE NO	:	2014
SERVICE ADVISOR	:	SHARIFAH
PAGE	:	3 OF 5

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1	BONNET HINGE RH <i>RM ✓</i>	0.00	65.70
1	BONNET WEATHERSTRIP <i>RM ✓</i>	0.00	
1	BONNET LOCK <i>RM ✓</i>	0.00	156.79
1	BONNET LOCK CATCH <i>RM X</i>	0.00	125.90
1	BONNET STAND <i>RM X</i>	0.00	72.60
1	WIPER PANEL <i>?</i>	0.00	488.95
1	WIPER SIDE GARNISH LH <i>?</i>	0.00	45.90
1	WIPER SIDE GARNISH RH <i>?</i>	0.00	45.90
1	FRONT FENDER RH <i>RM ✓</i>	0.00	511.64
1	FRONT FENDER EMBLEM RH "HYBRID" <i>RM ✓</i>	0.00	56.95
1	FRONT FENDER INNER SHIELD RH <i>?</i>	0.00	175.90
1	FRONT FENDER INNER GARNISH RH <i>?</i>	0.00	
1	FRONT FENDER TOP RUBBER RH <i>?</i>	0.00	78.76
1	FRONT FENDER TOP RUBBER LH <i>?</i>	0.00	78.76
1	WASHER TANK <i>?</i>	0.00	184.11
1	RADIATOR NO. 1 <i>?</i>	0.00	1811.97
1	RADIATOR NO. 2 <i>?</i>	0.00	695.95
1	RADIATOR FAN BLADE <i>?</i>	0.00	185.70
1	RADIATOR FAN MOTOR <i>?</i>	0.00	511.30
1	RADIATOR FAN COWLING <i>?</i>	0.00	292.40
1	RADIATOR TOP COVER <i>?</i>	0.00	133.70
1	AIR CON CONDENSER <i>?</i>	0.00	1337.80
1	AIR CON CONDENSER FAN MOTOR <i>?</i>	0.00	497.30
1	AIR CON CONDENSER FAN BLADE <i>?</i>	0.00	197.63
1	FRONT DOOR RH <i>RM X</i>	0.00	1331.70
2	FRONT DOOR HINGE RH <i>RM X</i>	0.00	78.34
1	FRONT DOOR CHECKER RH <i>RM X</i>	0.00	135.70
1	BATTERY (HYBRID) <i>?</i>	0.00	
1	REAR WINDSCREEN MOULDING <i>RM ✓</i>	0.00	

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000277**

TO : SOMPO INSURANCE SINGAPORE PTE LTD
ATTN : MOTOR CLAIM DEPARTMENT

SH2715R
ONG KEOK CHING
 BLK 49 DORSET ROAD
 #13-118
 SINGAPORE 210049
 CONTACT NO : 96251213

DATE : 19-FEB-2020
 MAKE : TOYOTA
 MODEL : PRIUS TAXI (YELLOW TOP)
 CHASSIS NO : 2ZRR754870
 ENGINE NO : 2014
 SERVICE ADVISOR : SHARIFAH
 PAGE : 4 OF 5

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
	Sub Total	0.00	0.00

SPECIAL NETT

10	REAR BUMPER CLIPS <i>nee ✓</i>	50.00	
10	REAR END PANEL TOP GARNISH CLIPS <i>11 X</i>	50.00	
1	REAR NUMBER PLATE W/CASING <i>11 X</i>	60.00	
1	REVERSE SENSOR <i>shut 200</i>	380.00	
1	REAR WINDSCREEN SEALANT <i>nee 40</i>	50.00	
10	FRONT BUMPER CLIPS <i>nee ✓ 11</i>	50.00	✓
10	FRONT FENDER INNER SHIELD RH CLIPS	50.00	X
1	FRONT NUMBER PLATE W/CASING <i>34</i>	60.00	40
1	COOLANT <i>nee</i>	50.00	✓
1	TOWING FEE	240.00	?
	Sub Total	1,040.00	0.00

LABOUR

1	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS	2,200.00	1600
1	TO SPRAY PAINT ON AFFECTED AREAS	2,000.00	1500
1	TO CHECK WIRING	150.00	30
1	TO APPLY UNDERCOATING FOR RUST PROOFING	150.00	120
1	TO DISMANTLE AND REPLACE REAR WINDSCREEN COMPONENTS	150.00	120

ABWIN SERVICE PTE LTD

17 KAKI BUKIT ROAD 4
 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809
 Tel: 67139400 Fax: 67139415
 Email: servicecentre@abwinm9.com Website: www.abwinm9.com
 Company Reg. No: 201318685G GST Reg. No: 201318685G

**ESTIMATED COST: HQQ000277**

TO : SOMPO INSURANCE SINGAPORE PTE LTD
ATTN : MOTOR CLAIM DEPARTMENT

SH2715R
ONG KEOK CHING
 BLK 49 DORSET ROAD
 #13-118
 SINGAPORE 210049
 CONTACT NO : 96251213

DATE : 19-FEB-2020
 MAKE : TOYOTA
 MODEL : PRIUS TAXI (YELLOW TOP)
 CHASSIS NO : 2ZRR754870
 ENGINE NO : 2014
 SERVICE ADVISOR : SHARIFAH
 PAGE : 5 OF 5

QTY	DESCRIPTION	REPAIR AMOUNT (SGD)	SURVEYOR APP (SGD)
1	TO DISMANTLE, REPLACE AND/OR REPAIR AIR-CON CONDENSER & REFILL AIR-CON GAS	120.00	100
1	TO DISMANTLE, REPLACE AND/OR REPAIR REVERSE SENSOR & TESTING	180.00	50
1	TO DISMANTLE & REFIX INTERIOR UPHOLSTERY	180.00	80
1	TO DISMANTLE, REPLACE AND/OR REPAIR BOOT LID COMPONENTS	250.00	60
Sub Total		5,380.00	0.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

not *Actual*
1/65
13 days.
19/2/20
Whisper Agency.

SUB-TOTAL	6,420.00	28962.64	0.00
GST - 7 %	449.40		0.00
TOTAL	6,869.40		0.00

ABWIN SERVICE PTE LTD

28958.84

Prepared By

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20002787/Usf3s2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 28-02-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGC 959K	Veh. Inspected	SH 2715R
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2000748/SYH	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	18/02/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS TAXI (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JTDKN36U601907562	Colour	YELLOW / BLACK
Odometer	592740	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R15	KAPSEN	6 mm
L/H Front Tyre	195/55 R15	KAPSEN	6 mm
R/H Rear Tyre	195/55 R15	KAPSEN	6 mm
L/H Rear Tyre	195/55 R15	KAPSEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	17/02/2020	Inspection Date	19/02/2020
Survey held at	ABWIN SERVICE PTE LTD 17 KAKI BUKIT ROAD 4 #01-60 BARTLEY BIZ CENTRE SINGAPORE 417809		

5a. Remarks

A)THE VEHICLE HAS NOT SEND IN FOR REPAIR. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	13 Working Days
-------------------------------------	------------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SH 2715R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	DISTORTED	489.20	489.20
1	REAR BUMPER SIDE RETAINER LH	BENT	102.70	102.70
1	REAR BUMPER SIDE RETAINER RH	BENT	102.70	102.70
1	REAR BUMPER LOWER GARNISH LH	* CHECK	289.70	-
1	REAR BUMPER LOWER GARNISH RH	* CHECK	289.70	-
1	REAR BUMPER LOWER GARNISH (CENTRE)	DISTORTED	312.70	312.70
1	REAR BUMPER LOWER GARNISH SIDE RETAINER LH (NPA)	* CHECK	-	-
1	REAR BUMPER LOWER GARNISH SIDE RETAINER RH (NPA)	* CHECK	-	-
1	REAR BUMPER REINFORCEMENT	* CHECK	295.87	-
1	TAIL LAMP LH	* CHECK	601.53	-
1	TAIL LAMP RH	* CHECK	601.53	-
1	TAIL LAMP BRACKET LH	NOT NECESSARY	50.79	-
1	TAIL LAMP BRACKET RH	NOT NECESSARY	50.79	-
1	BOOT LID	DENTED / BENT	921.70	921.70
1	BOOT LID EMBLEM	NECESSARY	60.90	60.90
1	BOOT LID EMBLEM "PRIUS"	NECESSARY	63.70	63.70
1	BOOT LID EMBLEM "HYBRID"	NECESSARY	45.17	45.17
1	BOOT LID EMBLEM "TOYOTA"	NECESSARY	59.67	59.67
1	BOOT LID RUBBER STOPPER LH	NOT NECESSARY	35.90	-
1	BOOT LID LOCK	TWISTED	411.67	411.67
1	REAR END PANEL	BADLY DENTED	678.40	678.40
1	REAR END PANEL TOP GARNISH	* CHECK	192.70	-
1	REAR BUMPER TOP RUBBER (NPA)	* CHECK	-	-
1	REAR END PANEL LOWER COVER	* CHECK	497.60	-
1	REAR EXTENSION PANEL (NPA)	* CHECK	-	-
1	TRUNK WEATHERSTRIP	* CHECK	392.96	-
1	SPARE TYRE TOP BOARD	NOT NECESSARY	715.80	-
1	SPARE TYRE TOOLS COMPARTMENT	* CHECK	298.50	-
1	EXHAUST SILENCER BOX (NPA)	BENT	-	-

Report Ref No. CS/SMO20002787/Usf3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	EXHAUST TAIL PIPE	* CHECK	422.67	-
1	EXHAUST MID PIPE	* CHECK	3,628.10	-
1	ALUMINIUM HEAT PRESSURE PROTECTOR	* CHECK	137.80	-
1	REAR SUSPENSION RH	* CHECK	171.02	-
1	FRONT BUMPER	DISTORTED	496.50	496.50
1	FRONT BUMPER EMBLEM	CRACKED	72.60	72.60
1	FRONT BUMPER SIDE RETAINER LH	BENT	87.20	87.20
1	FRONT BUMPER SIDE RETAINER RH	BENT	87.20	87.20
1	FRONT BUMPER GRILLE	CRACKED	323.70	323.70
1	FRONT BUMPER REINFORCEMENT	* CHECK	377.60	-
1	FRONT BUMPER REINFORCEMENT BRACKET LH	* CHECK	267.70	-
1	FRONT BUMPER REINFORCEMENT BRACKET RH	* CHECK	267.70	-
1	TOWING COVER LH	TWISTED	34.70	34.70
1	TOWING COVER RH	TWISTED	34.70	34.70
1	FOG LAMP LH	* CHECK	233.60	-
1	FOG LAMP RH	* CHECK	233.60	-
1	SIGNAL LAMP LH	* CHECK	400.79	-
1	SIGNAL LAMP RH	* CHECK	400.79	-
1	HEAD LAMP LH	* CHECK	962.50	-
1	HEAD LAMP RH	CRACKED	962.50	962.50
1	HEAD LAMP PANEL LH	BENT	81.70	81.70
1	HEAD LAMP PANEL RH	BENT	81.70	81.70
1	FRONT GRILLE	CRACKED	397.63	397.63
1	SUPPORT PANEL	BENT	1,562.30	1,562.30
1	SUPPORT PANEL TOP COVER	* CHECK	180.70	-
1	ENGINE LOWER COVER	* CHECK	423.75	-
1	BONNET	BENT / WARPED	798.17	798.17
1	BONNET HINGE LH	BENT	65.70	65.70
1	BONNET HINGE RH	BENT	65.70	65.70
1	BONNET WEATHERSTRIP (NPA)	NECESSARY	-	-
1	BONNET LOCK	TWISTED	156.79	156.79
1	BONNET LOCK CATCH	NOT NECESSARY	125.90	-
1	BONNET STAND	NOT NECESSARY	72.60	-

Report Ref No. CS/SMO20002787/Usf3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WIPER PANEL	* CHECK	488.95	-
1	WIPER SIDE GARNISH LH	* CHECK	45.90	-
1	WIPER SIDE GARNISH RH	* CHECK	45.90	-
1	FRONT FENDER RH	BUCKLED	511.64	511.64
1	FRONT FENDER EMBLEM RH "HYBRID"	NECESSARY	56.95	56.95
1	FRONT FENDER INNER SHIELD RH	* CHECK	175.90	-
1	FRONT FENDER INNER GARNISH RH (NPA)	* CHECK	-	-
1	FRONT FENDER TOP RUBBER RH	* CHECK	78.76	-
1	FRONT FENDER TOP RUBBER LH	* CHECK	78.76	-
1	WASHER TANK	* CHECK	184.11	-
1	RADIATOR NO.1	* CHECK	1,811.97	-
1	RADIATOR NO.2	* CHECK	695.95	-
1	RADIATOR FAN BLADE	* CHECK	185.70	-
1	RADIATOR FAN MOTOR	* CHECK	511.30	-
1	RADIATOR FAN COWLING	* CHECK	292.40	-
1	RADIATOR TOP COVER	* CHECK	133.70	-
1	AIR CON CONDENSER	* CHECK	1,337.80	-
1	AIR CON CONDENSER FAN MOTOR	* CHECK	497.30	-
1	AIR CON CONDENSER FAN BLADE	* CHECK	197.63	-
1	FRONT DOOR RH	TO REPAIR SEE LABOUR	1,331.70	-
2	FRONT DOOR HINGE RH	NOT NECESSARY	78.34	-
1	FRONT DOOR CHECKER RH	NOT NECESSARY	133.70	-
1	BATTERY (HYBRID) (NPA)	* CHECK	-	-
1	REAR WINDSCREEN MOULDING (NPA)	NECESSARY	-	-
	LESS 25% DISCOUNT		-7,512.96	-2,281.48
			22,538.89	6,844.41
	<u>SPECIAL NETT ITEMS</u>			
10	REAR BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
10	REAR END PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	50.00	-
1	REAR NUMBER PLATE W/CASING (SN)	NOT NECESSARY	60.00	-
1	REVERSES SENSOR (SN)	SHORTED	380.00	200.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00

Report Ref No. CS/SMO20002787/Usf3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
10	FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	50.00
10	FRONT FENDER INNER SHIELD RH CLIPS (SN)	NOT NECESSARY	50.00	-
1	FRONT NUMBER PLATE W/CASING (SN)	BENT	60.00	40.00
1	COOLANT (SN)	NECESSARY	50.00	50.00
			800.00	430.00
	LABOUR			
	TOWING FEE.	* CHECK	240.00	-
	TO CONDUCT PANEL BEATING AND STRAIGHTEN PARTS ON DAMAGED AREAS. INCLUSIVE OF THE REPAIR OF FRONT DOOR RH.		2,200.00	1,600.00
	TO SPRAY PAINT ON AFFECTED AREAS.		2,000.00	1,500.00
	TO CHECK WIRING.		150.00	30.00
	TO APPLY UNDERCOATING FOR RUST PROOFING.		150.00	120.00
	TO DISMANTLE AND REPLACE REAR WINDSCREEN COMPONENTS.		150.00	120.00
	TO DISMANTLE, REPLACE AND/OR REPAIR AIR-CON CONDENSER & REFILL AIR-CON GAS.		120.00	100.00
	TO DISMANTLE, REPLACE AND/OR REPAIR REVERSE SENSOR & TESTING.		180.00	50.00
	TO DISMANTLE & REFIX INTERIOR UPHOLSTERY.		180.00	80.00
	TO DISMANTLE, REPLACE AND/OR REPAIR BOOT LID COMPONENTS.		250.00	60.00
			5,620.00	3,660.00
GRAND TOTAL			28,958.89	10,934.41
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$13987.83 NETT)				10,934.41

Report Ref No. CS/SMO20002787/Usf3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.