BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE:	11-Feb-20
J/ (L.	11-1 00-20

INSURANCE:

MODEL: TOYOTA PRIUS

VEHICLE NO.: SH9248B

DESCRIPTION	QTY	LIST PRICE	AMOUNT
REAR TRUNK LID COVER / (M	1	\$1,126.60	\$1,126.60
REAR TRUNK LID LOCK / IJT	1	\$457.90	\$457.90
REAR TRUNK LID COVER TRIM BOARD	1	\$216.50	\$216.50
REAR TRUNK LID RUBBER / CRY	1	\$365.20	\$365.20
REAR TRUNK LID GLASS (BLACK COLOR) X	1	\$1,569.70	\$1,569.70
BOARD ASSY, BACK DOOR TRIM	1	\$254.40	\$254.40
GARNISH SUB-ASSY, BACK DOOR, OUTSIDE / JR	1	\$889.70	\$889.70
REAR TRUNK LID LOGO (PRIUS) / /	1	\$60.80	\$60.80
REAR TRUNK LID LOGO (HYBRID)	1	\$52.40	\$52.40
REAR TRUNK LID LOGO (TOYOTA STAR) / 11	1	\$52.90	\$52.90
REAR BUMPER / //R	1	\$458.60	\$458.60
REAR BUMPER RE-INFORCEMENT / (1)	1	\$318.80	\$318.80
REAR BUMPER UNDER COVER (MIK) / (V)	1	\$552.60	\$552.60
REAR BUMPER SIDE RETAINER / RR	1	\$112.70	\$112.70
REAR BUMPER UNDER SIDE COVER (RH) / MIS	1	\$232.00	\$232.00
REAR BUMPER UNDER SIDE CENTRE COVER ?	1	\$552.60	\$552.60
REAR BUMPER TOWING COVER / MIS	1	\$82.70	\$82.70
REAR BUMPER CLIPS / 1/4	1	\$22.00	\$22.00
REAR BUMPER SIDE CLIP / NC	1	\$25.00	\$25.00
ARM SUB-ASSY, REAR BUMPER, RH / () ()	1	\$139.60	\$139.60
ARM SUB-ASSY, REAR BUMPER, LH	1	\$139.60	\$139.60
RETAINER, REAR BUMPER, UPPER SIDE X	1	\$30.70	\$30.70
RETAINER, REAR BUMPER, SIDE, RH / JR	1	\$94.80	\$94.80
SEAL, REAR BUMPER SIDE, RH ×	1	\$148.40	\$148.40
SEAL, REAR BUMPER SIDE, LH	1	\$148.40	\$148.40
TAIL LAMP ASSY (UPPER) / IR	2	\$557.90	\$1,115.80
TAIL LAMP ASSY (LOWER)	2	\$548.40	\$1,096.80
TAIL LAMP QUARTER PANEL X	2	\$216.00	\$432.00
TAIL LAMP SIDE COVER ♥	2		
AMP ASSY, SIDE TURN SIGNAL, RH	1	\$256.00	\$512.00
AMP ASSY, SIDE TURN SIGNAL, L H	1	\$65.30	\$65.30
REAR END PANEL	1	\$65.30	\$65.30
REAR END PANEL GARNISH / CRV	1	\$602.10	\$602.10
REAR SPARE TYRE PANEL X	1	\$161.80	\$161.80
REAR SPARE TYRE CUSHION (FLR BOARD CENTRE)	1	\$667.70	\$667.70
REAR FIBER TOOL BOX TRIM	1	\$101.40	\$101.40
REAR EXHAUST PIPE / 0//	1	\$398.00	\$398.00
REAR EXHAUST PIPE / //	1	\$1,163.40	\$1,163.40
REAR EXHAUST PIPE INSULATOR X	1	\$40.70	\$40.70
REAR FENDER, RH	1	\$314.60	\$314.60
	1	\$836.70	\$836.70
REAR FENDER SHIELD (LH/RH) / ()(1	\$134.20	\$134.20

DEAD FENDED ADVEDTISEMENT LOGO (LH/RH)		4	0100.00	\$100.00
REAR PENDER ADVERTISEMENT 2000 (2177(11)		1	\$100.00	
REAR FENDER AIR DUCT / DR		1	\$165.10	\$165.10
REAR WINDSCREEN GLASS W/ MOULDING X		1	\$1,778.30	\$1,778.30
REAR WINDSCREEN SEALANT / MC		1	\$46.00	\$46.00
REAR WIRING ASSY X		1	\$582.40	\$582.40
TAPE, BLACK OUT, NO. 1 RH		1	\$45.60	\$45.60
TAPE, BLACK OUT, NO. 2 RH		1	\$37.30	\$37.30
SPOILERSUB-ASSY, REAR X		1	\$953.70	\$953.70
SUB TOTAL				\$19,520.80
LESS 20%				\$3,904.16
DISCOUNTED TOTAL				\$15,616.64
REVERSE CAMERA X	Nett	1	\$320.00	\$320.00
REAR BUMPER REVERSE SENSOR	Nett	1	\$135.70	\$135.70
REAR BUMPER RUBBER MAT / NC	Nett	1	\$50.00	\$50.00
REAR TRUNK LID APPS STICKER / MC	Nett	1	\$40.00	\$40.00
REAR TRUNK LID COMFORT & TEL NO. STICKER / M	Nett	1	\$60.00	\$60.00
SUB TOTAL				\$605.70
Labour Charge	+++			
Panel Beating 1000		1	\$1,200.00	\$1,200.00
Spray Painting Charge 800		1	\$1,000.00	\$1,000.00
Wiring Charge 70		1	\$150.00	\$150.00
Tuff Kote 50		1	\$150.00	\$150.00
Towing Charge		1	\$50.00	\$50.00
Remove/Refix Rear Windscreen Glass		1	\$120.00	\$120.00
Remove/Refix Reverse Sensor		1	\$120.00	\$120.00
Repair Exhaust Pipe		1	\$60.00	\$60.00
TOTAL LABOUR				\$2,850.00
ESTIMATE TOTAL				\$19,072.34

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Steve (LKK) WH Print 8322 8813 17/2/29, 3-15pm L/S 8 dy My ALSM

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date: