

21/03/2002

ADM. REC. BY:

REF: CS/MSG 20002794/KVfs

Special Instruction:

SURVIVOR: Kenneth

ASSIGNMENT (Office)

From (Person): Muhammad Achik B madi of MSG Date/Time: 18.2.2020 16:19 pm

Estimated Cost: _____ Bill to: _____

OD / TP / AWS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No: SJV 7558 C Insured: SLP 78075at Workshop m/s Cheng Hoe Tel: 67556142of BIC 1019 #01-374/382 YishunPolicy No: 2911475.6 Claim No: 613369

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 30.11.2019

(Client's Record)

CA / REV / REP. / REV 24 HRS up H.O.D. Endorsement: _____Date/Time: 18/2/2020 4:43 pm Person Contacted: June Vehicle IN/OUT: OUTDate/Time Action/Instruction (☒) Estimate nable will call KennethSVJ 7558 C - 04/13/1404054 E/S/1 #12 11/12/21SLP 78075 - 82/4/20 Send preli revised via merimen14/4/20 Final fig \$ 2008.24 Confirmed by email (Ref 537.15, 21/20)

ASS. REC. BY:

REF:

MSG/

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 1-B1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Date / Time Action / Instruction

Veh No: PTV 7358C Yr Regn: 06, 19Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or A)Make: Toy Woz c.c. 1498Colour: M. Blue A/C: Insured / Std / NI / NASp. Reading: 25714 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR 2823F3401176073Gen. Cond: Good / Fair / Poor / BurntSteering: Inop / Jammed / Leaked / Burnt orBrake: Inop / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size: F: _____ R: 185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 5 mm R/Bal. 3 mmL/Bal. 5 mm L/Bal. 3 mmD.O.A. 30/11/19 D.O.I. 1/4/2020

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prel. ReportDays Of Repair: 4

1)

☐ : Final ReportResurvey No. of Trip: 1

Date/Time, File Return to?

2)

14/4 - typistAdd Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S - RS - SI

Fees:

Others:

TOTAL

Report Format:

Lump Sum / I.B.I. (\$

Merriman

2008-24

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

TP/MSIG

SJV 7558C

M/S : MSIG INSURANCE (S) PTE LTD (SGX)
16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660 FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP-MSIG

Claim Type: Third Party

Accident Date: 30/11/2019

TP Veh Reg No: SLP7807S

Estimate No: ES2090325/WS

Date: 01 Apr 2020

Policy No: 5109730104

Veh Reg No: SJV7558C.1

Make/Model: TOYOTA VIOS 1.5E A

Chassis No: MR2B23F3401176073

Engine No: 2NRX438809

Reg. Date: 12/06/2019

Estimate Repair Cost to Vehicle No :SJV7558C.1

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	452.80	1 PC	452.80	—
2 REAR BUMPER REINFORCEMENT	316.20	1 PC	316.20	—
3 REAR BUMPER CLIPS	3.50	6 PCS	21.00	—
4 REAR BOOT	659.90	1 PC	659.90	—
5 REAR BOOT LOGO	59.15	1 PC	59.15	—
6 REAR BOOT EMBLEM 'VIOS'	46.30	1 PC	46.30	—
7 REAR BOOT EMBLEM 'E'	38.50	1 PC	38.50	—
			1,593.85	
	Less 25%		398.46	1,195.39
Special Net				
8 REVERSE SENSOR	200.00	1 PC	200.00	—
			200.00	200.00
Labour				
9 TO REMOVE AND REFIX REAR BUMPER ASSY, BOOT AND ATTACHMENT REVERSE SENSOR. TO KNOCK AND REPAIR REAR PANEL AND REALIGN THE SAME	500.00	1 LA	500.00	—
10 PUTTY AND RESPRAY REAR BOOT, REAR PANEL, REAR BUMPER	600.00	1 LA	600.00	—
11 REMOVE & REFIX REVERSE CAMERA, RESET SYSTEM	50.00	1 PC	50.00	—
			1,150.00	1,150.00

Note: b4p two set photo

① with reverse sensor \$2008.24

② without reverse sensor \$1808.24

Total SS 2,545.39

Add GST @ 7% 178.18

Total Amount Payable SS 2,723.57

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications allowed
- Supplemental survey is allowed and is subject to the approval of the Insurance Company

Acknowledged by Repairer:

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE