

22/03/2002

As's. REC. BY:

REF: CS/MSG 20002794/KVf3

Special Instruction:

Surveyor: Kenneth

ASSIGNMENT (Office)

From (Person): Muhammad Achit B madi of MSG Date/Time: 18.2.2020 16.19p.m

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SJV 7558 C Insured: SLP 78075at Workshop m/s Chung Hoo Tel: 67556142of BIR 1019 #01-374/382 YishunPolicy No: 29114756 Claim No: 613369

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 30.11.2019
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 18/2/2020 4.43p.m Person Contacted: June H.O.D. Endorsement: _____Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate: Nabilo will call Kenneth
	SJV 7558 C - CC4 / AIG 170240371 E3b342 D.O.A - 12/12/2017
	SLP 78075 - X
<u>2/4/20</u>	<u>Send preli revised via merimen</u>

ASS. REC. BY:

REF:

MSG/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

1-B/

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

PTV 7558C

Yr Regn:

06, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

A)

Make:

Toy Uos

c.c

1498

Colour

M-Red

A/C:

Insured / Std / NI / NA

Sp. Reading

25714

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR 2B23F3401176073

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

3

mm

L/Bal.

5

mm

L/Bal.

3

mm

D.O.A.

30/11/19

D.O.I.

1/4/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



: Prell. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

Fees:

Others:

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Feb 2020		18 Feb 2020 16:19 Assign				New Assignment Cancel Case

[Main](#)[Reference](#)[Claim Details](#)[Documents](#)[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	GRAB RENTALS PTE.LTD., Co. Reg. No.: 201617200G		
Main Claimant:	LIM PEK GEK, ID: S0203777G		
Vehicle Reg. No.:	SJV7558C	Date of Loss:	30/11/2019 11:00 - :59 [5 Months and 18 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 613369	Policy/Cover Note No.:	29114756 (Comprehensive) Coverage: 01/02/2019 - 31/01/2020
Vehicle Reg. No. (Insured):	SLP7807S	Policy No. (Claimant):	
		Excess:	S\$2,000.00
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 19/02/2020]		
Driver/Custodian (Insured):	MOHAMAD DANIAL BIN MOHAMAD NIZAR (31 / Male) , NRIC: S8741170B, Tel: +6584841151 Email:		
Adj Asg. Remarks:	on WP, OI:Grab. Liab: clear. Agree on SJE, Assign: LKK Auto Consultants Pte Ltd. Contact: June @ 6755 6142.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 02 Apr 2020

Preliminary Advice

Insured Vehicle No	: SLP7807S	Accident Date	: 30/11/2019
TP Vehicle No	: SJV7558C	Assignment Date	: 18/02/2020
Make	: TOYOTA VIOS	Est. Duration of Repair	: 4.00
Date of Inspection	: 01/04/2020		
Inspection At	: CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,545.39
Revised Amount	:S\$	1,808.24
Check Items (Estimated)	:S\$	237.15
Total	:S\$	2,045.39

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	777G
Vehicle Details	
Vehicle No.:	SJV7558C
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5 E (AUTO)
Primary Colour:	Red
Manufacturing Year:	2019
Engine No.:	2NRX438809
Chassis No.:	MR2B23F3401176073
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$13,788.00
Original Registration Date:	12 Jun 2019
First Registration Date:	12 Jun 2019
Transfer Count:	0
Actual ARF Paid:	\$13,788.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Jun 2029
PARF Rebate Amount:	\$10,341.00
Intended COE Rebate Details	
COE Expiry Date:	11 Jun 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$33,199.00
COE Rebate Amount:	\$31,622.00
Total Rebate Amount:	\$41,963.00

The information contained herein is correct as at 02 Dec 2019

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

TP/MSIG
SJV 7558C

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP-MSIG

Claim Type: Third Party

Accident Date: 30/11/2019

TP Veh Reg No: SLP7807S

Estimate No: ES2090325/WS

Date: 01 Apr 2020

Policy No: 5109730104

Veh Reg No: SJV7558C.1

Make/Model: TOYOTA VIOS 1.5E A

Chassis No: MR2B23F3401176073

Engine No: 2NRX438809

Reg. Date: 12/06/2019

*Not authorized
Running B & Paim
4 days*

Estimate Repair Cost to Vehicle No :SJV7558C.1

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 REAR BUMPER	452.80	1 PC	452.80	—
2 REAR BUMPER REINFORCEMENT	316.20	1 PC	316.20	—
3 REAR BUMPER CLIPS	3.50	6 PCS	21.00	—
4 REAR BOOT	659.90	1 PC	659.90	—
5 REAR BOOT LOGO	59.15	1 PC	59.15	—
6 REAR BOOT EMBLEM 'VIOS'	46.30	1 PC	46.30	—
7 REAR BOOT EMBLEM 'E'	38.50	1 PC	38.50	—
			1,593.85	
	Less 25%		398.46	1,195.39
Special Net				
8 REVERSE SENSOR	200.00	1 PC	200.00	X
			200.00	200.00
Labour				
9 TO REMOVE AND REFIX REAR BUMPER ASSY, BOOT AND ATTACHMENT REVERSE SENSOR. TO KNOCK AND REPAIR REAR PANEL AND REALIGN THE SAME	500.00	1 LA	500.00	400.00
10 PUTTY AND RESPRAY REAR BOOT, REAR PANEL, REAR BUMPER	600.00	1 LA	600.00	400.00
11 REMOVE & REFIX REVERSE CAMERA, RESET SYSTEM	50.00	1 PC	50.00	✓
			1,150.00	1,150.00
			Total	SS 2,545.39
			Add GST @ 7%	178.18
			Total Amount Payable	SS 2,723.57

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary work is surveyed and is subject to final approval of the insurance Company

Acknowledged by Repairer
Signature:
Date:

For Cheng Hoe Motor Pte Ltd

[Signature]
AUTHORISED SIGNATURE