

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20002800/R1PA3Q2

**Date:** 07/10/2020

#### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> FBQ4148T	<b>Insured Vehicle No :</b>	SHD3165Y
Date of Loss: 10/12/2019	Nature of Claim: TP	Claim No: MCT19120247

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBQ4148T	Engine No:	G3H6E0014531
Make & Model:	YAMAHA NMAX155, 155cc	Chassis No:	MH3SG431000011698
Reg. Date:	26/09/2019 (Man. Year: 2019)	Odometer:	7422 km
Colour:	White		
Engine Capacity:	155 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	110/70-13	Rear Tyre Size:	130/70-13
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	839.50	772.00	67.50	8.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	480.00	310.00	170.00	35.42
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>1,319.50</b>	<b>1,082.00</b>	<b>237.50</b>	<b>18.00</b>
<b>+ Loss of Use (3.0 x S\$25.00/day) (S\$)</b>		75.00		
		<b>Nett Liability (S\$)</b>		<b>1,157.00</b>

#### INSPECTION

Date of Assignment:	18/02/2020	
Date Inspected:	18/02/2020	Inspected At: Hup Hin (HQ) Blk 1006 Bt Merah Lane 2, #01-02 Singapore 159762
Estimated Period of Repair:	3.0 days	

**Adjuster:** MOHD RASUL

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 23 Apr 2020)	
<b>Parts:</b>	N/A	YAMAHA NMAX155 155cc (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FBQ4148T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*BOTTOM FRONT SIDE COVER	Scratched	54.00 FL	*54.00 FL	
2	1		*TOP FRONT SIDE COVER	Scratched	33.00 FL	*33.00 FL	
3	1		*FRONT LEFT SIGNAL	Scratched	86.00 FL	*86.00 FL	
4	1		*FOOT REST COVER	Scratched	67.00 FL	*67.00 FL	
5	1		*YAMAHA LOGO	Necessary	17.00 FL	*17.00 FL	
6	1		*FRONT FENDER	Scratched	75.00 FL	*75.00 FL	
7	1		*AIR BOX COVER	Scratched	27.00 FL	*27.00 FL	
8	1		*MAIN STAND	Scratched	81.00 FL	*81.00 FL	
9	1		*REAR BRAKE LEVER	Scratched	41.00 FL	*41.00 FL	
10	1		*LEFT MIRROR	Scratched	38.00 FL	*38.00 FL	
11	1		*EXHAUST COVER	Not Necessary	75.00 FL	*- FL	
12	1		*FRONT COVER BRACKET	Bent	161.00 FL	*161.00 FL	
13	1		*REAR BOX	Scratched	160.00 FS	*160.00 FS	
					<b>Sub Total (\$\$)</b>	<b>915.00</b>	<b>840.00</b>
					<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	75.50	68.00
					<b>Total Parts (\$\$)</b>	<b>839.50</b>	<b>772.00</b>

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSPORT -3 WAYS	New	150.00	50.00
2	FORK ALIGNMENT	New	80.00	60.00
3	LABOUR CHARGE (REPAIR)	New	250.00	200.00
			<b>Gross Labour Cost (\$\$)</b>	<b>480.00</b>
				<b>310.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >