

Hup Hin

合興

Blk 1006 Bukit Merah Lane 2 #01-02 Singapore 159762

Tel: 6270 9810 Fax: 6272 4225

Co. Reg. 05631700W

Email: hhmotor@singnet.com.sg

18 February 2020

RE : CLAIM OF ACCIDENT MOTORCYCLE REGN NO. FBQ 4148 T

ENGINE NO.: G3H6E0014531

CHASIS NO. : MH3SG431000011698

MODEL : YAMAHA NMAX155 ABS (YEAR: 2019) (WHITE)

1 PC	BOTTOM FRONT SIDE COVER	\$	54.00
1 PC	TOP FRONT SIDE COVER	\$	33.00
1 PC	FRONT LEFT SIGNAL	\$	86.00
1 PC	FOOT REST COVER	\$	67.00
1 PC	YAMAHA LOGO	\$	17.00
1 PC	FRONT FENDER	\$	75.00
1 PC	AIR BOX COVER	\$	27.00
1 PC	MAIN STAND	\$	81.00
1 PC	REAR BRAKE LEVER	\$	41.00
1 PC	LEFT MIRROR	\$	38.00
1 PC	EXHAUST COVER	\$	75.00
1 PC	FRONT COVER BRACKET	\$	161.00

		\$	755.00
	LESS 10% SPARE PARTS	\$	(75.50)

		\$	679.50
	TRANSPORT - 3 WAYS	\$	150.00
	FORK ALIGNMENT	\$	80.00
	REAR BOX	\$	160.00
	LABOUR CHARGE (REPAIR)	\$	250.00

		\$	1,319.50
		=====	