

Hup Hin

合興

Blk 1006 Bukit Merah Lane 2 #01-02 Singapore 159762

Tel: 6270 9810 Fax: 6272 4225

Co. Reg. 05631700W

Email: hhmotor@singnet.com.sg

18 February 2020

RE : CLAIM OF ACCIDENT MOTORCYCLE REGN NO. FBQ 4148 T

ENGINE NO.: G3H6E0014531

CHASIS NO. : MH35G431000011698

MODEL : YAMAHA NMAX155 ABS (YEAR: 2019) (WHITE)

1 PC	BOTTOM FRONT SIDE COVER <i>scr</i>	\$	54.00
1 PC	TOP FRONT SIDE COVER <i>scr</i>	\$	33.00
1 PC	FRONT LEFT SIGNAL <i>scr</i>	\$	86.00
1 PC	FOOT REST COVER <i>scr</i>	\$	67.00
1 PC	YAMAHA LOGO <i>ne</i>	\$	17.00
1 PC	FRONT FENDER <i>scr</i>	\$	75.00
1 PC	AIR BOX COVER <i>scr</i>	\$	27.00
1 PC	MAIN STAND <i>scr</i>	\$	81.00
1 PC	REAR BRAKE LEVER <i>scr</i>	\$	41.00
1 PC	LEFT MIRROR <i>scr</i>	\$	38.00
1 PC	EXHAUST COVER <i>X inconsistency</i>	\$	75.00 X
1 PC	FRONT COVER BRACKET <i>bt</i>	\$	161.00

Rasul
Hp 90010068
3 days
P/P
18/02/2020
@1220
Resurvey after repair

	\$	755.00	<i>680</i>
LESS 10% SPARE PARTS	\$	(75.50)	<i>10%</i>
			<i>612</i>
	\$	679.50	
TRANSPORT - 3 WAYS	\$	150.00 <i>50</i>	<i>470</i>
FORK ALIGNMENT	\$	80.00 <i>60</i>	
REAR BOX <i>scr</i>	\$	160.00	
LABOUR CHARGE (REPAIR)	\$	250.00 <i>200</i>	

612.00
450.00

1082.00

=====

\$ 1,319.50

=====

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: