

# SLV 8595P

| Item                                         | Estimated Price | Item                                  | Estimated Price   |
|----------------------------------------------|-----------------|---------------------------------------|-------------------|
| Front Panel <i>Repair</i>                    | \$616.60        | Left Fog Lamp <i>X</i>                | \$350.65          |
| Front Re-enforcement Bar <i>bt</i> 288       | \$386.10        | Right Fog Lamp <i>X</i>               | \$350.65          |
| Front Bumper <i>de</i> 950                   | \$992.50        | Rear Panel <i>repair</i>              | \$440.80          |
| Headlight - Right <i>cm</i> 1760             | \$1,947.60      | Rear Bumper <i>de</i>                 | \$832.35          |
| Headlight - Left <i>cm</i> 1760              | \$1,947.60      | Rear Sensor <i>X</i>                  | \$220.00          |
| Condenser <i>bt</i> 770                      | \$1,872.50      | Rear Number Plate <i>sc</i> s/n       | \$32.10           |
| Radiator <i>bt</i>                           | \$1,338.20      | Rear Vezel Logo <i>ne</i>             | \$46.05           |
| Front Bonnet <i>bt</i>                       | \$954.85        | Rear Right Tail Lamp (body) <i>cm</i> | \$472.40          |
| Front Number Plate <i>cm</i> s/n             | \$32.10         | Rear Left Tail Lamp (body) <i>cm</i>  | \$472.40          |
| Front Number Plate Holder <i>X</i>           | \$32.10         | Rear Left Wheel Arc <i>X</i>          | \$419.60          |
| Front Grill <i>cm</i> 233                    | \$406.60        | Rear Right Wheel Arc <i>X</i>         | \$419.60          |
| Honda Logo <i>ne X</i>                       | \$41.00         | Rear Boot <i>bt</i>                   | \$1,177.95        |
| Honk <i>X</i>                                | \$69.60         | Rear Boot Lock <i>bt</i>              | \$210.40          |
| Left Retainer <i>ne</i>                      | \$22.05         | Left Retainer <i>X</i>                | \$29.45           |
| Right Retainer <i>X</i>                      | \$22.05         | Right Retainer <i>ne</i>              | \$29.45           |
| Lower Front Lip <i>sc</i> 323                | \$481.75        | Front Right Fender <i>X</i>           | \$620.60          |
| Lower Front Grille <i>X</i>                  | \$123.70        | Front Left Fender <i>repair</i>       | \$620.60          |
| Front Right Wheel Arch <i>X</i>              | \$422.65        | Grille Chrome LH <i>X</i>             | \$85.60           |
| Front Left Wheel Arch <i>X</i>               | \$422.65        | Grille Chrome RH <i>X</i>             | \$85.60           |
| Grille Chrome <i>cm</i> 114                  | \$470.80        | Spray Paint                           | \$2,800.00 / 1600 |
| Labour to dismantle / install of above parts |                 | \$2500 / 1500                         |                   |

|                 |                   |
|-----------------|-------------------|
| Company Name:   | LKK Auto          |
| Surveyed by:    | Rasul             |
| Contact Number: | 90010068          |
| Date / Time:    | 20/02/2020 @ 1430 |

*cm* Boot lamp RH \$283.20  
*cm* Boot lamp LH \$283.20

12 days

L/S

Resing after repair