

SLV 8595P

Item	Estimated Price	Item	Estimated Price
Front Panel Repair	XR \$616.60	Left Fog Lamp X SLV	\$350.65 X
Front Re-enforcement Bar bt 288	\$386.10	Right Fog Lamp X SLV	\$350.65 X
Front Bumper de 950	\$992.50	Rear Panel repair	\$440.80 XR
Headlight - Right CR	1760 \$1,947.60	Rear Bumper de	\$832.35
Headlight - Left CR	1760 \$1,947.60	Rear Sensor X SLV	\$220.00 X
Condenser bt	770 \$1,872.50	Rear Number Plate SLV	\$32.10 SLV
Radiator bt	\$1,338.20	Rear Vezel Logo CR	\$46.05
Front Bonnet bt	\$954.85	Rear Right Tail Lamp (body) CR	\$472.40
Front Number Plate CR	SLV \$32.10	Rear Left Tail Lamp (body) CR	\$472.40
Front Number Plate Holder X SLV	\$32.10	Rear Left Wheel Arc X SLV	\$419.60 X
Front Grill CR	233 \$406.60	Rear Right Wheel Arc X SLV	\$419.60 X
Honda Logo CR X 911	\$41.00	Rear Boot bt	\$1,177.95
Honk X SLV	\$69.60	Rear Boot Lock bt	\$210.40
Left Retainer CR	\$22.05	Left Retainer X SLV	\$29.45 X
Right Retainer X CR	\$22.05	Right Retainer CR	\$29.45
Lower Front Lip SLV	323 \$481.75	Front Right Fender X SLV	\$620.60 X
Lower Front Grille X SLV	\$123.70	Front Left Fender repair	\$620.60 XR
Front Right Wheel Arch X SLV	\$422.65	Grille Chrome LH X SLV	\$85.60 X
Front Left Wheel Arch X SLV	\$422.65	Grille Chrome RH X SLV	\$85.60 X
Grille Chrome CR	114 \$470.80	Spray Paint	\$2,800.00 / 650
Labour to dismantle / install of above parts	\$2,500 1550		

Company Name:	LKK Auto
Surveyed by:	Rasul
Contact Number:	90010068
Date / Time:	20/02/2020 @ 1430

CR / Best lamp RH \$283.20
CR / Best lamp LH \$283.20

P - 12320.50
20%
9856.40

SLV - 64.20

L - 3200.00
T - 13,120.60

20%
10,496.48

41-10,500

12 days

12 days
L/S
Resing after repair