

SLV 8595P

Item	Estimated Price	Item	Estimated Price
Front Panel Repair	XR \$616.60	Left Fog Lamp X SVL	\$350.65 X
Front Re-enforcement Bar bt 288	\$386.10	Right Fog Lamp X SVL	\$350.65 X
Front Bumper de 950	\$992.50	Rear Panel repair	\$440.80 XR
Headlight - Right CR ✓	1760 \$1,947.60	Rear Bumper de	\$832.35 ✓
Headlight - Left CR ✓	1760 \$1,947.60	Rear Sensor X SVL	\$220.00 X
Condenser bt ✓	770 \$1,872.50	Rear Number Plate SCL ✓ S/N	\$32.10 S/N
Radiator bt ✓	\$1,338.20	Rear Vezel Logo CR ✓	\$46.05
Front Bonnet bt ✓	\$954.85	Rear Right Tail Lamp (body) CR ✓	\$472.40
Front Number Plate CR ✓ S/N	\$32.10	Rear Left Tail Lamp (body) CR ✓	\$472.40
Front Number Plate Holder X SVL	\$32.10	Rear Left Wheel Arc X SVL	\$419.60 X
Front Grill CR ✓ 233	\$406.60	Rear Right Wheel Arc X SVL	\$419.60 X
Honda Logo CR X 911	\$41.00	Rear Boot bt ✓	\$1,177.95
Honk X SVL	\$69.60	Rear Boot Lock bt ✓	\$210.40 ✓
Left Retainer CR ✓	\$22.05	Left Retainer X SVL	\$29.45 X
Right Retainer X CR	\$22.05	Right Retainer CR ✓	\$29.45
Lower Front Lip SCL ✓ 323	\$481.75	Front Right Fender X SVL	\$620.60 X
Lower Front Grille X SVL	\$123.70	Front Left Fender repair	\$620.60 XR
Front Right Wheel Arch X SVL	\$422.65	Grille Chrome LH X SVL	\$85.60 X
Front Left Wheel Arch X SVL	\$422.65	Grille Chrome RH X SVL	\$85.60 X
Grille Chrome CR ✓ 114	\$470.80	Spray Paint	\$2,800.00 / 650
Labour to dismantle / install of above parts	\$2,500 1550		

Company Name:	LKK Auto
Surveyed by:	Rasul
Contact Number:	90010068
Date / Time:	20/02/2020 @ 1430

CR ✓ Boot lamp LH \$283.20

CR ✓ Boot lamp RH \$283.20

25,685.65#

P - 12 320.50

20%

9856.40

S/N - 64.20

L - 3200.00

T - 13,120.60

20%

10,496.48

41-10,500

12 days

12 days

L/S

Resing after repair