

ASS. REC. BY:

REF:

CS/INC20002802/ET/312

Special Instructions:

Surveyor: Stev1

ASSIGNMENT (Office)

From (Person):

Cynthia Aug

of

INC

Date/Time:

18/2/2020

Estimated Cost:

Bill to:

OD-FIT-WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMM 1490P

Insured:

GBJ 8605B

at Workshop m/s

SK Automobile

Tel:

62660555 Wilson

48 Poh Guan Rd East #01-121

Policy No:

Claim No:

MT/1084583-001

Sum Insured:

Excess:

Make of Veh:

D.O.A.

14/2/2020

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

18/2

Person Contacted:

Wilson

Vehicle IN/OUT

Date/Time

Action/Instruction

Issued (✓)

SMM 1490P - NA/INC20002802/24 DOR: 14/2/2020

GBJ 8605B - X

Surgeur

Steve

REF:

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured

Policy No.

Claims No.

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR. Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: **SMM 1490P**

Yr Regn:

26/7/09

Type: ☒ M. Car / ☐ M. Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Troller or

Make: **Ford V195**

c.c **1497**

Colour

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

112587

T/Radio:

Insured / Std / NI / NA

Eng/No:

MR053HY 9305117841

C/Nr:

Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ Burnt

Steering: In order / ☒ Jammed / ☐ Leaked / ☐ Burnt or

Brake: In order / ☒ Jammed / ☐ Leaked / ☐ Burnt or

Modl: Nil / ☒ S/Rim / ☐ STD A/Rim or

Tyre Size:

F:

195/55R15

R:

1

☒ BS / ☐ DUN / ☐ EXNOVA / ☐ GY / ☐ FS / ☐ LIZA / ☐ MIC / ☐ OHTSU / ☐ PIR / ☐ SUMI / ☐ TOYO / ☐ YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

14/2/20

D.O.I.

18/2/20

Survey held at

SK Automobile

0217PM

Des. of Damages

☒ Frt / ☒ Rear / ☐ O/S / ☐ NIS / ☐ UIC / ☐ Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV - 43,099

PV - 27,916

NV - 15,984

16/3/20 Final \$11,450, 13 days (winn). (Red: 1820635; 6106)

RECEIVED 16 MAR 2020

Date/Time, File Pass to?

1) 16/3 Typist

Date/Time, File Return to?

2)

Report Format:

TP

Lump Sum / I.B.I. (\$

114501

Days Of Repair:

13

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Inv (\$

☐

Weekend (\$

Survey Fee:

250

Transportation:

\$ - RS - \$

Plate

Others

TOTAL

250

Nivitha (LKK Auto)

From: Cynthia Ang <Cynthia.Ang@income.com.sg>
Sent: Tuesday, 18 February 2020 9:53 AM
To: 'assignments@lkkauto.com'; Admin-D (LKKAuto)
Cc: Toh Choon Hin; Thio Tse Kiat
Subject: TP CASES FARMED OUT TO LKK ON 18/02/2020

Dear LKK,

Please assist to survey the following vehicles as per Mr Toh's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	OI VEH	DOA	Additional Remarks
1		MT/1084583-001	5MM1490P	SK AUTOMOBILE PTE LTD	48 Toh Guan Road East # 01-121 Enterprise Hub Singapore 608586	Winson / 62660555			
2			GBD275D	WOON MENG MOTOR PTE LTD	50 BUKIT BATOK STREET 23 #01-06 MIDVIEW BUILDING SINGAPORE 659578	/ 63161131			
3			PC6504T	SK AUTOMOBILE PTE LTD	8 KAKI BUKIT AVENUE 4 #08-46 PREMIER@KAKI BUKIT	CHRIS / 6702 1555			
4			PC6855E	SK AUTOMOBILE PTE LTD	8 KAKI BUKIT AVENUE 4 #08-46 PREMIER@KAKI BUKIT	CHRIS / Julie / 6702 1555			6789 5155
5		MT/1082747-002	SMK1259C	SK AUTOMOBILE PTE LTD	8 KAKI BUKIT AVENUE 4 #08-46 PREMIER@KAKI BUKIT	Julie / 6789 5155			9623 4440 / 9099 6204
6			SLK6383E	XIN HUA WORKSHOP	8 KAKI BUKIT AVENUE 4 #08-40 PREMIER @ KAKI BUKIT SINGAPORE 415875	Eric / 8222 8966			

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Cynthia Ang

Admin Assistant

Operations, Motor & Personal Lines

T +65 6430 7900

www.income.com.sg

Cc: Toh Choon Hin; Thio Tse Kiat
 Subject: TP CASES FARMED OUT TO LKK ON 18/02/2020

Dear LKK,

Please assist to survey the following vehicles as per Mr Toh's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	OI VEH	DOA	Additional Remarks
1	Chryllis Quah	MT/1084583-001	SMM1490P	SK AUTOMOBILE PTE LTD	48 Toh Guan Road East # 01-121 Enterprise Hub Singapore 608586	Winson / 62660555	GBJ8605B	14/02/2020	
2	Helena Tan	MT/1084612-002	GBD275D	WOON MENG MOTOR PTE LTD	50 BUKIT BATOK STREET 23 #01-06 MIDVIEW BUILDING SINGAPORE 659578	/ 63161131	GBB5975U	15/02/2020	
3	Charlotte Chew	MT/1084714-002	PC6504T	SK AUTOMOBILE PTE LTD	8 KAKI BUKIT AVENUE 4 #08-46 PREMIER@KAKI BUKIT	CHRIS / 6702 1555	GBJ6751A	17/02/2020	
4	David Phua	MT/1084799-001	PC6855E	SK AUTOMOBILE PTE LTD	8 KAKI BUKIT AVENUE 4 #08-46 PREMIER@KAKI BUKIT	CHRIS / Julie / 6702 1555	GBB9320H	11/02/2020	6789 5155
5	Charlotte Chew	MT/1082747-002	SMK1259C	SK AUTOMOBILE PTE LTD	8 KAKI BUKIT AVENUE 4 #08-46 PREMIER@KAKI BUKIT	Julie / 6789 5155	SLQ976C	03/02/2020	9623 4440 / 9099 6204
6	Cyndie Yong	MT/1084738-001	SLK6383E	XIN HUA WORKSHOP	8 KAKI BUKIT AVENUE 4 #08-40 PREMIER @ KAKI BUKIT SINGAPORE 415875	Eric / 8222 8966	SKA2577D	15/02/2020	

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

With Regards

Cynthia Ang

Admin Assistant

Operations, Motor & Personal Lines

T +65 6430 7900

www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify. Find out more at Income.com.sg/careers



PLEASE CONSIDER OUR ENVIRONMENT BEFORE YOU PRINT THIS EMAIL...

Steve Chen (LKK Auto)

From: toh guan <tohguan@skauto.com.sg>
Sent: Wednesday, March 11, 2020 7:15 PM
To: Steve Chen (LKK Auto)
Cc: Winson Ng; SK Admin
Subject: Re: SMM1490P - Finalize

Hi Steve Chen,

We accept vehicle SMM1490P finalize \$11450.00 (before GST) with 13 working days.

Thank you.

On Wed, Mar 11, 2020 at 7:05 PM SK Admin <admin@skauto.com.sg> wrote:
FYI

----- Forwarded message -----

From: SK Admin <admin@skauto.com.sg>
Date: Tuesday, March 10, 2020
Subject: SMM1490P - Finalize
To: "Steve Chen (LKK Auto)" <stevechen@lkkauto.com>
Cc: simon koh <simon@skauto.com.sg>, KY Leong <kyleong@skauto.com.sg>, Winson Ng <winsonng@skauto.com.sg>

Dear Steve,

Thanks for your email.

Aside to Winson,

Kindly assist.
Thank you

Regards,
Huey Lee
SK Automobile Pte Ltd

----- Forwarded message -----

From: Steve Chen (LKK Auto) <SteveChen@lkkauto.com>
Date: Tue, Mar 10, 2020 at 7:55 PM
Subject: SMM1490P - Finalize
To: Pioneer Workshop <pioneer@skauto.com.sg>
Cc: SK Admin <admin@skauto.com.sg>

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/02/2020 16:54
Date Of Accident	14/02/2020 17:30
Exact Location Of Accident	AYE TWDS CITY AFTER JURONG TOWN HALL RD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMM1490P
Insured/Policyholder	
Name Of Registered Owner	CHEONG SIEW PUN
NRIC No	SXXXX718H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-90999721
Alternative Phone No	OFFICE-90999721

Vehicle Particulars

Manufacturer	TOYOTA
Model	VIOS E MANUAL
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5110535615
Cover Note Number	

Driver

Name of Driver	CHEONG WEN QING
NRIC No	TXXXX595D
Date Of Birth	25/06/2000
Occupation	INDOOR
Date Of Driving Pass	02/11/2018
Driving Experience	1 YEAR AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93918700
Fax Number	
Contact Number	OFFICE-93918700
Email Address	NOEMAIL

Address	BLK 114 HO CHING ROAD #09-62
Postcode	610114
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TRAFFIC POLICE DIVISION HQ - SINGAPORE CITY
Police Station Address	ROAD: 10 UBI AVENUE 3 , POSTCODE: 408865 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 65470000 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20200215/7012.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBJ8605B
Vehicle Make/Model/Colour	NISSAN NV200
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	91117560
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SBL6226P
Vehicle Make/Model/Colour	BMW 3 SERIES
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	94554056
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	SLW2221C
Vehicle Make/Model/Colour	TOYOTA CHR
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	90402127
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	CHEONG WEN QING
Approximate Age	
Injuries Sustain	BODY
Injured person in which vehicle?	SMM1490P
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to regulate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:


Reporting Centre Person's Signature
Name:
NRIC/Pass No.:

Accident Sketch Plan



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

[Signature]

Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature]

Reporting Constable Person's Signature
Name:
NRSC/TIN No.:

Police Report



**SINGAPORE
POLICE FORCE**



T/20200215/7012

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

1 of 3

Report No. T/20200215/7012

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 15/02/2020 16:33	Video Report No.:	Station Diary No.:
--	-------------------	--------------------

Informant's Particulars

Name of Informant: CHEONG WEN QING			Address: APT BLK 114 HO CHING ROAD #09-62 SINGAPORE 610114		
ID Type / ID No.: NRIC NO / T0020595D			Contact No.: Home/Office: Mobile: 88008132		
Nationality: SINGAPORE CITIZEN			Email: cheong.wqing@gmail.com		
Sex: Male	Age: 19	Date of Birth: 25/06/2000	Type of Informant: Driver		
Race: Chinese			Language: English		Institution / School Name
Occupation: UNEMPLOYED			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 14/02/2020 17:30	Type of Location: Straight Road
Location: AYER RAJAH EXPRESSWAY				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBJ6605B	Van	NISSAN	NV200		Slightly Damaged	0
SBL6221C	Car	BMW				0
SLW2221C	Car	TOYOTA	CHR		Slightly Damaged	0
SMM1490P	Car	TOYOTA	vios	Grey	Slightly Damaged	0

Police Report



**SINGAPORE
POLICE FORCE**



T/20200215/7012

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000

2 of 3

Report No. T/20200215/7012

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	CHEONG WEN QING	ID No.	T0020595D
Related Vehicle	SMM1490P (Car)	Contact No.	88008132
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	14/02/2020	Date Discharge	14/02/2020
No. of Days granted Medical Leave	05	Degree of Injury	Slight

Brief Details

On the stated time and date,

I was driving my car (Veh A: SMM1490P) along AYE towards City after Jurong Town Hall Exit. The traffic was heavy thus the car (Veh C: SBL6226P) in front of me slowed down and came to a complete stop. I followed suite. Suddenly, I felt an impact from my rear which caused me to surge forward and collide onto Veh C. I alighted and realized a van (Veh B:GBG8605) had collided onto me and there was another car (Veh D: SLN2221C) behind of him. We were involved in a 4 car chain accident. I felt pain on my left shoulder, neck and chest area and went to see a doctor. I was give 5 days of MC by Intermedical 24 HR clinic at AMK.

Police Report



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police
10 Ubi Avenue 3 SINGAPORE 408865
Tel No: 65470000



T/20200215/7012

3 of 3

Report No. T/20200215/7012

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan.

Signature Of Officer Recording The Report:
Not applicable

Signature Of Interpreter:
Not applicable

Officer In Charge Of Case:
TP / TPHQ /
ONG YONG HOCK
Contact No.: 65476436

Authentication Stamp
NP168

Signature Of Informant:
The identity of the person making this report has
been authenticated by SingPass. No signature is
required.

Date/Time:
15/02/2020 16:33

Classification Of Case:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 718H

Vehicle Details

Vehicle No.: SMM1490P
Vehicle to be Exported: No
Intended Deregistration Date: 17 Feb 2020
Vehicle Make: TOYOTA
Vehicle Model: VIOS E MANUAL
Primary Colour: Silver
Manufacturing Year: 2009
Engine No.: 1NZX925042
Chassis No.: MR053HY9305117841
Maximum Power Output: 80.0 kW (107 bhp)
Open Market Value: \$11,860.00
Original Registration Date: 26 Jun 2009
First Registration Date: 26 Jun 2009
Transfer Count: 1
Actual ARF Paid: \$11,860.00

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 25 Jun 2029
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
PQP Paid: \$29,839.00
COE Rebate Amount: \$27,916.00
Total Rebate Amount: \$27,916.00

The information contained herein is correct as at 17 Feb 2020

OK

SKODA
presentsSMARTS THAT ALWAYS STEAL THE SHOW.
CENTURY SQUARE | 26 FEB - 3 MAR

Post an Advertisement
Sell it yourself. Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

How it's Selling



How to Upgrade Your Used Car
1. Find a car to upgrade to
2. Get a loan for the car
3. Upgrade to the new car
4. Sell the old car
5. Repeat the process



Browse by Category

1 2 3 4 5 6 | Total 6

Sort by Date Posted | 22 results/page

109 vehicles

Toyota Vios

Filter

Model Price Depreciation Mileage Year Type Status

Search Selection Toyota Vios 2015 13 year(s) 131,847 km Sedan Available



Toyota Vios 1.5A G (COE 18/03/2025) \$15,588 \$5,830 /yr 18-Apr-2008 1,957 cc 131,847 km Sedan Available

No Quibble, Direct Owner, Appointment To Be Made For Any Location For Viewing, WhatsApp Now.

Model: 18-Apr-2008 Price: \$15,588 Toyota Vios, 2008 Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios



Toyota Vios 1.5A E (COE 18/04/2024) \$25,500 \$5,585 /yr 29-Apr-2008 1,957 cc 122,720 km Sedan Available

One Of The Most Popular Japanese Car In Singapore In Best Condition Major Servicing Just Done With New And Tires Replaced, Drive Off With A Peace Of Mind Trade-In Welcome. Call Now To Book An Appointment To View This Beauty. Viewing Strictly Appointment.

Model: 11-Feb-2020 Price: \$25,500 Toyota Vios, 2008 Toyota Vios, 2008 Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios



Toyota Vios 1.5A E (COE 18/04/2024) \$24,000 \$5,715 /yr 26-Mar-2008 1,957 cc 130,803 km Sedan Available

Full Efficiency Of 12km Per Liter! One Of The Best Selling Japanese Car! Owner Upgrade Hence Selling His Well Maintained Unit, Smooth Condition And Fastwork, Very Low Mileage! Trade-In/High Loan Offered Here At 10% Below Singapore! Call Us Now To View This Beauty.

Model: 10-Jun-2020 Price: \$24,000 Toyota Vios, 2008 Toyota Vios, 2008 Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios



Toyota Vios 1.5A G (COE 18/03/2024) \$17,800 \$4,490 /yr 10-Jun-2009 1,957 cc - Sedan Available

Car On Zero Down Payment, 100% Full Loan, Easy Approval, Bank Loan And In House Loan, Monthly From \$400, Bad Credit And Damaged Bankruptcy Are Welcome, No Payday Also Can, All Car Comes With Warranty, Loan Amount Started - Full Loan Specialist, See...

Model: 19-Feb-2020 Price: \$17,800 Toyota Vios, 2009 Toyota Vios, 2009 Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios



34 year COE expiring? Let us help you renew it!

Getting your COE renewed is easy, fast and affordable. We'll help you renew your COE and get a loan for it. Get the cheapest loan in town and an approval in 2 days without effort! Inquire today.



Toyota Vios 1.5A G (COE 18/07/2024) \$18,800 \$4,760 /yr 15-Jul-2008 1,957 cc - Sedan Available

Full Loan Available! Rare Highest Score G-Max! Vios For Sale! Car In Perfect Condition! 100% Accident-Free! STA Evaluation! View To Believe! Full And Flexible Loan Available! Call Us Now To Make An Appointment To View Now Before It's Gone!

Model: 20-Jun-2020 Price: \$18,800 Toyota Vios, 2008 Toyota Vios, 2008 Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios



Toyota Vios 1.5A E (COE 18/07/2024) \$18,800 \$4,340 /yr 27-Jul-2008 1,957 cc - Sedan Available

Full Loan Available At \$500 Plus, We Can Help To Convert To 220 Usage If Needed. In House Loan Or Bank Loan Available! Fast, Easy And Flexible Loan Approval! We Are sgCarMart Premium Dealer! Buy With Confidence! Viewing And Test Drive Available Daily Including...

88 Motor Trading

Model: 22-Apr-2020 Price: \$18,800 Toyota Vios, 2008 Toyota Vios, 2008 Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios



Toyota Vios 1.5A E (COE 18/05/2025) \$43,888 \$4,730 /yr 04-Aug-2008 1,957 cc 171,000 km Sedan Available

Full Economics.

Model: 21-Jun-2020 Price: \$43,888 Toyota Vios, 2008 Toyota Vios, 2008 Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios



Toyota Vios 1.5A E Sports (COE 18/08/2024) \$27,800 \$5,180 /yr 18-Aug-2008 1,957 cc - Sedan Available

Original Sports Edition! Full Loan Monthly \$700! Sports Model Back Vios With New COE, Low Mileage! 0000 Condition! Regularly Maintained, Good Engine, Clean And Neat Interior, Flexible Loan Packages, Most Practical, Reliable Engine, Not Fuel Efficient, Call Us For...

88 Motor Trading

Model: 28-Jun-2020 Price: \$27,800 Toyota Vios, 2008 Toyota Vios, 2008 Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios



Toyota Vios 1.5A E (COE 18/09/2024) \$24,500 \$5,810 /yr 11-Sep-2008 1,957 cc - Sedan Available

Monthly \$428, Whole Fully Done Up With Premium Drapery And Brand New Paint Coat, Purchase Comes With 6 Months Certified Pre-Owned Car Warranty With 24/7 Roadside Assistance Coverage. STA/CDP/VA Evaluation Friendly. Viewing Available Daily By Appointment.

Model: 10-Jun-2020 Price: \$24,500 Toyota Vios, 2008 Toyota Vios, 2008 Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios



Toyota Vios 1.5A E (COE 18/09/2024) \$18,800 \$4,390 /yr 16-Sep-2008 1,957 cc 102,300 km Sedan Available

COE Specialist! 100% Loan Approval Offering 6 Months Warranty! Very Well Maintained By Previous Owner! Vehicle Is Always Parked Under Shelter! Call Us Now To Book A Test Drive! No Obligations!

Young Motor Pte Ltd

Model: 18-Feb-2020 Price: \$18,800 Toyota Vios, 2008 Toyota Vios, 2008 Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios, Toyota Vios

Save on petrol with UDS One card!

Enjoy huge petrol savings of up to 24%, attractive cashback on your monthly spend, and 1-year annual fee waiver. Apply now and start enjoying today.

Compare

SK Automobile Pte. Ltd.
(Co Reg. No. 201500047H)
23 Kaki Bukit Ave 4, #03-01
Vicom Inspection Centre (S415933)
Tel : 6789 5155 Fax : 6783 5155

TO : NTUC	DATE : 17-Feb-20
ATTENTION : MOTOR CLAIMS DEPARTMENT	JOB TYPE : T/P CLAIMS
ESTIMATE REPORT :	
OWNER PARTICULAR	VEHICLE DETAILS
NAME :	VEHICLE NO. : SMM1490P
ADDRESS :	MODEL / MAKE : TOYOTA VIOS
TEL. NO. :	CHASSIS NO. : MR053HY9305117841
OWNER INSURANCE : NTUC	ACCIDENT DETAIL
POLICY NO. : 5110535615	DATE : 14-Feb-20
	TIME : 17:30hrs
PERSON INCHARGE :	

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BOOT LID / DD	1	\$ 625.70	\$ 625.70
2	REAR BOOT LID LOGO EMBLEM / M	1	\$ 47.20	\$ 47.20
3	REAR BOOT LID E EMBLEM / M	1	\$ 36.71	\$ 36.71
4	REAR BOOT LID OUTER GARNISH / OR	1	\$ 153.80	\$ 153.80
5	REAR BOOT LID OUTER KEY LOCK X MM	1	\$ 95.70	\$ 95.70
6	REAR NUMBER PLATE LAMP LH/RH X MM	2	\$ 45.80	\$ 91.60
7	REAR BOOT LID HINGES LH/RH X R	2	\$ 75.21	\$ 150.42
8	REAR BOOT LID RUBBER GUIDE STOPPER X MM	2	\$ 25.10	\$ 50.20
9	REAR BOOT LID MECHANISM LOCK / BT	1	\$ 119.01	\$ 119.01
10	REAR BOOT LID WEATHERSHIP / PM	1	\$ 185.30	\$ 185.30
11	REAR TAILLAMP LH/RH / BR	2	\$ 256.10	\$ 512.20
12	REAR TAILLAMP BACK RUBBER GASKET LH/RH / M	2	\$ 15 28.20	\$ 56.40
13	REAR TAILLAMP INNER PANEL LH/RH / BT	1/2	\$ 205.24	\$ 410.48
14	REAR BUMPER / DD	1	\$ 527.15	\$ 527.15
15	REAR BUMPER REFLECTOR LH/RH / OR	1/2	\$ 98.25	\$ 196.50
16	REAR BUMPER RETAINER LH/RH / BR	2	\$ 85.00	\$ 170.00
17	REAR BUMPER CORNER RETAINER LH/RH / OR	2	\$ 85.10	\$ 170.20
18	REAR BUMPER INNER SIDE SHIELD LH/RH X TN	1/2	\$ 48.60	\$ 97.20
19	REAR END PANEL / DD	1	\$ 617.10	\$ 617.10
20	REAR END PANEL INNER TOP GARNISH / CRV	1	\$ 182.50	\$ 182.50
21	REAR END PANEL LOCK STRIKER X MM	1	\$ 36.80	\$ 36.80
22	REAR ENG PANEL BRAKET PLATE LH/RH X MM	2	\$ 38.20	\$ 76.40
23	SPARE TYRE PANEL / DD	1	\$ 657.20	\$ 657.20
24	SPRAY TYRE PANEL INNER TOP CARD BOARD / CRV	1	\$ 135.70	\$ 135.70
25	SPARE TYRE PANEL INNER TOP SPONGE X MM	1	\$ 125.60	\$ 125.60
26	SPARE TYRE SIDE PANEL LH/RH X MM	2	\$ 105.70	\$ 211.40
27	SPARE TYRE SIDE PANEL INNER TOP SPONGE LH/RH / CRV	2	\$ 95.10	\$ 190.20

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
28	SPRAY TYRE RETAINER LOCK X <i>NN</i>	1	\$ 45.60	\$ 45.60 X
29	REAR FENDER RH / <i>DT</i>	1	\$ 826.10	\$ 826.10 /
30	REAR FENDER INNER AIR VENT RH X <i>MM</i>	1	\$ 123.50	\$ 123.50 X
31	REAR FENDER INNER UPHOLSTERY TRIM LH/RH X <i>NN</i>	2	\$ 213.60	\$ 427.20 X
32	REAR WINDSCREEN MOULDING / <i>MC</i>	1	\$ 28.60	\$ 28.60 /
33	EXHAUST MID PIPE / <i>DT</i>	1	\$ 635.80	\$ 635.80 /
34	REAR EXHAUST RUBBER MOUNTING / <i>TN</i>	2 3	\$ 18.90 28.90	\$ 86.70 3780 ✓
35	REAR EXHAUST ALUMINIUM HEAT SHIELD / <i>DT</i>	1	\$ 185.70	\$ 185.70 /
36	REAR SUB CHAISIS FRAME RH X <i>MM</i>	1	\$ 455.80	\$ 455.80 X
TOTAL PRICE				\$ 8,743.67
LESS -25%				\$ (2,185.92)
SUB TOTAL PRICE				\$ 6,557.75

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BOOT LID OUTER GARNISH CLIPS SET / <i>MC</i>	1	\$ 40.00	\$ 40.00 10 ✓
2	REAR BOOT LID NUMBER PLATE WITH GARNISH SET X <i>NN</i>	1	\$ 95.00	\$ 95.00 X
3	REAR TAILLAMP INNER PANEL SEALANT LH/RH / <i>MC</i>	2	\$ 50.00	\$ 100.00 30 ✓
4	REAR TAILLAMP CLIPS SET LH/RH / <i>MC</i>	2	\$ 40.00	\$ 80.00 20 ✓
5	REAR TAILLAMP BRAKE BULB LH/RH X <i>NN</i>	2	\$ 15.00	\$ 30.00 X
6	REAR TAILLAMP SIGNAL BULB LH/RH X <i>NN</i>	2	\$ 15.00	\$ 30.00 X
7	REAR TAILLAMP REVERSE BULB LH/RH X <i>NN</i>	2	\$ 15.00	\$ 30.00 X
8	REAR BUMPER REVERSE SENSOR SET / <i>SL</i>	1	\$ 280.00	\$ 280.00 280 ✓
9	REAR BUMPER CLIPS SET / <i>MC</i>	1	\$ 65.00	\$ 65.00 30 ✓
10	REAR END PANEL SEALANT / <i>MC</i>	1	\$ 60.00	\$ 60.00 30 ✓
11	REAR END PANEL INNER TOP GARNISH CLIPS SET / <i>MC</i>	1	\$ 40.00	\$ 40.00 10 ✓
12	SPRAY TYRE PANEL SEALANT / <i>MC</i>	1	\$ 150.00	\$ 150.00 30 ✓
13	SPRAY TYRE PANEL INSULATOR MAT X <i>NN</i>	1	\$ 380.00	\$ 380.00 X
14	SPRAY TYRE PANEL INNER TOP JACKING TOOL X <i>NN</i>	1	\$ 180.00	\$ 180.00 X
15	SPRAY TYRE PANEL INNER TOP BREAK SOWN X <i>NN</i>	1	\$ 150.00	\$ 150.00 X
16	REAR FENDER SEALANT RH / <i>MC</i>	1	\$ 120.00	\$ 120.00 20 ✓
17	REAR FENDER INSULATOR MAT RH / <i>MC</i>	1	\$ 180.00	\$ 180.00 30 ✓
18	REAR FENDER INNER UPHOLSTERY TRIM CLIPS SET LH/RH / <i>MC</i>	2	\$ 60.00	\$ 120.00 30 ✓
19	REAR WINDSCREEN INNER GARNISH CLIPS SET LH/RH X <i>NN</i>	2	\$ 40.00	\$ 80.00 X
20	REAR WINDSCREEN SEALANT WITH PRIMER SET / <i>MC</i>	1	\$ 100.00	\$ 100.00 40 ✓
21	REAR EXHAUST SILENCER BOX / <i>DT</i>	1	\$ 1,800.00	\$ 1,800.00 600 ✓
22	REAR SUB CHAISIS FRAME SEALANT RH X <i>NN</i>	1	\$ 60.00	\$ 60.00 X

TOTAL

\$ 4,170.00

1980

QUOTATION SUMMARY

PAGE 04

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
37	FRONT GRILLE / DR	1	\$ 255.90	\$ 255.90
38	FRONT GRILLE CHROME MOULDING / DR	1	\$ 135.80	\$ 135.80
39	FRONT HEADLAMP LH/RH / DR	12	\$ 446.70	\$ 893.40
40	FRONT HEADLAMP TOP PANEL LH/RH / DT	12	\$ 100.60	\$ 201.20
41	FRONT BUMPER / DR	1	\$ 485.50	\$ 485.50
42	FRONT BUMPER LOGO EMBLEM / MC	1	\$ 55.40	\$ 55.40
43	FRONT BUMPER LOGO EMBLEM BASE X MI	1	\$ 85.40	\$ 85.40
44	FRONT BUMPER LOWER CENTER GRILLE / DR	1	\$ 80.30	\$ 80.30
45	FRONT BUMPER FOG LAMP COVER LH/RH X (R4) DR	12	\$ 105.20	\$ 210.40
46	FRONT BUMPER SIDE RETAINER LH/RH / DR	2	\$ 70.10	\$ 140.20
47	FRONT BUMPER TOP RETAINER / CR4	1	\$ 115.90	\$ 115.90
48	FRONT BUMPER REINFORCEMENT / DD	1	\$ 382.80	\$ 382.80
49	FRONT BUMPER REINFORCEMENT BRACKET LH/RH / DT	12	\$ 202.70	\$ 405.40
50	FRONT BUMPER REINFORCEMENT EXTENSION PANEL LH/RH / DT	12	\$ 75.60	\$ 151.20
51	FRONT FENDER LH/RH X R	12	\$ 559.50	\$ 1,119.00
52	FRONT FENDER VVT-I EMBLEM LH/RH / MC	12	\$ 30.40	\$ 60.80
53	FRONT FENDER INNER SHIELD LH/RH X MI	2	\$ 168.30	\$ 336.60
54	FRONT FENDER INNER SHIELD VERTICAL LH/RH X MI	2	\$ 222.20	\$ 444.40
55	FRONT SUPPORT PANEL / DT	1	\$ 925.90	\$ 925.90
56	AIR DUCT X MI	1	\$ 70.70	\$ 70.70
57	WASHER TANK / CR4	1	\$ 120.60	\$ 120.60
58	AIRCON CONDENSER / DD	1	\$ 1,155.50	\$ 1,155.50
59	AIRCON CONDENSER AIR GUIDE UPPER LH/RH - CR4	12	\$ 40.40	\$ 80.80
60	AIRCON CONDENSER AIR GUIDE BOTTOM LH/RH - CR4	12	\$ 85.30	\$ 170.60
61	AIRCON CONDENSER AIR GUIDE RH X / DR	1	\$ 85.20	\$ 85.20
62	AIRCON OUTSIDE TEMPERATURE SENSOR X MI	1	\$ 255.10	\$ 255.10
63	RADIATOR X MI	1	\$ 1,819.90	\$ 1,819.90
64	RADIOATR FAN COWLING X MI	1	\$ 240.80	\$ 240.80
65	RADIATOR FAN MOTOR X MI	1	\$ 120.70	\$ 120.70
66	RADIATOR FAN BLADE X MI	1	\$ 195.60	\$ 195.60
67	ENGINE LOWER UNDER COVER LH/RH X MI	2	\$ 158.90	\$ 317.80

TOTAL PRICE \$ 11,118.80
 LESS -25% \$ (2,779.70)
SUB TOTAL PRICE \$ 8,339.10

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
23	FRONT HEADLAMP CLIPS SET LH/RH / MC	12	\$ 40.00	\$ 80.00
24	FRONT BUMPER CLIPS SET / MC	1	\$ 65.00	\$ 65.00
25	FRONT BUMPER LED LAMP SET / DR	1	\$ 450.00	\$ 450.00
26	FRONT FENDER INNER SHIELD CLIPS SET LH/RH X MI	2	\$ 60.00	\$ 120.00
27	FRONT SUPPORT PANEL SEALANT / MC	1	\$ 80.00	\$ 80.00
28	AIRCON CONDENSER AIR GUIDE TOP CLIPS SET LH/RH X MI	2	\$ 40.00	\$ 80.00
29	AIRCON CONDENSER AIR GUIDE BOTTOM CLIPS SET LH/RH X MI	2	\$ 40.00	\$ 80.00
30	AIRCON CONDENSER AIR GUIDE CLIPS SET RH X MI	1	\$ 40.00	\$ 40.00
31	RADIATOR COOLANT X MI	1	\$ 80.00	\$ 80.00

TOTAL \$ 1,075.00

QUOTATION SUMMARY

PAGE 03

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING REAR PORTION

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 2,200.00	1500	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,800.00	1100	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 200.00	50	
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	30	
TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION	\$ 280.00	X	
TO DISMANTLE & REINSTALL REAR PETROL TANK FOR FACILITATE REPAIR	\$ 250.00	X	
TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM WITH WATER LEAK TEST	\$ 150.00	120	
TO PERFORM TRANSFER REAR BOOT LID MECHANISM & REALIGN BACK TO MANUFACTURING SPECIFICATION	\$ 120.00	50	
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 80.00	30	
TO DISMANTLE & REPLACED REAR EXHAUST SILENCER BOX WITH EXHAUST MID PIPE	\$ 280.00	80	
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00	80	
TOWING SERVICE ACCIDENT SCENE TOW TO WORKSHOP	\$ 120.00	60	

TOTAL

\$ 5,840.00

4799.22

1080

3100

8979.22

3100

QUOTATION SUMMARY

PAGE 05

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

fl pda

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$	1,600.00	800	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$	1,400.00	700	
TO APPLY ANTI-RUST & TUFF KOTE	\$	175.00	30	
TO PERFORM LIGHTING & WIRING CHECK	\$	80.00	7	
TO DISMANTLE & REINSTALL AIRCON CONDENSOR WITH REFILL AIRCON GAS	\$	120.00	/	
TO DISMANTLE & REINSTALL RADIATOR WITH REFILL RADIATOR COOLANT & HIGH PRESSURE TEST	\$	120.00	50	
TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT	\$	100.00	X	
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$	80.00	X	

TOTAL \$ 3,675.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 20,141.85
 TOTAL LABOUR COST : \$ 9,515.00
 TOTAL REPAIR COST : \$ 29,656.85

APPROVED DETAILS

NO. OF REPAIR DAYS : 13 DAYS

REPAIR UNDER : PART BY PART OR LUMP SUM

DATE / TIME OF SURVEY : 18/2/20, 3:00pm

SURVEYED BY / FROM :

CONTACT NUMBER :

FAX NUMBER :

EMAIL ADDRESS :

DATE / TIME OF RE-SURVEY :

1700
 3333-75
 290
 1700
 5323-75
 + 8970-22
 14,293-97
 L/S - 11,435-17
 = 11,450

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607196R GST Reg. No. 19-9607196-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC20002802/Etf3e2

73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 24-03-2020



ATTN: CHRYLLIS QUAH

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBJ 8605B	Veh. Inspected	SMM 1490P
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1084583-001	Excess (\$)	0.00
Assign From	CYNTHIA ANG	Assign Date	18/02/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	MR053HY9305117841	Colour	SILVER
Odometer	143587 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R15	BRIDGESTONE	5 mm
L/H Front Tyre	195/55 R15	BRIDGESTONE	5 mm
R/H Rear Tyre	195/55 R15	BRIDGESTONE	5 mm
L/H Rear Tyre	195/55 R15	BRIDGESTONE	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	14/02/2020	Inspect Date / Time	18/02/2020 (02:17 PM)
Survey held at	48 TOH GUAN ROAD EAST #01-121		
Repairer	SK AUTOMOBILE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	13 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMM 1490P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT LID	DENTED	625.70	625.70
1	REAR BOOT LID LOGO EMBLEM	NECESSARY	47.20	47.20
1	REAR BOOT LID E EMBLEM	NECESSARY	36.71	36.71
1	REAR BOOT LID OUTER GARNISH	BROKEN	153.80	153.80
1	REAR BOOT LID OUTER KEY LOCK	NOT NECESSARY	95.70	-
2	REAR NUMBER PLATE LAMP LH/RH @\$45.80	NOT NECESSARY	91.60	-
2	REAR BOOT LID HINGES LH/RH @\$75.21	TO REPAIR SEE LABOUR	150.42	-
2	REAR BOOT LID RUBBER GUIDE STOPPER @\$25.10	NOT NECESSARY	50.20	-
1	REAR BOOT LID MECHANISM LOCK	BENT	119.01	119.01
1	REAR BOOT LID WEATHERSTRIP	CRUSHED	185.30	185.30
2	REAR TAILLAMP LH/RH @\$256.10	BROKEN	512.20	512.20
2	REAR TAILLAMP BACK RUBBER GASKET LH/RH @\$28.20	NECESSARY	56.40	30.00
2	REAR TAILLAMP INNER PANEL LH/RH @\$205.24	O/S BENT	410.48	205.24
1	REAR BUMPER	DENTED	527.15	527.15
2	REAR BUMPER REFLECTOR LH/RH @\$98.25	O/S BROKEN	196.50	98.25
2	REAR BUMPER RETAINER LH/RH @\$85.00	BROKEN	170.00	170.00
2	REAR BUMPER CORNER RETAINER LH/RH @\$85.10	BROKEN	170.20	170.20
2	REAR BUMPER INNER SIDE SHIELD LH/RH @\$48.60	O/S TORN	97.20	48.60
1	REAR END PANEL	DENTED	617.10	578.00
1	REAR END PANEL INNER TOP GARNISH	CRUSHED	182.50	182.50
1	REAR END PANEL LOCK STRIKER	NOT NECESSARY	36.80	-
2	REAR END PANEL BRACKET PLATE LH/RH @\$38.20	NOT NECESSARY	76.40	-
1	SPARE TYRE PANEL	DENTED	657.20	657.20
1	SPARE TYRE PANEL INNER TOP CARD BOARD	CRUSHED	135.70	135.70
1	SPARE TYRE PANEL INNER TOP SPONGE	NOT NECESSARY	125.60	-
2	SPARE TYRE SIDE PANEL LH/RH @\$105.70	NOT NECESSARY	211.40	-
2	SPARE TYRE SIDE PANEL INNER TOP SPONGE LH/RH @\$95.10	CRUSHED	190.20	190.20
1	SPARE TYRE RETAINER LOCK	NOT NECESSARY	45.60	-
1	REAR FENDER RH	DENTED	826.10	826.10

Report Ref No. CS/INC20002802/Etf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR FENDER INNER AIR VENT RH	NOT NECESSARY	123.50	-
2	REAR FENDER INNER UPHOLSTERY TRIM LH/RH @ \$213.60	NOT NECESSARY	427.20	-
1	REAR WINDSCREEN MOULDING	NECESSARY	28.60	28.60
1	EXHAUST MID PIPE	BENT	635.80	635.80
3	REAR EXHAUST RUBBER MOUNTING @ \$28.90	TORN (2 PCS ONLY)	86.70	37.80
1	REAR EXHAUST ALUMINIUM HEAT SHIELD	BENT	185.70	185.70
1	REAR SUB CHASIS FRAME RH	NOT NECESSARY	455.80	-
1	FRONT GRILLE	BROKEN	255.90	255.90
1	FRONT GRILLE CHROME MOULDING	BROKEN	135.80	135.80
2	FRONT HEADLAMP LH/RH @ \$446.70	O/S BROKEN	893.40	446.70
2	FRONT HEADLAMP TOP PANEL LH/RH @ \$100.60	BENT (1 PC ONLY)	201.20	100.60
1	FRONT BUMPER	BROKEN	485.50	485.50
1	FRONT BUMPER LOGO EMBLEM	NECESSARY	55.40	55.40
1	FRONT BUMPER LOGO EMBLEM BASE	NOT NECESSARY	85.40	-
1	FRONT BUMPER LOWER CENTER GRILLE	BROKEN	80.30	80.30
2	FRONT BUMPER FOG LAMP COVER LH/RH @ \$105.20	O/S BROKEN	210.40	105.20
2	FRONT BUMPER SIDE RETAINER LH/RH @ \$70.10	BROKEN	140.20	140.20
1	FRONT BUMPER TOP RETAINER	CRUSHED	115.90	115.90
1	FRONT BUMPER REINFORCEMENT	DENTED	382.80	382.80
2	FRONT BUMPER REINFORCEMENT BRACKET LH/RH @ \$202.70	O/S BENT	405.40	202.70
2	FRONT BUMPER REINFORCEMENT EXTENSION PANEL LH/RH @ \$75.60	O/S BENT	151.20	75.60
2	FRONT FENDER LH/RH @ \$559.50	TO REPAIR SEE LABOUR	1,119.00	-
2	FRONT FENDER VVT-I EMBLEM LH/RH @ \$30.40	O/S NECESSARY	60.80	30.40
2	FRONT FENDER INNER SHIELD LH/RH @ \$168.30	NOT NECESSARY	336.60	-
2	FRONT FENDER INNER SHIELD VERTICAL LH/RH @ \$222.20	NOT NECESSARY	444.40	-
1	FRONT SUPPORT PANEL	BENT	925.90	345.00
1	AIR DUCT	NOT NECESSARY	70.70	-
1	WASHER TANK	CRUSHED	120.60	120.60
1	AIRCON CONDENSER	DENTED	1,155.50	1,155.50

Report Ref No. CS/INC20002802/Etf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	AIRCON CONDENSER AIR GUIDE UPPER LH/RH @\$40.40	O/S CRUSHED	80.80	40.40
2	AIRCON CONDENSER AIR GUIDE BOTTOM LH/RH @\$85.30	O/S CRUSHED	170.60	85.30
1	AIRCON CONDENSER AIR GUIDE RH	BROKEN	85.20	85.20
1	AIRCON OUTSIDE TEMPERATURE SENSOR	NOT NECESSARY	255.10	-
1	RADIATOR	NOT NECESSARY	1,819.90	-
1	RADIATOR FAN COWLING	NOT NECESSARY	240.80	-
1	RADIATOR FAN MOTOR	NOT NECESSARY	120.70	-
1	RADIATOR FAN BLADE	NOT NECESSARY	195.60	-
2	ENGINE LOWER UNDER COVER LH/RH @\$158.90	NOT NECESSARY	317.80	-
	LESS 25% DISCOUNT		-4,965.62	-2,707.99
			14,896.85	8,123.97
	<u>SPECIAL NETT ITEMS</u>			
1	SET BOOT LID OUTER GARNISH CLIPS (SN)	NECESSARY	40.00	10.00
1	SET REAR BOOT LID NUMBER PLATE WITH GARNISH (SN)	NOT NECESSARY	95.00	-
2	REAR TAILLAMP INNER PANEL SEALANT LH/RH @\$50.00 (SN)	NECESSARY	100.00	30.00
2	REAR TAILLAMP CLIPS SET LH/RH @\$40.00 (SN)	NECESSARY	80.00	20.00
2	REAR TAILLAMP BRAKE BULB LH/RH @\$15.00 (SN)	NOT NECESSARY	30.00	-
2	REAR TAILLAMP SIGNAL BULB LH/RH @\$15.00 (SN)	NOT NECESSARY	30.00	-
2	REAR TAILLAMP REVERSE BULB LH/RH @\$15.00 (SN)	NOT NECESSARY	30.00	-
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	65.00	30.00
1	REAR END PANEL SEALANT (SN)	NECESSARY	60.00	30.00
1	SET REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NECESSARY	40.00	10.00
1	SPARE TYRE PANEL SEALANT (SN)	NECESSARY	150.00	30.00
1	SPARE TYRE PANEL INSULATOR MAT (SN)	NOT NECESSARY	380.00	-
1	SPARE TYRE PANEL INNER TOP JACKING TOOL (SN)	NOT NECESSARY	180.00	-
1	SPARE TYRE PANEL INNER TOP BRAKE SOWN (SN)	NOT NECESSARY	150.00	-
1	REAR FENDER SEALANT RH (SN)	NECESSARY	120.00	20.00
1	REAR FENDER INSULATOR MAT RH (SN)	NECESSARY	180.00	30.00
2	REAR FENDER INNER UPHOLSTERY TRIM CLIPS SET LH/RH @\$60.00 (SN)	NECESSARY	120.00	30.00

Report Ref No. CS/INC20002802/Etf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR WINDSCREEN INNER GARNISH CLIPS SET LH/RH @\$40.00 (SN)	NOT NECESSARY	80.00	-
1	SET REAR WINDSCREEN SEALANT WITH PRIMER (SN)	NECESSARY	100.00	40.00
1	REAR EXHAUST SILENCER BOX (SN)	DENTED	1,800.00	600.00
1	REAR SUB CHASSIS FRAME SEALANT RH (SN)	NOT NECESSARY	60.00	-
2	FRONT HEADLAMP CLIPS SET LH/RH @\$40.00 (SN)	NECESSARY (1 PC ONLY)	80.00	10.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	65.00	30.00
1	SET FRONT BUMPER LED LAMP (SN)	BROKEN	450.00	220.00
2	FRONT FENDER INNER SHIELD CLIPS SET LH/RH @\$60.00 (SN)	NOT NECESSARY	120.00	-
1	FRONT SUPPORT PANEL SEALANT (SN)	NECESSARY	80.00	30.00
2	AIRCON CONDENSER AIR GUIDE TOP CLIPS SET LH/RH @\$40.00 (SN)	NOT NECESSARY	80.00	-
2	AIRCON CONDENSER AIR GUIDE BOTTOM CLIPS SET LH/RH @\$40.00 (SN)	NOT NECESSARY	80.00	-
1	AIRCON CONDENSER AIR GUIDE CLIPS SET RH (SN)	NOT NECESSARY	40.00	-
1	RADIATOR COOLANT (SN)	NOT NECESSARY	80.00	-
			5,245.00	1,370.00
	LABOUR			
	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION. INCLUSIVE OF THE REPAIR OF REAR BOOT LID HINGES LH/RH.		2,200.00	1,500.00
	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA.		1,800.00	1,100.00
	TO APPLY ANTI-RUST & TUFF KOTE.		200.00	50.00
	TO PERFORM LIGHTING & WIRING CHECK.		80.00	30.00
	TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION.	NOT NECESSARY	280.00	-
	TO DISMANTLE & REINSTALL REAR PETROL TANK FOR FACILITATE REPAIR.	NOT NECESSARY	250.00	-
	TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM WITH WATER LEAK TEST.		150.00	120.00
	TO PERFORM TRANSFER REAR BOOT LID MECHANISM & REALIGN BACK TO MANUFACTURING SPECIFICATION.		120.00	50.00
	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING.		80.00	30.00

Report Ref No. CS/INC20002802/Etf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE & REPLACED REAR EXHAUST SILENCER BOX WITH EXHAUST MID PIPE.		280.00	80.00
	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR.		280.00	80.00
	TOWING SERVICE ACCIDENT SCENE TOW TO WORKSHOP.		120.00	60.00
	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION.INCLUSIVE OF THE REPAIR OF FRONT FENDER LH/RH.		1,600.00	800.00
	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA.		1,400.00	700.00
	TO APPLY ANTI-RUST & TUFF KOTE.		175.00	30.00
	TO PERFORM LIGHTING & WIRING CHECK.	NOT NECESSARY	80.00	-
	TO DISMANTLE & REINSTALL AIRCON CONDENSOR WITH REFILL AIRCON GAS.		120.00	120.00
	TO DISMANTLE & REINSTALL RADIATOR WITH REFILL RADIATOR COOLANT & HIGH PRESSURE TEST.		120.00	50.00
	TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT.	NOT NECESSARY	100.00	-
	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION.	NOT NECESSARY	80.00	-
			9,515.00	4,800.00
GRAND TOTAL			29,656.85	14,293.97
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				11,450.00

Report Ref No. CS/INC20002802/Etf3e2

CHEN TSUE YEE

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MinstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.