

Speed Auto Works
(Co Reg. No. 5321801E)
Blk 90 Bedok North Street 4
#13-1537 Singapore 460090
Tel: 6789 5155 Fax : 6783 5155

TO	: AXA	DATE	: 17-Feb-20
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SKB7855M
ADDRESS	:	MODEL	: TOYOTA ALTIS
TEL. NO.	:	CHASSIS NO	:
OWNER'S INSURANCE	:		
POLICY NO.	:		
<u>ACCIDENT DETAILS</u>	DATE :		
	TIME :		
THIRD PARTY REQUESTOR / CONTACT : XIONG 8121 0478			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER ✓ <i>CRH</i>	1	\$654.00	\$ 654.00
2	REAR BUMPER REFLECTOR <i>R/H ✓ CRH</i>	1	\$76.40	\$ 76.40
3	REAR BUMPER RETAINER (FRONT) <i>R/H ✓ Vm</i>	1	\$64.20	\$ 64.20
4	REAR BUMPER SIDE RETAINER (BLACK) <i>Side R/H ✓ Vm</i>	1	\$35.00	\$ 35.00
5	REAR BUMPER BRACKET ✓ <i>BT</i>	1	\$78.00	\$ 78.00
6	REAR BUMPER SPONGE ✓ <i>mis 7 cone</i>	1	\$169.40	\$ 169.40
7	REAR BUMPER PROTECTOR BAR <i>7 cone</i>	1	\$124.20	\$ 124.20
8	BOOTLID X (R)	1	\$689.00	\$ 689.00
9	BOOTLID REFLECTOR X (SVC)	2	\$314.00	\$ 628.00
10	BOOTLID REFLECTOR GARNISH (INNER) X (SVC)	2	\$39.20	\$ 78.40
11	BOOT LID HINGE X (R)	2	\$127.60	\$ 255.20
12	BOOTLID MOULDING CHROME X (SVC)	1	\$184.40	\$ 184.40
13	BOOTLID TOP LOCK X (SVC)	1	\$158.20	\$ 158.20
14	BOOTLID LOWER LOCK X (SVC)	1	\$24.10	\$ 24.10
15	BOOTLID WEATHERSTRIP ✓ <i>CRH</i>	1	\$165.90	\$ 165.90

410.80 ✓

✓

✓

✓

46.80 ✓

163.80 ✓

137.80 ✓

16	BOOTLID LOGO ✓ <i>mm</i>	1	\$52.60	\$ 52.60	✓
17	BOOTLID EMBLEM '1.8' ✓ <i>mm</i>	1	\$46.40	\$ 46.40	✓
18	BOOTLID EMBLEM 'COROLLA' ✓ <i>mm</i>	1	\$65.30	\$ 65.30	✓
19	BOOTLID EMBLEM 'ALTIS' ✓ <i>mm</i>	1	\$59.50	\$ 59.50	✓
20	BOOTLID EMBLEM 'VVTI' ✓ <i>mm</i>	1	\$49.20	\$ 49.20	✓
21	BOOTLID EMBLEM 'DUAL' ✓ <i>mm</i>	1	\$41.00	\$ 41.00	271.80 ✓
22	TAILLAMP R/L ✓ <i>CRA</i>	1	\$398.40	\$ 398.40	250.90 ✓
23	TAILLAMP LOWER BARCKET ✓ <i>CRA R/L</i>	1	\$67.20	\$ 67.20	✓
24	REAR FENDER RH X (R)	1	\$1,045.00	\$ 1,045.00	
25	REAR FENDER INNER COWLING X (SVC)	1	\$194.60	\$ 194.60	
26	REAR FENDER INNER TRIM X (SVC)	1	\$415.00	\$ 415.00	
27	AIR VANT X (SVC)	1	\$112.00	\$ 112.00	
28	REAR END PANEL ✓ <i>BT</i>	1	\$548.00	\$ 548.00	430.80 ✓
29	REAR END PANEL TOP GARNISH ✓ <i>CRA</i>	1	\$178.50	\$ 178.50	✓
30	REAR FLOOR PANEL X (R)	1	\$1,398.40	\$ 1,398.40	✓
31	REAR FLOOR PANEL TOP BOARD ✓ <i>CRA</i>	1	\$119.20	\$ 119.20	✓
32	REAR SPRE TYRE BOLT X (SVC)	1	\$59.00	\$ 59.00	
33	REAR EXHAUST PIPE ✓ <i>BT</i>	1	\$595.40	\$ 595.40	410.80 ✓
34	REAR EXHAUST INSULATOR X (SVC)	1	\$99.60	\$ 99.60	
35	REAR EXHAUST MOUNTING X (SVC)	2	\$58.20	\$ 116.40	

TOTAL PRICE \$ 9,045.10
 LESS 25% \$ 2,261.28
 SUB TOTAL PRICE \$ 6,783.83

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR NUMBER PLATE X (N.C) BT	1	\$ 50.00	\$ 50.00	
2	REAR BUMPER CLIPS ✓ <i>mm</i>	10	\$ 6.50	\$ 65.00	25 ✓
3	BOOT LID INSULATOR CLIP ✓ <i>mm</i>	<i>P18</i>	\$ 6.50	\$ 65.00	16 ✓
4	TAILLAMP CLIPS R/L ✓ <i>mm</i>	<i>24</i>	\$ 8.00	\$ 32.00	6 ✓
5	REAR FENDER COWLING CLIPS NOT nec	12	\$ 6.50	\$ 78.00	
6	REAR FENDER INNER TRIMD CLIPS R/L ✓ <i>mm</i>	<i>P12</i>	\$ 6.50	\$ 78.00	20 ✓
7	REAR END PANEL TOP GARNISH CLIPS ✓ <i>mm</i>	6	\$ 6.50	\$ 39.00	18 ✓
8	REAR END PANEL INSULATION SEAL ✓ <i>mm</i>	1	\$ 120.00	\$ 120.00	20 ✓
9	REAR FLOOR PANEL INSULATION SEAL X (SVC)	1	\$ 150.00	\$ 150.00	
11	REVERSE SENSOR ✓ <i>short</i>	1	\$ 220.00	\$ 220.00	200 ✓

TOTAL \$ 897.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	✓	\$1,400.00	700	
2	TO SPRAY PAINT AFFECTED AREA	✓	\$1,200.00	600	
3	TUFF COAT	X	\$180.00		
4	WIRING CHECK	✓	\$80.00	36	
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	✓	\$150.00	40	
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	✓	\$80.00	20	
7	REAR CHASSIS ALIGNMENT	X	\$250.00		
8	TRANSFER BOOTLID MECHANISM	X	\$60.00		
9	CONDUCT WATER LEAKAGE TEST	✓	\$100.00	20	
10	REMOVE AND REFIX REAR EXHAUST PIPE	✓	\$150.00	40	

TOTAL

\$3,650.00

TOTAL PARTS COST : \$ 7,680.83
TOTAL LABOUR COST : \$ 3,650.00
TOTAL REPAIR COST : \$ 11,330.83

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAYS :
RE-SURVEY :

PART BY PART OR LUMP SUM :

DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

L/S repair
with preparation
resurvey after paint
12/2/20 6:10pm
Hendrick 6 day
853/1885

resurvey taken 12/2/20
1:00pm
Hendrick

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Parts 2693
Parts less 25%
2019.75
Spa net 305
labour 1450
3774.75
L/s less 20%
3019.80
total
L/s A+ \$3000.00