

⏮ Reply all ⏵ Delete 🗑 Junk Block ...

Re: SMJ 6682K FINALIZED CLOSE CASE

HA

Hock Ann (LKK Auto)

Tue 4/7/2020 3:02 PM

Speed auto works <speedauto90@gmail.com>; Cecilia Chong (LKK Auto); Admin A ✉



Dear susan,

Good day, o.k will be process base on finalized total amount COR \$ 5650 L/SUMP REPAIR and DOR 7 days close.

Noted : All finalized document > LOA ,LOD,DV,LTA need direct send to lkk claim dept in-charge person handler (CECILIACHONG@LKKAUTO.COM)

Thanks.

Best Regards,

Hock Ann | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6741 3061 | Email: HockAnn@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Speed auto works <speedauto90@gmail.com>

Sent: Thursday, April 2, 2020 10:53 AM

To: Hock Ann (LKK Auto) <HockAnn@lkkauto.com>

Cc: Cecilia Chong (LKK Auto) <CeciliaChong@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: Re: SMJ 6682K FINALIZED

Dear Hock Ann,

Thanks for your mail.

We confirmed accept repair cost S\$5,650.00-7 days

Best Regards,

Susan

Speed Auto Works

Phone: 6842-2035 | email: speedauto90@gmail.com | fax: 6783-5155
8 Kaki Bukit Ave 4 #08-46 Premier @ Kaki Bukit | S(415875)

Speed Auto Works
(Co Reg. No. 5321801E)
Blk 90 Bedok North Street 4
#13-1537 Singapore 460090
Tel: 6789 5155 Fax: 6783 5155

TO	: AXA	DATE	19-Feb-20
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	T/P CLAIM
ESTIMATE REPORT :			
<u>OWNER'S PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO	: SMJ6682K
ADDRESS	:	MODEL	: HONDA VEZEL
TEL. NO.	:	CHASSIS NO	:
<u>ACCIDENT DETAILS</u>		DATE	:
		TIME	:
THIRD PARTY REQUESTOR / CONTACT : DAUD/9391482			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAILGATE ✓ <i>AT</i>	1	\$ 1,542.00	\$ 1,542.00
2	TAILGATE OUTER GARNISH X (SVC)	1	\$ 421.00	\$ 421.00
3	TAILGATE REFLECTOR <i>length 1/4 only ✓ CNA</i>	12	\$ 421.10	\$ 5,053.20
4	TAILGATE INNER TRIM ✓ <i>CNA</i>	1	\$ 358.00	\$ 358.00
5	TAILGATE GLASS MOULDING ✓ <i>me</i>	14	\$ 168.00	\$ 2,352.00
6	TAILGATE INNER HANDLE ✓ <i>mis</i>	1	\$ 68.50	\$ 68.50
7	TAILGATE LOCK ✓ <i>me</i>	1	\$ 224.00	\$ 224.00
8	TAILGATE LOWER LOCK X (SVC)	1	\$ 24.00	\$ 24.00
9	TAILGATE WEATHER STRIP ✓ <i>CNA</i>	1	\$ 154.00	\$ 154.00
10	TAILGATE WIPER MOTOR X (SVC)	1	\$ 541.00	\$ 541.00
11	TAILGATE LOGO ✓ <i>me</i>	1	\$ 84.00	\$ 84.00
12	TAILGATE EMBLEM 'VEZEL' ✓ <i>me</i>	1	\$ 56.00	\$ 56.00
13	TAILGATE STOPPER X (SVC)	2	\$ 18.00	\$ 36.00
14	TAILGATE DETECTOR (INNER) ✓ <i>CNA</i>	1	\$ 321.00	\$ 321.00
15	TAILGATE BUZZER ✓ <i>CNA</i>	1	\$ 125.00	\$ 125.00
16	TAILLAMP X (SVC)	2	\$ 460.00	\$ 920.00
17	REAR BUMPER ✓ <i>me</i>	1	\$ 689.00	\$ 689.00
18	REAR BUMPER SIDE UPPER ✓ <i>me 4/4 only</i>	12	\$ 450.00	\$ 5,400.00

1100.90 ✓

310.20 ✓

245.80 ✓

120.30 ✓

37.50 ✓

151.80 ✓

✓

43.50 ✓

33.50 ✓

145.80 ✓

105.30 ✓

506.80 ✓

300.30 ✓

19	REAR BUMPER SIDE RETAINER	HH only ✓ LRA	1/2	\$ 55.00	\$ 110.00	49.60 ✓
20	REAR BUMPER REFLECTOR	HH only ✓ LRA	1/2	\$ 45.00	\$ 90.00	45 ✓
21	REAR FENDER INNER COWLING	HH only ✓ LRA	1/2	\$ 187.00	\$ 374.00	127.80 ✓
22	REAR WHEEL ARCH GARNISH	HH only ✓ LRA	1/2	\$ 312.00	\$ 624.00	150.20 ✓
23	REAR FENDER INNER TRIM	HH only ✓ LRA	1/2	\$ 548.00	\$ 1,096.00	309.30 ✓
24	REAR END PANEL	✓ BT	1	\$ 630.00	\$ 630.00	430.80 ✓
25	REAR END PANEL TOP GARNISH	✓ LRA	1	\$ 189.00	\$ 189.00	110.80 ✓
26	REAR FLOOR PANEL	✓ LRA	1	\$ 845.00	\$ 845.00	670.80 ✓
27	REAR FLOOR PANEL TOP BOARD	✓ LRA	1	\$ 300.00	\$ 300.00	220.80 ✓
28	REAR FLOOR PANEL UNDER COVER	✓ LRA	1	\$ 254.00	\$ 254.00	160.30 ✓
29	REAR FLOOR PANEL TOOLS BOX SPONGE	✓ LRA	1	\$ 258.00	\$ 258.00	140.80 ✓
30	REAR EXHAUST PIPE	X (SVC)	1	\$ 1,221.00	\$ 1,221.00	
31	REAR EXHAUST INSULATOR	X (SVC)	1	\$ 154.00	\$ 154.00	

TOTAL PRICE \$14,122.70

LESS 20% \$2,824.54

SUB TOTAL PRICE \$11,298.16

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR BUMPER CLIPS	10	\$ 6.50	\$ 65.00	25 ✓
2	REAR BUMPER SIDE UPPER CLIP	3/6	\$ 6.50	\$ 39.00	9 ✓
3	TAILGATE SEALANT	1	\$ 80.00	\$ 80.00	
4	TAILGATE INNER TRIM CLIP	12	\$ 6.50	\$ 78.00	20 ✓
5	TAILGATE WINDSCREEN SEALANT	1	\$ 80.00	\$ 80.00	40 ✓
6	TAILGATE WINDSCREEN INNER SEAL	1	\$ 50.00	\$ 50.00	30 ✓
7	TAILLAMP CLIP	2/4	\$ 8.00	\$ 32.00	6 ✓
8	REAR FENDER INNER COWLING CLIP	15	\$ 6.50	\$ 97.50	8 ✓
9	REAR FENDER INNER TRIM CLIPS	12	\$ 6.50	\$ 78.00	15 ✓
10	REAR WHEEL ARCH GARNISH CLIP	10	\$ 6.50	\$ 65.00	15 ✓
11	REAR END PANEL TOP GARNISH CLIPS	4	\$ 8.50	\$ 34.00	8 ✓
12	REAR END PANEL INSULATION SEAL	1	\$ 150.00	\$ 150.00	30 ✓
13	REAR FLOOR PANEL INSULATION SEAL	1	\$ 150.00	\$ 150.00	
14	REVERSE SENSOR	1	\$ 220.00	\$ 220.00	200 ✓
15	REVERSE CAMERA	1	\$ 450.00	\$ 450.00	

TOTAL \$1,668.50

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST	APPROVED
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$1,400.00	1700 ✓	

2	TO SPRAY PAINT AFFECTED AREA	✓	\$1,500.00	200 ✓
3	WIRING CHECK	✓	\$80.00	30 ✓
4	REMOVE AND REFIX REAR WINDSCREEN	✓	\$150.00	100 ✓
5	CONDUCT LEAKAGE TEST ON TAILGATE	✓	\$80.00	30 ✓
6	TUFF COTE	X	\$250.00	
7	REMOVE AND REFIX EXHAUST TAILPIPE	X	\$250.00	
8	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY TO FACILITATE REPAIR	✓	\$350.00	60 ✓
9	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	✓	\$250.00	20 ✓

TOTAL

\$4,310.00

ESTIMATE REPORT

TOTAL PARTS COST : \$12,966.66
TOTAL LABOUR COST : \$4,310.00
TOTAL REPAIR COST : \$17,276.66

APPROVED DETAILS

EXCESS :
NO. OF WORKING DAY :
RE-SURVEY :
PART BY PART OR LUMP SUM :
DATE & TIME OF SURVEY :
SURVEYED BY :
CONTACT NUMBER :
FAX NUMBER :

parts 5671.90

parts less 20%

4537.52

spe mtl 406

labour 2140

7083.52

4/5 less 20%

5666.81

total 4/5 At \$5650 #

Resurvey taken
H. B. 19/2/22
3:35pm

2/5 repair
initial problem
Kanger of car part
7 day (1/1/22)

Hadi B. 85211893
Hadi B. 19/2/22 2:50pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: