



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

Lec / Mr Achen

TP FWD.

Xiao Tony

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

ESTIMATE

Repair Code : CLM16051 (FWD)

Date in : 14/02/2020

Vehicle Num. : SLR4214L

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31253371/LEB5953389

Contact : 66550005-GRAB 90050409

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>replaced</i>	1	762.70	762.70 ✓
REAR BUMPER LOWER COVER <i>replaced</i>	1	250.00	250.00 ✓
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	23.00	46.00 ✓
REAR END PANEL <i>replaced</i>	1	415.60	415.60 ✓
REAR END PANEL BUZZLE SENSOR <i>could</i>	1	85.20	85.20 ✓
REAR END PANEL INNER TOP GARNISH <i>replaced</i>	1	98.00	98.00 ✓
REAR EXHAUST CHROME TAIL PIPE <i>Best</i>	1	135.00	135.00 ✓
REAR EXHAUST RUBBER MOUNTING <i>3 pieces 14mm</i>	2	16.50	33.00 +
REAR EXHAUST SILENCER BOX <i>Best</i>	1	517.70	517.70 ✓
REAR EXHAUST SILENCER BOX GASKET <i>new</i>	1	48.30	48.30 +
REAR FLOOR PANEL COMPARTMENT TRAY GARNISH <i>replaced</i>	1	485.30	485.30 ✓
REAR FLOOR PANEL INNER TOP BOARD COVER <i>replaced</i>	1	430.30	430.30 ✓
REAR RH BUMPER REFLECTOR <i>could</i>	1	141.10	141.10 ✓
REAR RH BUMPER SIDE <i>replaced</i>	1	195.00	195.00 ✓
REAR RH FENDER ARCH GARNISH <i>new</i>	1	195.00	195.00 +
REAR RH FENDER INNER TRIM GARNISH <i>new</i>	1	295.00	295.00 +
REAR RH TAILGATE REFLECTOR <i>could</i>	1	413.20	413.20 ✓
REAR RH TAILGATE REFLECTOR BACK RUBBER GASKET <i>new</i>	1	38.50	38.50 ✓

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005-GRAB 90050409

ESTIMATE

Repair Code : CLM16051

Date in : 14/02/2020

Vehicle Num. : SLR4214L

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31253371/LEB5953389

REAR RH TAILLAMP <i>crack</i>	1	474.60	474.60	✓
REAR TAILGATE <i>Dented</i>	1	953.30	953.30	✓
REAR TAILGATE 'HYBRID' EMBLEM <i>3 pc</i>	1	75.80	75.80	✓
REAR TAILGATE 'VEZEL' EMBLEM	1	56.20	56.20	✓
REAR TAILGATE INNER PULL GARNISH <i>new</i>	1	27.50	27.50	+
REAR TAILGATE INNER TRIM GARNISH <i>Del d</i>	1	153.40	153.40	✓
REAR TAILGATE MECHANISM LOCK <i>new</i>	1	180.00	180.00	✓
REAR TAILGATE MECHANISM LOCK STRIKER <i>new</i>	1	27.50	27.50	+
REAR TAILGATE OUTER GARNISH <i>new</i>	1	220.00	220.00	+
REAR TAILGATE OUTER GARNISH 'H' LOGO EMBLEM <i>new</i>	1	25.00	25.00	+
REAR TAILGATE RUBBER GUIDE STOPPER L/R <i>new</i>	2	18.50	37.00	+
REAR TAILGATE WEATHER STRIP <i>cut</i>	1	96.80	96.80	✓
REAR TAILGATE WINDSCREEN INNER SEAL <i>3 pc</i>	2	50.00	100.00	✓
REAR TAILGATE WINDSCREEN MOULDING	2	50.00	100.00	✓
Subtotal before discount			6,612.00	
Percentage discount 20%			1,322.40	
Sub-total 1			5,289.60	
REAR BUMPER CLIPS - SET <i>new</i>	1	50.00	50.00	✓
			30	

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005-GRAB 90050409

ESTIMATE

Repair Code : CLM16051

Date in : 14/02/2020

Vehicle Num. : SLR4214L

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31253371/LEB5953389

REAR BUMPER SENSOR <i>Damaged</i>	1	250.00	250.00 <i>250</i>
REAR RH FENDER INNER TRIM GARNISH CLIPS - SET	1	50.00	50.00 <i>30</i>
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET	1	80.00	80.00 <i>30</i>
REAR TAILGATE WINDSCREEN SEALANT <i>see</i>	1	80.00	80.00 <i>60</i>
Subtotal before discount			510.00
Percentage discount 0%			0.00
Sub-total 2			510.00
Parts-total			5,799.60

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	60.00 ✓
To remove, reinstall tailgate windscreen	150.00 <i>120</i>
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	140.00 <i>80</i>
To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.	1,400.00 <i>800</i>
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	120.00 <i>80</i>
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	1,200.00 <i>800</i>
To apply anti-rust chemical on repaired and replaced panel.	80.00 ✓
To remove, reinstall tailgate mechanism and check for function	80.00 ✓

Labour Total 3,230.00

Parts & Labour Total 9,029.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is a computer-generated document which requires no signature.***

page 3

Adrian Lj
L/S 18/02/20

total 7398.16 06 days
L/S: S.9K ✓