



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

LONPAC INSURANCE BHD  
300 BEACH ROAD  
#17-04/07 THE CONCOURSE  
SINGAPORE 199555

INV No. AC2008178  
INV Date 08/12/2020  
Reference CC4/LPC20002813/R1ra3q2  
Code LPC2



#### PROFESSIONAL SERVICE FEE

Vehicle No. SKC 7098B  
Insured Veh. YP 2834S  
Claim No. 19/20/20/VC00/023038  
Policy No. Z/19/VC00/104525  
Accident Date 11/02/2020  
Inspection Date 17/02/2020

Description	Total
Third Party Express Settlement	400.00
<b>Subtotal</b>	<b>400.00</b>
<b>GST (7%)</b>	<b>28.00</b>
<b>Grand Total</b>	<b>428.00</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC20002813/R1ra3q2

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 08-12-2020



Code : LPC2

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	YP 2834S	<b>Veh. Inspected</b>	SKC 7098B
<b>Policy No.</b>	Z/19/VC00/104525	<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	19/20/20/VC00/023038	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	ONG LI LI	<b>Assign Date</b>	14/02/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	MITSUBISHI OUTLANDER 2.0 CVT	<b>c.c</b>	1998
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2018
<b>Chassis No.</b>	GF7W0401109	<b>Colour</b>	GREY
<b>Odometer</b>	031360	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	FAIR		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	225/55 R18	TOYO	6 mm
<b>L/H Front Tyre</b>	225/55 R18	TOYO	6 mm
<b>R/H Rear Tyre</b>	225/55 R18	TOYO	6 mm
<b>L/H Rear Tyre</b>	225/55 R18	TOYO	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.
---

### 5. General Information

<b>Accident Date</b>	11/02/2020	<b>Inspection Date</b>	17/02/2020
<b>Survey held at</b>	38 TOH GUAN ROAD EAST #42-0179		
<b>Repairer</b>	WAH HONG & CREDIT PTE LTD		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>3 Working Days</b>
-------------------------------------	-----------------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKC 7098B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BONNET	BENT	780.00	780.00
1	BONNET INSULATOR	NOT NECESSARY	120.00	-
1	BONNET HINGE LH	NOT NECESSARY	65.00	-
1	BONNET HINGE RH	NOT NECESSARY	65.00	-
1	BONNET LOCK ASSY	NOT NECESSARY	70.00	-
1	HEADLAMP LH	SERVICEABLE	1,380.00	-
1	FRONT BUMPER	SERVICEABLE	960.00	-
1	FRONT CENTER CHROME GRILLE	CRACKED	390.00	390.00
1	FRONT OUTLANDER EMBLEM	NECESSARY	90.00	90.00
1	FRONT MITSUBISHI EMBLEM	NECESSARY	85.00	85.00
	LESS 10% DISCOUNT		-400.50	-134.50
			3,604.50	1,210.50
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT BUMPER CLIPS (SN)	NOT NECESSARY	35.00	-
1	BONNET INSULATOR CLIPS (SN)	NECESSARY	25.00	25.00
1	FRONT SENSOR (SN)	NOT NECESSARY	280.00	-
			340.00	25.00
	<b><u>LABOUR</u></b>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS.		1,000.00	300.00
	TO SUPPLY PAINT MATERIALS ,EXPANDABLE ITEMS & PUTTY, RESPRAY PAINT ON PARTS REPLACED & REPAIRED.		800.00	200.00
	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREA.		150.00	40.00
			1,950.00	540.00
	<b>GRAND TOTAL</b>		<b>5,894.50</b>	<b>1,775.50</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>1,400.00</b>

Report Ref No. CC4/LPC20002813/R1ra3q2



Report Ref No. CC4/LPC20002813/R1ra3q2

A handwritten signature in black ink, appearing to read 'MRB'.

**MOHAMMED RASUL BIN MOHD YUNUS**

**Automotive Assessor**

A handwritten signature in black ink, appearing to read 'Ho Leong Chuan'.

**HO LEONG CHUAN**

**Automotive Assessor**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

**No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKC 7098B

INSPECTION







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKC 7098B

RE-INSPECTION

