

Finalised Invoice

Jiahe



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Page No. 1

Vehicle No. SKC7098B MITSUBISHI OUTLANDER 2.0A / 2018 / 6F 7W 0401109

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Bonnet H ✓		780.00	
1	Bonnet insulator X 77		120.00	X
1	Bonnet hinge LH X 77		65.00	X
1	Bonnet hinge RH X 77		65.00	X
1	Bonnet lock assy X 77		70.00	X
1	Headlamp LH X 77		1380.00	X
1	Front bumper X 77		960.00	X
1	Front center chrome grille CA ✓		390.00	
1	Front OUTLANDER emblem A ✓		90.00	
1	Front MITSUBISHI emblem A ✓		85.00	
		10% Plus 15%	4005.00	
			400.50	
			4405.50	
SPECIAL NETT ITEMS				
1	Front bumper clips X 77		35.00	X
1	Bonnet insulator clips A ✓		25.00	
1	Front sensor X 77		280.00	X
Total Parts			4745.50	



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)
Email: motor@wahhong.sg
(199806235M)

Page No. 2

Vehicle No. SKC7098B MITSUBISHI OUTLANDER 2.0A

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
1	<u>LABOUR</u> To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	1000.00	300
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	800.00	200
4	To provide anti-rust treatment on affected area	150.00	40
Labour Total :		1950.00	
TOTAL (PARTS & LABOUR):		6695.50	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Panel

4p 90010368

3 days

4/5

17/02/2020 @ 1520

Resy after paint

1210.50

25.00

540.00

1775.50

20%

1420.40

4/5-1, 40

3 days