



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Page No. 1

Vehicle No. SKC7098B MITSUBISHI OUTLANDER 2.0A

| QTY                       | DESCRIPTION                           | CONDITION | REPAIRER'S<br>ESTIMATE(\$\$) | SURVEYOR'S<br>ADJUSTMENT |  |
|---------------------------|---------------------------------------|-----------|------------------------------|--------------------------|--|
| <u>PARTS (LIST ITEMS)</u> |                                       |           |                              |                          |  |
| 1                         | Bonnet <i>h/</i>                      | Plus 15%  | 780.00                       |                          |  |
| 1                         | Bonnet insulator <i>X</i>             |           | 120.00                       |                          |  |
| 1                         | Bonnet hinge LH <i>X</i>              |           | 65.00                        |                          |  |
| 1                         | Bonnet hinge RH <i>X</i>              |           | 65.00                        |                          |  |
| 1                         | Bonnet lock assy <i>X</i>             |           | 70.00                        |                          |  |
| 1                         | Headlamp LH <i>?</i>                  |           | 1380.00                      |                          |  |
| 1                         | Front bumper <i>X</i>                 |           | 960.00                       |                          |  |
| 1                         | Front center chrome grille <i>ch/</i> |           | 390.00                       |                          |  |
| 1                         | Front OUTLANDER emblem <i>ne/</i>     |           | 90.00                        |                          |  |
| 1                         | Front MITSUBISHI emblem <i>ne/</i>    |           | 85.00                        |                          |  |
|                           |                                       |           |                              | 4005.00                  |  |
|                           |                                       |           |                              | 400.50                   |  |
|                           |                                       |           |                              | 4405.50                  |  |
| <u>SPECIAL NETT ITEMS</u> |                                       |           |                              |                          |  |
| 1                         | Front bumper clips <i>X</i>           |           | 35.00                        |                          |  |
| 1                         | Bonnet insulator clips <i>ne/</i>     |           | 25.00                        |                          |  |
| 1                         | Front sensor <i>X</i>                 |           | 280.00                       |                          |  |
| Total Parts               |                                       |           | 4745.50                      |                          |  |



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Page No. 2

Vehicle No. SKC7098B MITSUBISHI OUTLANDER 2.0A

| S/N                     | DESCRIPTION                                                                                                                                                         | REPAIRER'S<br>ESTIMATE (S\$) | SURVEYOR'S<br>ADJUSTMENT |
|-------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------|--------------------------|
| 1                       | <b>LABOUR</b><br>To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components. | <del>1000.00</del>           | 300                      |
| 2                       | To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired                                                                     | <del>800.00</del>            | 200                      |
| 4                       | To provide anti-rust treatment on affected area                                                                                                                     | <del>150.00</del>            | 40                       |
| Labour Total :          |                                                                                                                                                                     | 1950.00                      |                          |
| TOTAL (PARTS & LABOUR): |                                                                                                                                                                     | 6695.50                      |                          |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rame

4p 9001068

3 days

4/3

17/02/2020 @ 1520

Resy after paint