



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Page No. 1

Vehicle No. SKC7098B MITSUBISHI OUTLANDER 2.0A

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)		SURVEYOR'S ADJUSTMENT	
	<u>PARTS (LIST ITEMS)</u>					
1	Bonnet			780.00		
1	Bonnet insulator			120.00		
1	Bonnet hinge LH			65.00		
1	Bonnet hinge RH			65.00		
1	Bonnet lock assy			70.00		
1	Headlamp LH			1380.00		
1	Front bumper			960.00		
1	Front center chrome grille			390.00		
1	Front OUTLANDER emblem			90.00		
1	Front MITSUBISHI emblem			85.00		
		Plus 15%		4005.00		
				400.50		
				4405.50		
	<u>SPECIAL NETT ITEMS</u>					
1	Front bumper clips			35.00		
1	Bonnet insulator clips			25.00		
1	Front sensor			280.00		
		Total Parts		4745.50		



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Page No. 2

Vehicle No. SKC7098B MITSUBISHI OUTLANDER 2.0A

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	1000.00	
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	800.00	
4	To provide anti-rust treatment on affected area	150.00	
	Labour Total :	1950.00	
	TOTAL (PARTS & LABOUR):	6695.50	