

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd

Date 17/2/2020

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO.SLJ1346B

CHASSIS NO : GP71043818

MAKE / MODEL : Honda Shuttle Hybrid 1.5 Auto

DATE OF ACCIDENT : 14/02/2020

YOUR INSURED VEHICLE NUMBER : SMJ8342D

MILEAGE :168282 km

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	F/L fender / PD	1PC	\$ 1,100.00	\$ 1,100.00
2	F/L fender liner / CR4	1PC	\$ 240.00	\$ 240.00
3	F/L fender Hybrid emblem / Npc	1PC	\$ 88.60	\$ 88.60
4	Front bumper X R	1PC	\$ 1,850.00	\$ 1,850.00
5	F/L door / PD		\$ 1,600.00	\$ 1,600.00
6	R/L door / PD		\$ 1,600.00	\$ 1,600.00
LIST TOTAL S\$:			\$	3,278.60
20.00% DISCOUNT S\$:			\$	655.72
			\$	2,622.88

SPECIAL NETT

1	F/L fender clips	1 SET	\$	100.00
2	F/L wheel cap MIS \$120/-		\$	100.00
Special Nett Total S\$:			\$	100.00

LABOUR CHARGES

1	To labour charge for removing out F/L fender, F/L door, R/L door, R/L fender and front bumper out to facilitate replacement of damaged parts	\$	1,000.00	800
2	To respray F/L fender, F/L door, R/L door, LH side sill panel and R/L fender	\$	1,200.00	1,000

LABOUR TOTAL S\$:	\$	2,200.00
TOTAL S\$:	\$	4,922.88
7% GST	\$	344.60
GRAND TOTAL S\$:	\$	5,267.48

Repair dy - 5 days

Lump Sum Repair
After paint photo

Sum Pm (LHK)

17/02/2020

TP without prejudice

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: