

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms AIG Asia Pacific Insurance Pte Ltd
Date 17/2/2020
Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLJ1346B
CHASSIS NO : GP71043818
MAKE / MODEL : Honda Shuttle Hybrid 1.5 Auto
DATE OF ACCIDENT : 14/02/2020
YOUR INSURED VEHICLE NUMBER : SMJ8342D
MILEAGE :168282 km

<u>PARTS DESCRIPTION</u>		<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	F/L fender / PD	1PC	\$ 1,100.00	\$ 1,100.00 /
2	F/L fender liner / CRU	1PC	\$ 240.00	\$ 240.00 / 110
3	F/L fender Hybrid emblem / Nec	1PC	\$ 88.60	\$ 88.60 /
4	Front bumper X R	1PC	\$ 1,850.00	\$ 1,850.00 X
5	F/L door / PD		\$ 1,600.00	\$ 1,600.00 1,250
6	R/L door / PD		\$ 1,600.00	\$ 1,600.00 1,250
		LIST TOTAL S\$:		\$ 3,278.60 3,798.6
		20.00% DISCOUNT S\$:		\$ 655.72 - 20%
				\$ 2,622.88 3,038.88

SPECIAL NETT

1	F/L fender clips / Nec			
2	F/L wheel Cap MIS \$120/	1 SET	\$ 100.00	X 20
			Special Nett Total S\$:	\$ 100.00 140

LABOUR CHARGES

1	To labour charge for removing out F/L fender, F/L door, R/L door, R/L fender and front bumper out to facilitate replacement of damaged parts	\$ 1,000.00	800
2	To respray F/L fender, F/L door, R/L door, LH side sill panel and R/L fender	\$ 1,200.00	1,000
LABOUR TOTAL S\$:		\$ 2,200.00	1,800
TOTAL S\$:		\$ 4,922.88	
7% GST		\$ 344.60	
GRAND TOTAL S\$:		\$ 5,267.48	

Repair dy - 5 dy

Lump Sum Repair
After paint photo

Sur Pm (Lick)

17/02/2020

TP without prejudu

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P=3,038.88

N= 140

L=1,800

4,978.88

- 20%

3,983.10

45 \$4,000

5 days