

Think One Autocare Pte Ltd  
No.18 Defu Avenue 2  
Singapore 539522

**YP400Z FUSO FEB50**

DATE 14.02.2020

No	Qty	DESCRIPTION	SPECAIL NETT	AMOUNT S\$
1	1	CARGO BOX SIDE DOOR LH	<i>XR</i>	\$ 1,200.00

**LABOUR & MISCELLANEOUS:**

1	To remove damaged parts with all necessary components/attach- ments apply hot-works where necessary repair,reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components/attachments	1,000.00 <i>150</i>
2	To spray paint replaced/repaired body parts inclusive of preparatory works and painting materials	800.00 <i>500</i>
		\$ 1,800.00

*Repair dg - 1 days*

*P/P*

*After paint photo*

*Sun Pm (Llele)*

*17/02/2020*

*TP without prejudice*

*sunpin@lkk auto.com*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: