

YAP LEE MOTOR

No 1 Kaki Bukit Avenue 6 #01-26 AutoBay @ Kaki Bukit

Singapore 417883

Tel : 6844 1555 Fax : 6844 1311

12 February 2020

REG NO. : SMS 6668 E
MAKE/MODEL : TOYOTA SIENTA

TP China.

Trale.

NSP170 7042379

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Rear windscreen moulding <i>new</i>	\$ 120.70 ✓
1	Rear tailgate <i>Dented</i>	\$ 1,602.41 ✓ 1180
2	Rear tailgate dampers <i>new</i>	\$ 482.58 ✓
1	Rear tailgate inner trim board <i>new</i>	\$ 481.94 ✓
2	Rear tailgate lamps <i>new</i>	\$ 770.40 ✓
1	Rear tailgate lock <i>Dmgd</i>	\$ 489.67 ✓ 372
1	Rear tailgate logo <i>new</i>	\$ 58.50 ✓
1	Rear tailgate rubber <i>cut</i>	\$ 291.61 ✓
1	Rear tailgate outer garnish <i>new</i>	\$ 257.30 ✓
2	Rear taillamps <i>new</i>	\$ 874.40 ✓
1	Rear end panel <i>Dented</i>	\$ 820.65 ✓ 609
1	Rear end panel inner garnish <i>Dented</i>	\$ 221.50 ✓
1	Rear smart keyless sensor <i>could</i>	\$ 189.50 ✓
1	Rear bumper <i>Dented</i>	\$ 788.70 ✓
2	Rear bumper brackets <i>new</i>	\$ 197.00 ✓
1	Rear bumper centre pad <i>cut</i>	\$ 225.00 ✓
2	Rear bumper reflectors <i>new could</i>	\$ 190.00 ✓
2	Rear bumper reflector outer garnishes <i>Not new</i>	\$ 361.00 ✓
2	Rear bumper side outer garnishes <i>Dented</i>	\$ 255.00 ✓
2	Rear bumper side retainers <i>new</i>	\$ 128.80 ✓
1	Rear bumper tow hook cover <i>new</i>	\$ 55.20 ✓
		\$ 8,861.86
	Less 25%	\$ 2,215.47
		\$ 6,646.40

SPECIAL NETT ITEMS

1	Rear windscreen sealant <i>new</i>	\$ 80.00-60
1	Rear bumper clip (1 set) <i>new</i>	\$ 50.00-30
1	Rear bumper carbon sticker <i>cut</i>	\$ 180.00-120
1	Rear reverse sensor (1 set) <i>Dmgd</i>	\$ 350.00-200
1	Rear reverse camera <i>new</i>	\$ 480.00 ✓
		\$ 1,140.00

S/N

LABOUR CHARGES

- 1 To remove, replaced damaged lamps and check up rear wiring.
- 2 To remove and refit inner garnishes.
- 3 To remove and refit rear reverse sensor and reverse camera.
- 4 To transfer rear tailgate mechanism and wiring assembly.
- 5 To remove and refit rear windscreen glass.
- 6 To apply undercoating.
- 7 Panel beating.
- 8 To re-spray painting on the affected areas.

2250

\$	80.00	30.
\$	150.00	60
\$	150.00	100
\$	120.00	80
\$	180.00	120
\$	200.00	60
\$	1,500.00	90
\$	1,400.00	90
\$	3,780.00	

GRAND TOTAL :

\$ 11,566.40

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
h/s 17/02/20.
06 Days

total: 6132.73.

h/s: 4-9K.

(4.9K)