



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2004239
INV Date 02/06/2020
Reference CC4/FCI20002819/Db3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. FBG 9782G
Insured Veh. SHB 4317E
Claim No. D20000679MFSH
Policy No. D-20094922MFSH
Accident Date 27/01/2020
Inspection Date 18/02/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20002819/Db3q2

36 ROBINSON ROAD
#16-01 CITY HOUSES SINGAPORE 068877

Date : 02-06-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 4317E	Veh. Inspected	FBG 9782G
Policy No.	D-20094922MFSH	Coverage (\$)	0.00
Claim No.	D20000679MFSH	Excess (\$)	0.00
Assign From	JOANNE YONG	Assign Date	14/02/2020

2. Vehicle Particulars & Condition

Make & Model	YAMAHA FZ 16	c.c	153
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	ME121C0DCC2020347	Colour	RED
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	110/70 R17	DUNLOP	3 mm
L/H Front Tyre			mm
R/H Rear Tyre	140/70 R17	DUNLOP	3 mm
L/H Rear Tyre			mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	27/01/2020	Inspection Date	18/02/2020
Survey held at	S9 MOTOR TRADING PTE LTD BLK 4001 ANG MO KIO INDUSTRIAL PARK 1 #01-21 SINGAPORE 569622		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FBG 9782G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	HANDLE BAR	BENT	165.00	165.00
1	SET MIRROR	BROKEN	160.00	160.00
1	BRAKE LEVER	BROKEN	75.00	75.00
1	VISOR	CUT	185.00	185.00
1	HEAD LAMP	MTG BROKEN	350.00	350.00
1	FRONT MUDGUARD	BROKEN	250.00	250.00
1	FRONT RH SIGNAL	CUT	90.00	90.00
1	SIGNAL PANEL RH	CUT	75.00	75.00
1	HEAD LAMP GUARD	CUT	195.00	195.00
1	HEAD LAMP STAY	NOT NECESSARY	210.00	-
1	FORK TUBE	BENT / MTG BROKEN	300.00	300.00
1	FRONT RIM	DISTORTED	280.00	280.00
1	FRONT RH FOOTREST	NOT NECESSARY	85.00	-
1	EXHAUST GUARD	NOT NECESSARY	135.00	-
1	FRONT BRAKE DISC	NOT NECESSARY	195.00	-
	LESS 10% DISCOUNT		-275.00	-212.50
			2,475.00	1,912.50
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	CUT	15.00	15.00
1	METER ASSEMBLY (ADDITIONAL) (SN)	CRACKED	760.00	760.00
			775.00	775.00
<u>LABOUR</u>				
	TOWING FEE.	NOT NECESSARY	40.00	-
	REMOVE & REPLACE NECESSARY PARTS,ALIGN & ETC.		250.00	150.00
	REMOVE & REPLACE FORK TUBE ,FORK OIL SEAL,FORK OIL ,FRONT RIM & BRAKE DISC.		150.00	80.00
	PUTTY & TOUCH UP PAINT WORK.		250.00	100.00
			690.00	330.00
GRAND TOTAL			3,940.00	3,017.50

Report Ref No. CC4/FCI20002819/Db3q2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,400.00
---	--	--	-----------------

Report Ref No. CC4/FCI20002819/Db3q2

A handwritten signature in black ink, appearing to be 'Ang Bryan Tani'.

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBG 9782G

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBG 9782G

RE-INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. FBG 9782G

RE-INSPECTION

