

S9 MOTOR TRADING PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 14 February 2020

To : LKK

By Fax: 6256-4315

Attn : Bryan Ang

Tel: 97237799

VEHICLE NO : FBG 9782G

Yamaha FZ16

ACCIDENT DATE: 27 January 2020

Description	Qty	Quotation \$
1 Handle Bar set <i>set</i>	1	165.00 <i>X</i> ✓
2 Mirror <i>broken</i>	1 set	160.00 ✓
3 Brake Lever <i>broken</i>	1	75.00 ✓
4 Visor <i>cut</i>	1	185.00 ✓
5 Head Lamp <i>mainly broken</i>	1	350.00 ✓
6 Front Mudguard <i>broken</i>	1	250.00 ✓
7 Front RH Signal set <i>cut</i>	1	90.00 ✓
8 Signal Panel RH <i>cut</i>	1	75.00 ✓
9 Head Lamp Guard <i>cut</i>	1	195.00 ✓
10 Head Lamp Stay <i>W</i>	1	210.00 <i>X</i>
11 Fork Tube - set <i>set</i> / <i>mainly broken</i>	1	300.00 <i>X</i> ✓
12 Front Rim set <i>distorted</i>	1	280.00 <i>X</i> ✓
13 Front RH Footrest <i>W</i>	1	85.00 <i>X</i>
14 Exhaust Guard <i>W</i>	1	135.00 <i>X</i>
15 Front Brake Disc <i>W</i>	1	195.00 <i>X</i>
Sub-Total		2,750.00
Less 10%		275.00
Sub-Total		2,475.00

LKK Auto Company's policy notice
the Repairer of the following:
• To receive before the repair work
• To receive damaged parts before repair
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modifications is allowed
• Supplementary items must be reviewed and
is subject to first approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

VEHICLE NO : FBG 9782G

Yamaha FZ16

Nett Items

- 1 Front number plate cut
- 2 Towing fee
- 3 Remove & replace necessary parts, align & etc
- 4 Remove & replace fork tube, fork oil seal, fork oil, front rim & brake disc
- 5 Putty & touch up paint work

15.00 ✓
40.00 X
~~250.00~~ + ~~120~~ 150/-
~~150.00~~ 80/-
~~250.00~~ 100/-

Sub-Total 705.00

Nett Total 3,180.00

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion.
Thank you

S9 MOTOR TRADING PTE LTD

:LG

18/02/2020 21430m

Not Actual

2/3mm

3 days
J. Yon

2 KK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: