



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

First Capital LKK Admin

MR. CHONG CHAM WENG
89 AROOZOO AVENUE
SINGAPORE 539848

Contact : 86412084

TP 1st Cap.
Vic.

ESTIMATE

Repair Code : CLM16045

Date in : 14/02/2020

Vehicle Num. : SFB7372Z

Model : HYUNDAI CM SANTA FE 2.7 A S/R

Chassis/Eng# : KMHSH81DR8U358059/G6EA8A103564

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>reld</i>	1	586.80	586.80 ✓
REAR BUMPER LOWER LID <i>reld</i>	1	161.80	161.80 ✓
REAR BUMPER SIDE RETAINER L/R <i>Rit Ang d</i>	2	37.20	74.40 <i>37.20</i>
REAR BUMPER SPONGE <i>canled</i>	1	255.10	255.10 ✓
REAR RH BALL JOINT ARM <i>Bent</i>	1	141.80	141.80 ✓
REAR RH BUMPER REFLECTOR <i>cut</i>	1	110.50	110.50 ✓
REAR RH CONTROL ARM <i>Bent</i>	1	86.00	86.00 ✓
REAR RH FENDER <i>Repair</i>	1	1927.80	1,927.80 +
REAR RH FENDER INNER SHIELD <i>tor</i>	1	97.10	97.10 ✓
REAR RH FENDER WHEEL MUDGUARD <i>cut</i>	1	61.60	61.60 ✓
REAR RH KNUCKLE ARM <i>new</i>	1	577.80	577.80 +
REAR RH KNUCKLE ARM BEARING <i>new</i>	1	395.00	395.00 ✓
REAR RH LOWER ARM <i>Bent</i>	1	369.00	369.00 ✓
REAR RH SHOCK ABSORBER <i>Bent</i>	1	276.80	276.80 ✓
REAR RH STABILIZER LINK <i>new</i>	1	68.00	68.00 +
STEP GARNISH RH <i>reld</i>	1	700.00	700.00 ✓

3278.7

2622.96

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

MR. CHONG CHAM WENG
89 AROOZOO AVENUE
SINGAPORE 539848

Contact : 86412084

ESTIMATE

Repair Code : CLM16045

Date in : 14/02/2020

Vehicle Num. : SFB7372Z

Model : HYUNDAI CM SANTA FE 2.7 A S/R

Chassis/Eng# : KMHSH81DR8U358059/G6EA8A103564

Subtotal before discount			5,889.50
Percentage discount	20%		1,177.90
Sub-total 1			4,711.60
REAR BUMPER CLIPS - SET <i>NE</i>	1	80.00	80.00 30
REAR BUMPER REVERSE SENSOR - SET <i>NE</i>	1	380.00	380.00 <i>X</i>
REAR RH FENDER INNER SHIELD CLIPS - SET <i>NE</i>	1	50.00	50.00 30
REAR RH SPORT RIM <i>lit</i>	1	800.00	800.00 500
REAR RH TYRE 235/60R18 <i>NE</i>	1	480.00	480.00 <i>X</i>
STEP GARNISH RH CLIPS - SET <i>NE</i>	1	50.00	50.00 30
Subtotal before discount			1,840.00
Percentage discount	0%		0.00
Sub-total 2			1,840.00
Parts-total			6,551.60

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

~~100.00~~ 80

To remove, reinstall fender glass

150.00 *X*

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.

~~350.00~~ 220

To road test driving, check and resetting wheel alignments system.

~~140.00~~ 80

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

~~140.00~~ 50

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

~~1,000.00~~ 600

*** This is a computer-generated document which requires no signature.***



N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

MR. CHONG CHAM WENG

89 AROOZOO AVENUE

SINGAPORE 539848

Contact : 86412084

ESTIMATE

Repair Code : CLM16045

Date in : 14/02/2020

Vehicle Num. : SFB7372Z

Model : HYUNDAI CM SANTA FE 2.7 A S/R

Chassis/Eng# : KMHSH81DR8U358059/G6EA8A103564

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	1,200.00
Parts & Labour Total	9,751.60

*** This is a computer-generated document which requires no signature.***

page 3

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
2/5 18/02/20
05 Days.

total: 4682.96

2/5: 3.7K ✓