

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLP 7960 G

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To tow and recover vehicle from scene of accident.	S/N \$	280.00	X ✓
2	To renew rhs 1/4 glass and rear windscreen.	S/N \$	600.00	✓
3	To install rear windscreen solar film.	S/N \$	400.00	✓
4	To carry out vacuum and clean up for interior and carpet.	S/N \$	480.00 300	✓
5	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, luggage compartment trims. Dislodge roof liner and disengage curtain airbag. To renew speaker tray and etc.	S/N \$	1,800.00 1800	✓
6	To repair rhs rear fender. Re-organise rear crash management components. Reinstall all parts removed.	\$	1,050.00 750	✓
7	To respray rooftop panel, rear lid and rhs rear fender. <i>Rear Bumper</i>	\$	3,100.00 2475	✓ 4.5 panel.
8	To carry out diagnostic check.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES			: \$ 7,902.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLP 7960 G

		Damage Parts & Prices		
S/N	Parts Description	S/Nett	Remarks	
1	REAR WINDOW <i>hatched</i>	\$ 766.00	✓	612.80
2	PRIMER <i>new</i>	\$ 19.00	✓	14.80
3	SIDE WINDOW - RH <i>it</i>	\$ 537.00	✓	429.20
4	ADDITIONAL BRAKE LIGHT <i>could</i>	\$ 221.00	✓	176.40
5	MOULDED HEADLINER <i>it</i>	\$ 1,666.00	✓	1332.80
6	D-PILLAR TRIM - LH / RH UPPER <i>RH it</i> 2	\$ 218.00	109	86.80
7	A-PILLAR TRIM - LH <i>new</i>	\$ 151.00	+X	
8	A PILLAR TRIM - RH UPPER ?	\$ 151.00	+X	
9	B-PILLAR TRIM - LH / RH <i>ilse ne</i> 2	\$ 408.00	+X	
10	C-PILLAR TRIM - LH <i>ARH</i> stained 12	\$ 284.00	+X	ask Admin 113.60
11	REAR SHELF PANEL TRIM <i>it</i>	\$ 614.00	✓	490.80
12	REAR SHELF PANEL TRIM COVER ? <i>1M</i>	\$ 50.00	?	19.12
13	HEAD RESTRAINT <i>nn?</i> <i>TN</i> 21	\$ 1,338.00	?X	Steel 535.20
14	HEAD RESTRAINT - CENTRE ? <i>nec</i>	\$ 669.00	?	6/3/20 535.20
15	BACKREST COVER - RH ? <i>nn</i>	\$ 2,232.00	?	1.15 pm
16	BACKREST COVER - LH ? <i>nn</i>	\$ 1,904.00	?	
17	REAR WINDSCREEN SEALANT <i>2</i> <i>2er</i> S/N	\$ 200.00	✓	✓
18	1/4 GLASS SEALANT S/N	\$ 100.00	✓	✓
19	SUNDRIES ? <i>nn</i>	\$ 400.00	?	X
TOTAL SPARE PARTS CHARGES		\$ 11,928.00		
TOTAL LABOUR CHARGES		\$ 7,902.00		
GRAND TOTAL		\$ 19,830.00		

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

20,080.96#