

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5688Y

AAD2002-104

*Not Authorised
L/Sing B*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

18 FEB 2020

SHC 5688Y
VF1ABL15AUC281648
RENAULT
LATITUDE
12.2.2020
TOKIO MARINE
5/6/2015

PART	LIST
1 BUMPER COVER REAR	\$ <i>Ry</i> 561.70 ✓
1 BUMPER LOWER REAR	\$ <i>mit</i> 411.90 ✓
1 BUMPER BRACKET CTR REAR	\$ <i>CM</i> 98.10 ✓
1 BUMPER BRACKET SIDE RH REAR	\$ <i>Dis</i> 82.10 ✓
1 BUMPER RETAINER RH REAR	\$ <i>Dis</i> 59.80 ✓
1 BUMPER REFLECTOR RH	\$ <i>CM</i> 16.60 ✓
1 BUMPER BRACKET SIDE LH REAR	\$ <i>CM</i> 80.80 ✓
1 BUMPER RETAINER LH REAR	\$ <i>Dis</i> 54.20 ✓
1 BUMPER REFLECTOR LH	\$ <i>mit</i> 16.60 ✓
1 BUMPER BEAM REAR	\$ <i>Ry</i> 547.80 ✓
1 BUMPER BEAM BRACKET LH REAR	\$ <i>Ry</i> 114.50 ✓
1 BUMPER BEAM BRACKET RH REAR	\$ <i>Dis</i> 100.90 ✓
1 BUMPER BLOCK LH REAR	\$ <i>NIP</i> 75.70 X
1 BUMPER BLOCK RH REAR	\$ <i>NIP</i> 76.50 A
1 BUMPER HARNESS REAR	\$ 301.10 ?
1 BOOT REAR	\$ <i>Ry</i> 1,677.20 ✓
1 BOOT FINISHER	\$ <i>wapp</i> 344.70 ✓
1 BOOT WHEATERSTRIP	\$ <i>Dis/Ad</i> 178.20 <i>50 jin</i>
1 BOOT REFLECTOR LAMP LH	\$ <i>Bro</i> 277.70 ✓
1 BOOT REFLECTOR LAMP RH	\$ <i>Bro</i> 277.70 ✓
1 BOOT BADGE 'RENAULT'	\$ <i>na</i> 82.40 ✓
1 BOOT BADGE	\$ <i>na</i> 95.80 ✓
1 BOOT STRUT LH	\$ <i>su</i> 145.10 X
1 BOOT STRUT RH	\$ <i>su</i> 145.10 X
1 BOOT HINGE LH	\$ <i>Ry</i> 254.20 ✓
1 BOOT HINGE RH	\$ <i>Dis</i> 253.80 ✓

Trans-cab Auto Services Pte Ltd

AAD2002-104

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5688Y

1	BOOT INNER TRIM BOARD	\$	Return	611.00	✓
1	BOOT SWITCH	\$	Sm	113.00	
1	BOOT LOCK	\$	Tm	246.60	✓
1	BOOT LOCK CATCH	\$	Dis	41.70	✓
2	LICENCE PLATE LAMP	\$	Sm	26.30	X
2	BOOT RUBBER PLUG	\$	Sm	139.30	X
1	BOOT LOCK LINKAGE	\$	Sm	20.60	X
1	BOOT LOCK LINKAGE HOLDER	\$	Sm	99.50	X
2	BOOT BUFFER	\$	Sm	26.80	X
1	FENDER PANEL REAR LH	\$	Bu	1,933.20	✓
1	WHEELARCH REAR LH	\$	CM	181.60	✓
1	FENDER PANEL INNER TRIM REAR LH	\$	Return	671.45	✓
1	FENDER PANEL REAR RH	\$	Bu	1,933.20	✓
1	WHEELARCH REAR RH	\$	Sm	275.40	X
1	FENDER PANEL INNER TRIM REAR RH	\$	Bu	671.45	✓
1	AIR VENT RH	\$	Sm	59.40	X
1	AIR VENT LH	\$	Dis	59.40	✓
1	TAILLAMP RH	\$	Sm	401.40	X
1	TAILLAMP PANEL RH	\$	R	401.40	X
1	TAILLAMP LH	\$	Bu	401.40	✓
1	TAILLAMP PANEL LH	\$	Bu	401.40	✓
1	OUTER PANEL REAR (End Panel)	\$	Bu	745.80	✓
1	OUTER PANEL REAR (End Panel) TRIM	\$	Dis	404.56	✓
1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	Bu/Bu	1,229.40	✓
1	SPARE WHEEL PANEL TRIM	\$		612.21	✓
1	SPARE TYRE BOARD	\$		680.90	✓
1	SPARE WHEEL PANEL BRACKET LH L70Y	\$	R	70.60	X
1	SPARE WHEEL PANEL BRACKET RH L70Y	\$	R	69.20	X
1	EXHAUST REAR	\$	R	5,263.60	X
1	EXHAUST CAP REAR	\$	Sm	125.40	X
1	CHASSIS PANEL REAR LH	\$	R	2,192.40	X
1	FENDER PANEL INNER REAR LH L70Y	\$	Bu	1,241.60	✓
1	FENDER INNER BOARD LH L70Y	\$	R	561.40	X
1	FENDER WHEEL HOUSING PANEL REAR LH	\$	R	4,682.09	X

Trans-cab Auto Services Pte Ltd

AAD2002-104

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5688Y

1 FUEL FLAP	\$	Bn 244.70	✓	
1 FUEL TANK FILLER NECK	\$	473.10	?	
1 FUEL TANK CAP	\$	136.90	?	
1 FUEL TANK	\$	Sn 2,748.95	X	
1 FUEL TANK PUMP	\$	1,266.53	?	
1 FUEL PIPE SHORT	\$	611.80	?	
1 FUEL PIPE LONG	\$	1,148.12	?	
1 TUBE FILLER	\$	297.19	?	
1 KNUCKLE ARM REAR RH L70Y	\$	Sn 472.10	X	
1 BRAKE DISC REAR RH L70Y	\$	Sn 266.50	X	
1 WHEEL HUB NUT L70Y	\$	Sn 41.80	X	
1 WHEEL HUB CAP L70Y	\$	Sn 30.50	X	
1 ABS SENSOR REAR RH L70Y	\$	Sn 190.50	X	
1 REAR AXLE L70Y	\$	3,469.00	?	
1 AXLE ARM RH L70Y	\$	Sn 69.50	} X	
1 REAR AXLE SPACER RH	\$	Sn 49.00		
1 REAR AXLE ARM ROD RH	\$	Sn 69.50		
1 LOWER ARM REAR RH L70Y	\$	Sn 543.50		
1 AXLE SPRING ARM RH	\$	Sn 220.60		
1 ABSORBER REAR RH	\$	Sn 217.30		
1 ABSORBER DUST COVER REAR RH	\$	Sn 47.10		
1 ABSORBER MOUNTING REAR RH	\$	Sn 49.40		
1 STABILIZER BAR REAR	\$	427.90		?
1 STABILIZER LINK REAR RH	\$	Sn 55.20		X
1 BRAKE CALIPER REAR RH	\$	Sn 659.10	} X	
1 BRAKE CALIPER BRACKET REAR LH/RH	\$	Sn 384.00		
1 BRAKE HOSE REAR RH	\$	Sn 79.50		
1 KNUCKLE HUB+ BEARING RH	\$	na 272.30		
1 SUBFRAME ARM REAR RH	\$	Sn 198.33		
1 RODE- LONG REAR RH	\$	Sn 120.16		
1 KNUCKLE ARM REAR LH L70Y	\$	Sn 472.10		
1 BRAKE DISC REAR LH L70Y	\$	Sn 266.50		
1 WHEEL HUB NUT L70Y	\$	Sn 41.80		
1 WHEEL HUB CAP L70Y	\$	Sn 30.50		

Trans-cab Auto Services Pte Ltd

AAD2002-104

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5688Y

1	ABS SENSOR REAR LH L70Y	\$	<i>Sm</i>	190.50	X
1	AXLE ARM LH L70Y	\$	<i>Sm</i>	69.50	X
1	REAR AXLE ARM ROD LH	\$	<i>Sm</i>	69.50	X
1	LOWER ARM REAR LH L70Y	\$		543.50	?
1	AXLE SPRING ARM LH	\$		220.60	?
1	ABSORBER REAR LH	\$		217.30	?
1	ABSORBER DUST COVER REAR LH	\$		47.10	?
1	ABSORBER MOUNTING REAR LH	\$		49.40	?
1	BRAKE CALIPER REAR LH	\$	<i>Sm</i>	659.10	X
1	BRAKE CALIPER BRACKET REAR LH/RH	\$	<i>Sm</i>	384.00	X
1	BRAKE HOSE REAR LH	\$	<i>Sm</i>	79.50	X
1	KNUCKLE HUB+ BEARING LH	\$	<i>na</i>	272.30	X
1	SUBFRAME ARM REAR LH	\$		198.33	?
1	RODE- LONG REAR LH	\$	<i>Sm</i>	120.16	X
1	REAR AXLE SPACER LH	\$	<i>Sm</i>	49.00	X
1	STABILIZER LINK REAR LH	\$		55.20	?
1	BRAKE PAD REAR	\$	<i>Sm</i>	145.60	X
1	WINDSCREEN REAR L70Y	\$	<i>Shatter</i>	817.20	✓
1	WINDSCREEN GARNISH INNER LH	\$	<i>DIT</i>	257.40	✓
2	WINDSCREEN SEALANT	\$	<i>Mc</i>	109.20	405A
1	WINDSCREEN GARNISH INNER RH	\$	<i>Sm</i>	257.40	X
1	WINDSCREEN LOWER GRILLE COVER	\$	<i>Sm</i>	310.60	X
1	SHELF ASSY (WINDSCREEN UNDER PANEL)	\$	<i>R</i>	443.76	?
1	SHELF AR	\$	<i>Sm</i>	730.60	X
1	EXTENSION-RR LH SIDE MEMBER	\$	<i>R</i>	247.69	X
1	EXTENSION-RR RH SIDE MEMB	\$	<i>R</i>	245.79	X
1	DOOR PANEL REAR RH	\$	<i>R</i>	758.70	X
1	DOOR LOCK REAR RH L70Y	\$	<i>R</i>	467.30	X
1	ROCKER PANEL INNER GARNISH LH	\$	<i>Sm</i>	466.51	X
1	ROCKER PANEL INNER LH	\$	<i>R</i>	1,024.79	X
1	ROCKER PANEL OUTER LH	\$	<i>R</i>	1,184.99	X
1	DOOR PANEL REAR LH	\$	<i>R</i>	758.70	X
1	DOOR LOCK REAR LH L70Y	\$	<i>R</i>	468.20	X
1	DOOR CATCH REAR LH/RH	\$	<i>R</i>	73.70	X

Trans-cab Auto Services Pte Ltd

AAD2002-104

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5688Y

1 DOOR FINISHER REAR LH	\$	Sm	230.30	}
1 DOOR WEATHESTRIP REAR LH L70Y	\$	Sm	240.50	
1 DOOR SEAL REAR LH	\$	Sm	119.40	
1 DOOR WAIST SEAL OUTER REAR LH	\$	Sm	116.10	
1 ROOF PANEL	\$	N	2,900.70	
1 ROOF SIDE PANEL OUTER LH	\$	N	704.21	
1 ROOF TOP CHANNEL MOLDING LH	\$	Sm	291.27	
1 ROOF TOP CHANNEL MOLDING RH	\$	Sm	291.27	

TOTAL	\$	65,482.71
10%	\$	6,548.27
	\$	58,934.44

Special Nett

1SET PARKING AID	\$	Nd	700.00	400.50
1SET REAR BUMPER CLIP	\$	Nn	66.00	—
1SET BUMPER BRACKET CTR CLIP	\$	Nn	33.00	—
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	Nn	10.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	Nn	20.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	Nn	10.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	Nn	20.00	✓
1SET BUMPER LOWER REAR RIVET	\$	Nn	22.00	X
1SET BUMPER LOWER REAR CLIP	\$	Nn	66.00	✓
1 EXHAUST MOUNTING REAR	\$	Nn	16.00	X
1SET BOOT FINISHER CLIP	\$	NCC	24.20	—
1 BOOT STICKER "Trans-cab"	\$	Nn	30.00	—
1 BOOT STICKER "6555-3333"	\$	Nn	30.00	—
1 BOOT INNER TRIM CLIP	\$	Nn	45.00	—
1SET FENDER WHEELARCH REAR RH CLIP	\$	Nn	35.00	—
1SET FENDER WHEELARCH REAR LH CLIP	\$	Nn	35.00	—
1 FENDER INNER TRIM CLIP LH	\$	Nn	28.00	—
1 FENDER INNER TRIM CLIP RH	\$	Nn	28.00	X
1 TAILLAMP CLIP RH	\$	Nn	5.00	X
1 TAILLAMP CLIP LH	\$	Nn	5.00	✓

Trans-cab Auto Services Pte Ltd

AAD2002-104

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5688Y

1	WINDSCREEN MOULDING	\$	<i>na</i>	160.00	<i>X</i>
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	100.00	<i>30na</i>
1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$		385.00	<i>?</i>
1	SPARE TYRE	\$		330.00	<i>?</i>
1	RIGHT REAR TYRE	\$	<i>su</i>	330.00	<i>X</i>
1	RIGHT REAR TYRE RIM	\$	<i>su</i>	380.00	<i>X</i>
1	RIGHT LEFT TYRE	\$	<i>pu</i>	330.00	<i>50na</i>
1	RIGHT LEFT TYRE RIM	\$	<i>su</i>	380.00	<i>X</i>
1	EXHAUST BRACKET REAR	\$	<i>K</i>	24.80	} <i>X</i>
1	REAR RH DOOR STICKER "6555-3333"	\$	<i>na</i>	100.00	
1	REAR LH DOOR STICKER "6555-3333"	\$	<i>na</i>	100.00	
1	REAR BUMPER PROTECTOR	\$	<i>na</i>	100.00	
1Set	REAR LICENCE PLATE WITH HOLDER	\$	<i>su</i>	100.00	
2	BOOT LOCK SCREW	\$	<i>su</i>	6.10	
2	BOOT LOCK CATCH SCREW	\$	<i>su</i>	12.50	
TOTAL		\$		4,066.60	

TOTAL PARTS \$ 63,001.04

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$	9,900.00	<i>1760l</i> <i>2400l</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	9,900.00	<i>2400l</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	<i>60l</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	350.00	<i>120l</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	<i>60l</i>

Trans-cab Auto Services Pte Ltd

AAD2002-104

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5688Y

To Rust-Proofing Of The Affected Areas.	\$	170.00	1501
To repair and realign rear exhaust pipe.	\$	<i>Repair</i> 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>nr</i> 170.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	} 801
To supply and re-do rear luggage floor panel insulation padding.	\$	380.00	
To transfer of tire, rim and on wheel balancing.	\$	<i>nr</i> 170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nr</i> 380.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>nr</i> 170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	170.00	1201
To check steering geometry and computer wheel alignment	\$	220.00	601
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	2501
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nr</i> 170.00	X

Trans-cab Auto Services Pte Ltd

AAD2002-104

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5688Y

To Check Electrical Lighting Concerned.	\$	170.00	201
Towing Fees	\$	150.00	501
To transfer of door fittings, attachment and perform water seepage test.	\$	<i>nr</i> 350.00	X
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	380.00	2201
To drop diesel/petrol tank, pipes, hoses and renew the necessary parts and final checking and testing for leak.	\$	440.00	601
To dismantle and refit rear axle assy, remove and renewal of parts, final checking and testing.	\$	<i>Repair</i> 380.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	4 380.00	X
To check ABS and brake efficiency, final checking and testing.	\$	<i>nr</i> 380.00	X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$	<i>nr</i> 380.00	X
TOTAL	\$	26,390.00	
Over All Total	\$	89,391.04	

LUMP SUM (Repair Days)

35 DAYS

21 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: