

ASS. REC. BY: Sun Pm.

REF:

MSG. (C3) MSG 200028321 09f35

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. 29141713
 Claims No. 619930
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 1 days Res.: Yes or No
 Turn Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMB166R Yr Regn: 28/10/2017
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Mercedes Benz Citaro 0530 c.c. 6374
 Colour: Multicolour A/C: Insured / Std / NI / NA
 Sp. Reading: 735438 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WEB62808323122703
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 275 / 70 R22.5
 R: 275 / 70 R22.5 (D)
 BS / DUN / EXNÖYA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Pirelli
 Front Rear
 R/Bal. 5 mm R/Bal. 5/5 mm
 L/Bal. 5 mm L/Bal. 5/5 mm
 D.O.A. 13/02/2020 D.O.I. 18/02/2020
 Survey held at SMRT
 Des. of Damages: Frnt / Rear / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SMB166R - (C3) LCR18001630 / R15b392 110A - 15/04/2018
	SLW5401E - X
20/2/2020 @ 9.00am	Email GIA & Estimate and Revised to MSG.
	RECEIVED 13 MAR 2020
	(confirm with Catherine)
	Finalise: \$950 @ 1 day (L/S) (Red \$7990.58, 79.1%)
Date/Time, File Pass to?	☐ : Prel. Report
1) 10/3 transfer	☐ : Final Report
Date/Time, File Return to?	
2)	
Report Formed: <u>MER-TP</u>	
Lump Sum / L/S: <u>950</u>	
Days Of Repair: <u>1</u>	
Resurvey No. of Trip: <u>1</u>	
Add Fee: ☐ : Site Insp (\$ _____)	
☐ : Interview (\$ _____)	
☐ : Tech. Invs (\$ _____)	
☐ : Wash and (\$ _____)	
Survey Fee: <u>150</u>	
Transportation: _____	
\$ + RS. \$ _____	
Phone: _____	
Others: <u>11</u>	
TOTAL	

Oi Sun Pin (LKK Auto)

From: Oi Sun Pin (LKK Auto)
Sent: Tuesday, 25 February, 2020 9:26 AM
To: Catherine Lee Sau Chan (Auto Svcs/ARC/ARC/Buses)
Subject: RE: Finalisation - SMB166R (BUS/02/20/1035) - MSIG

Hi Catherine,

Confirm the finalize amount \$950. Repair day 1 day under lump sum repair.

Thank you.

Best Regards,

Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Lee Sau Chan (Auto Svcs/ARC/ARC/Buses) [<mailto:catherineleesc@smrt.com.sg>]
Sent: Monday, 24 February, 2020 5:29 PM
To: Oi Sun Pin (LKK Auto); SUR; Admin A
Cc: Koo Yew Chung (Auto Svcs/ARC/ARC); AutoSvs-ARC (Bus)
Subject: Finalisation - SMB166R (BUS/02/20/1035) - MSIG

Hi Sun Pin,

Attached herewith our copy and your marked copy of the bus repair estimate for the case.
Our finalised amount is \$950/-@ 1 working day under lump sum repair. Attached after repair photos for your perusal.

Please confirm the COR by return email ASAP.

Thank you

Best Regards
Catherine Lee
SMRT Automotive Services Pte Ltd
(Accident Repair Centre)
DID: 6866 2669 Fax: 6368 5592
catherineleesc@smrt.com.sg



Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Thursday, 20 February 2020 9:22 AM
To: Motor Survey
Cc: SUR; KKLau; Accounts (LKKAuto)
Subject: DIRECT SURVEY INSPECTION ON WORKSHOP - SMRT AUTOMOTIVE SERVICES PTE LTD (TP VEHICLE: SMB 166R, INSURED VEHICLE: SLW 5401E, DOA: 13-02-2020)
Attachments: CC3MSG20002832Qqf3.pdf; SMB166 EST.pdf; SMB166 GIA.pdf

Dear Sir/Madam,

Please be informed that we had inspected the vehicle **SMB 166R** at M/s: **SMRT AUTOMOTIVE SERVICES PTE LTD**, 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705.

Enclosed herewith a copy of TP's GIA report and estimate.

Meanwhile, kindly provide us the claim reference number for our necessary action.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: Please advise

Date: 20th February 2020

Our Ref: CC3/MSG20002832/Qqf3

The Motor Claims Department
MSIG Insurance Singapore Pte Ltd

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SMB 166R

Please be informed that we had conducted the inspection of the abovementioned vehicle on 18/02/2020 at the premises of M/s SMRT and have the following to report:-

Workshop Estimate Amount	: S\$ 4,440.58 .
Revised Estimate Amount	: S\$ 983.77 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages at the front portion.



Comments/ Present Status:

Damages consistent.

We have not authorized repair.

Yours faithfully

Sun Pin
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/02/2020 08:51
Date Of Accident	13/02/2020 18:45
Exact Location Of Accident	JUNCTION OF JALAN BUKIT MERAH AND BUKIT MERAH VIEW
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMB166R
Insured/Policyholder	
Name Of Registered Owner	SMRT BUSES LTD
Co Reg No	1XXXXX292D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	CITARO 0530

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category BUS

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	D-19093203MFBP
Cover Note Number	


Driver

Name of Driver	MUHAMMAD RIMAL BIN ABDUL MALEK
NRIC No	SXXXX534A
Date Of Birth	26/04/1984
Occupation	OUTDOOR
Date Of Driving Pass	03/11/2014
Driving Experience	5 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

No. Of Passenger (Including Driver)

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT:

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____

Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	292D
Vehicle Details	
Vehicle No.:	SMB166R
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Feb 2020
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	CITARO O530
Primary Colour:	Multicolor
Manufacturing Year:	2011
Engine No.:	90292600909240
Chassis No.:	WEB62808323122703
Maximum Power Output:	-
Open Market Value:	\$300,329.00
Original Registration Date:	28 Oct 2011
First Registration Date:	28 Oct 2011
Transfer Count:	0
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 19 Feb 2020

OK



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 17/02/2020

User ID : BoonChewTay

Section A - Accident Details

Registration Number	SMB166R
Case Reference Number	BUS/02/20/1035
Registration Date	28/10/2011
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC530
Name of Driver	Muhammad Rimal Bin Abdul Malek
Type of Accident	Side Swipe
Accident Date and Time	13/2/2020 6:46 PM
Accident Reported Date and Time	14/2/2020 11:01 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB166R-LEFT FRONT PORTION SLW5401E (TP) INSURED WITH MSIG
Prepared Date and Time	17/2/2020 3:33 PM
Chassis Number	WEB62808323122703
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$0.00	\$0.00
Total Spray Cost	\$0.00	\$0.00
Total Spare Part Cost	\$2,316.12	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$2,316.12	\$0.00
Lump Sum Total	\$3,550.00	\$0.00
Number of Repair Days	3.0	
Prepared / Adjusted By	Boon Chew Tay	
ARC / Surveyor Sign Off Date	17/02/2020 3:46 PM	
Signature		☒
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 24/02/2020

User ID : CatherineLee

Section A - Accident Details

Registration Number	SMB166R
Case Reference Number	BUS/02/20/1035
Registration Date	28/10/2011
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC530
Name of Driver	Muhammad Rimal Bin Abdul Malek
Type of Accident	Side Swipe
Accident Date and Time	13/2/2020 6:46 PM
Accident Reported Date and Time	14/2/2020 11:01 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24105765
Special Instruction to ARC, if any	SMB166R-LEFT FRONT PORTION SLW5401E (TP) INSURED WITH MSIG
Prepared Date and Time	17/2/2020 3:33 PM
Chassis Number	WEB62808323122703
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$530.00
Total Spray Cost	\$446.00	\$324.00
Total Spare Part Cost	\$1,791.77	\$86.97
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$3,032.77	\$940.97
Lump Sum Total	\$3,050.00	\$950.00
Number of Repair Days	3.0	1.0
Prepared / Adjusted By	Boon Chew Tay	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	17/02/2020 3:46 PM	18/02/2020 2:54 PM
Signature		S
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 24/02/2020

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$795.00	\$530.00
Total Labour	\$795.00	\$530.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$446.00	\$324.00
Total Spray Painting & Panel Beating	\$446.00	\$324.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009902	BODY LH	6288800172	BUMPER FRONT, LH, FOR MB CITARO O530	1.00	\$1,767.78	100.00	\$0.00	Replace	Repair
6009700	VE		LAMP BLINKER FRONT, LEFT, FOR MB OC 500 LE	1.00	\$155.30	30.00	\$108.71	Replace	Replace
6009509	VE		HEADLAMP FOR MERCEDES OC500 LE, LEFT	1.00	\$1,278.50	100.00	\$0.00	Replace	Repair
Total					\$3,199.58		\$108.71		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

L/S = \$ 950

1 days

108.71
- 20%
86.97
530
324
940.97

950

→ 12.71

108.71
530
324
962.71

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	18 Feb 2020		21 Feb 2020 11:50 Edit Adj Rpt	S\$950.00 Edit Estimates	S\$950.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G			
Main Claimant:	SMRT BUSES LTD, Co. Reg. No.: 198202292D			
Vehicle Reg. No.:	SMB166R	Date of Loss:	13/02/2020 18:00 - :59 [99 Months and 16 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 619930	Policy/Cover Note No.:	29141713 (Comprehensive) Coverage: 01/02/2020 - 31/12/2020	
Vehicle Reg. No. (Insured):	SLW5401E	Policy No. (Claimant):		
		Excess:		
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]			
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by OI SUN PIN] ... [Imm.Advice due 22/02/2020]			
Driver/Custodian (Insured):	CHNG EE CHAY (65 / Male) , NRIC: S0014313H, Tel: +6581630675 Email:			
Adj Asg. Remarks:	Direct Survey by LKK Auto Consultants.			

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMB166R (619930)**
[SLW5401E]
TP
SMRT BUSES LTD
Feb 13 2020 6:00PM
[GRAB RENTALS PTE LTD]
SMRT Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter

View View in Browser ▼

Photos/Images

3 per page ▼

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	25/02/20 09:28	Chassis Number	 Load JPG	☒
2	25/02/20 09:28	Odometer Reading	 Load JPG	☒
3	25/02/20 09:29	General View	 Load JPG	☒
4	25/02/20 09:29	General View	 Load JPG	☒
5	25/02/20 09:29	General View	 Load JPG	☒
6	25/02/20 09:29	General View	 Load JPG	☒
7	25/02/20 09:29	General View	 Load JPG	☒
8	25/02/20 09:29	General View	 Load JPG	☒
9	25/02/20 09:29	General View	 Load JPG	☒
10	25/02/20 09:29	General View	 Load JPG	☒
11	25/02/20 09:29	General View	 Load JPG	☒
12	25/02/20 09:29	General View	 Load JPG	☒
13	25/02/20 09:29	General View	 Load JPG	☒
14	25/02/20 09:29	After Repair Photo	 Load JPG	☒
15	25/02/20 09:29	After Repair Photo	 Load JPG	☒
16	25/02/20 09:29	After Repair Photo	 Load JPG	☒
17	25/02/20 09:29	After Repair Photo	 Load JPG	☒
18	25/02/20 09:29	After Repair Photo	 Load JPG	☒

Documentation

1 per page ▼

No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/02/20 11:44	SMB166R E-filed GIA report	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset Save Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG20002832/QQF3S2
Date: 19/03/2020

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29141713

Claimant Vehicle No: SMB166R

Insured Vehicle No: SLW5401E

Date of Loss: 13/02/2020

Nature of Claim: TP Claim No: 619930

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMB166R

Make & Model: MERCEDES-BENZ CITARO O530, 6.4 D (A)

Engine No: 90292600909240

Reg. Date: 28/10/2011 (Man. Year: 2011)

Chassis No: WEB62808323122703

Colour: Multi-colour

Odometer: 735438 km

Engine Capacity: 6374 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable):

Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 275/70 R22.5

Rear Tyre Size: 275/70 R22.5(D)

Front Left Side: Firenza 5 mm

Rear Left Side: Firenza 5/5 mm

Front Right Side: Firenza 5 mm

Rear Right Side: Firenza 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,199.58	108.71	3,090.87	96.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,241.00	854.00	387.00	31.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,440.58	962.71	3,477.87	78.32
Approved Total (Overridden) (S\$)		950.00		
Nett Amount (S\$)	4,440.58	950.00	3,490.58	78.61

INSPECTION

Date of Assignment: 21/02/2020

Date Inspected: 18/02/2020 Inspected At:

SMRT Automotive Services Pte Ltd (Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705

Estimated Period of Repair: 1.0 days

Adjuster: OI SUN PIN

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 19 Mar 2020)		
Parts:	N/A	MERCEDES-BENZ CITARO O530 6.4 D (A) (Model not available in database)	
Labour:	Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SMB166R)		
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page		
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER: FRONT, LH, FOR MB CITARO O530	Repair	1,767.78 F	*- FL
2	1		*LAMP, BLINKER: FRONT, LEFT, FOR MB OC 500 LE	Cracked	155.30 F	*155.30 FL
3	1		*HEADLAMP FOR MERCEDES OC500 LE, LEFT	Serviceable	1,276.50 F	*- FL
					Sub Total (S\$)	3,199.58 155.30
					- List Item Discount on L Items 0.00/30.00% (S\$)	0.00 46.59
					Total Parts (S\$)	3,199.58 108.71

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGE AFFECTED AREAS.	New	795.00	530.00
2	PROVIDE LABOUR AND MATERIAL TO PUTTY RESPRAY ABOVE REPAIR ITEMS.	New	446.00	324.00
Gross Labour Cost (S\$)			1,241.00	854.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >