

ASS. REC. BY:

REF: CS/CT1 20002857/E1/f302 Special Instruction:

Surveyor: Sevi ASSIGNMENT (Office)From (Person): Cecilia Low of CTI Date/Time: 18.2.2003 16:57pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No: SLV 14674 Insured: GBB 53525at Workshop m/s Altitude Car Leasing Tel: 81912300of 1 Bukit Babok Crescent #0536Policy No: DMCUSN 3034 0219000 Claim No: SMM 200200846

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 14.2.2000
(Client's Record)CA / REV / REP. / REV 24 HRS ^{1yr} H.O.D. Endorsement: _____Date/Time: 19.2.2003 10:30am Person Contacted: Rose Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLV 14674 - X
	GBB 53525 - X

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
ID / TP / WS / TP.RES / OD.RES / EVA / INV / MV
 o Inspect Vehicle No: _____
 l Workshop m/s: _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)
 Remark: The veh. had commenced its repair at the time of inspection.
 Ins. or Market Value: _____
 AC Accident Rpt: Consistent? : Yes or No
 A / PR. Seen: Consistent? : Yes or No
 L Repairs: days Res.: Yes or No
 m Sum: % 3 Val.: Yes or No
 V / REV / REP. / 24 HRS
 Vehicle: IN / OUT
 Person Contacted: _____



Veh No: SLV 14674 Yr Regn: 22/12/17
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Traller or
 Make: Toyota Sienta Hybrid c.c. 1496
 Colour: Silk A/C: Insured / Std / NI / NA
 Sp. Reading: 188312 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 CiNo: NHP 1707100324
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Bln / STD A/Rim or
 Tyre Size: F: _____ R: _____
185/60R15
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or SINCERA
 Front R/Bal. 5 mm Rear R/Bal. 5 mm
 L/Bal. 5 mm L/Bal. 5 mm
 D.O.A. 14/2/20 D.O.I. 19/2/20
 Survey held at Altitude Car leasing
 Dos. of Damages: Frt Rear / O/S / N/S / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
19/2/20 MR-68K 19/2/20 Waiting Estimate

6/3 U/S \$7600f (Red \$5682-50, 42%)

RECEIVED 11 MAR 2020

u/Time, File Pass to? : Proll. Report
 : Final Report

Days Of Repair: 10
 Resurvey No. of Trip: 3

u/Time, File Return to? 11/3/20 Typist

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee:	<u>220</u>
Transportation:	
(\$ - RS - SI)	
Prize	
Others	
TOTAL	<u>220</u>

Report Format: U.S.
 mp Sum I.B.I: (\$) \$7600f

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Feb 2020		18 Feb 2020 16:57 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:			
Main Claimant:	CLT LEASING PTE. LTD., Co. Reg. No.: 201717731M		
Vehicle Reg. No.:	SLV1467Y	Date of Loss:	14/02/2020 10:00 - :59
Claim Type:	TP / SNM20D200B46	Policy/Cover Note No.:	DMCVSN30390219000
Vehicle Reg. No. (Insured):	GBB5352S	Policy No. (Claimant):	5111279474 (PREMIUM)
		Excess:	S\$0.00
Repairer:	- Not Applicable - (-)		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Cecilia Low - 63896530]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 27/02/2020]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nivitha (LKK Auto)

From: Cecilia Low <cecilia.low@sg.cntaiping.com>
Sent: Tuesday, 18 February 2020 4:52 PM
To: sur@lkkauto.com; assignments@lkkauto.com; admin-a@lkkauto.com
Cc: Altitude Car Leasing Pte Ltd
Subject: RE: OUR REF: SNM20D200846/GBB5352S/CECILIA - Accident involving GBB5352S & SLV1467Y.

Dear Sirs

Please attend to PRI on Without Prejudice basis.
Thank you.

Cecilia Low (Ms)
Senior Executive
Claims

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6530 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Altitude Car Leasing Pte Ltd [mailto:enquiry@altitudeleasing.com.sg]
Sent: Tuesday, 18 February 2020 2:07 PM
To: Cecilia Low <cecilia.low@sg.cntaiping.com>
Subject: Re: OUR REF: SNM20D200846/GBB5352S/CECILIA - Accident involving GBB5352S & SLV1467Y.

Hi,

You may assign Henry Ng over.
Location:

1 Bukit Batok Crescent
Wcega Plaza #05-36
S658064

Look for Ros/ Kerry

On Tue, Feb 18, 2020 at 10:46 AM Cecilia Low <cecilia.low@sg.cntaiping.com> wrote:

Without Prejudice

Dear Sirs

We refer to your email of even date.

We intend to conduct a Pre-Repair Survey of your client's vehicle jointly with your client/your motor workshop.

We propose to use one of the following motor surveyors to conduct the survey as a single joint expert.

LKK / LBS

Adrian Ling
Kelvin Ang
See Chew Seng
Mohd Fadhilah Bin Osman
Xing Quo Qiang
Kenneth Kong
Simon Ho
Chua Weijie
Marcus Chua
Henry Ng

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.

Thank you.

Cecilia Low (Ms)

Senior Executive

Claims

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 6389 6530 | F: (65) 6222 1033

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Altitude Car Leasing Pte Ltd [mailto:enquiry@altitudeleasing.com.sg]
Sent: Monday, 17 February 2020 4:34 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Cecilia Low <cecilia.low@sg.cntaiping.com>
Subject: Re: OUR REF: SNM20D200846/GBB5352S/CECILIA - Accident involving GBB5352S

Hi,

Our carplate number is SLV1467Y.

On Mon, Feb 17, 2020 at 4:23 PM Claims Dept of CTI <claimsdept@sg.cntaiping.com> wrote:

Dear Cecilia,

Please conduct PRS for SMF1521X.

Note : officer in charge – Cecilia 63896530.

***** Kindly quote our reference number when replying.**

Thank you,
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Altitude Car Leasing Pte Ltd <enquiry@altitudeleasing.com.sg>
Sent: Monday, February 17, 2020 4:02 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: Re: Accident involving GBB5352S

Hi,

As per attached is the report.

On Mon, Feb 17, 2020 at 3:53 PM Claims Dept of CTI <claimsdept@sg.cntaiping.com> wrote:

Hi,

Please provide us your vehicle number/GIA report.

Thank you,

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #15-00 Springleaf Tower Singapore 079909

DID: (65) 63896116 | F: (65) 62247175

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Altitude Car Leasing Pte Ltd <enquiry@altitudeleasing.com.sg>
Sent: Monday, February 17, 2020 12:37 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: Accident involving GBB5352S

Hi,

Would like to inform that you said vehicle GBB5352S is involved in an accident with our vehicle. I would like to seek what documents do you need and when the surveyor will be coming to survey the vehicle. Do feel free to drop me a call. Thank you

--

Best Regards,

Ros

CLT Leasing Pte Ltd

(ROC No.: 201717731M)
1 Bukit Batok Crescent, Weega Plaza,
#05-36, Singapore 658064
EMAIL : enquiry@altitudeleasing.com.sg

Tel : +6581812300

--

Best Regards,

Altitude Car Leasing Pte Ltd

(ROC No.: 201703858E)
1 Bukit Batok Crescent, Weega Plaza,
#05-36, Singapore 658064
EMAIL : enquiry@altitudeleasing.com.sg

Tel : +6581812300

--

Best Regards,

Altitude Car Leasing Pte Ltd

(ROC No.: 201703858E)

1 Bukit Batok Crescent, Weega Plaza,

#05-36, Singapore 658064

EMAIL : enquiry@altitudeleasing.com.sg

Tel : +6581812300

--

Best Regards,

Altitude Car Leasing Pte Ltd

(ROC No.: 201703858E)

1 Bukit Batok Crescent, Weega Plaza,

#05-36, Singapore 658064

EMAIL : enquiry@altitudeleasing.com.sg

Tel : +6581812300

8181 3556 Ros

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/02/2020 10:51
Date Of Accident	14/02/2020 10:35
Exact Location Of Accident	PIE TOWARDS CHANGI
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLV1467Y
Insured/Policyholder	
Name Of Registered Owner	CLT LEASING PTE. LTD.
Co Reg No	2XXXXX731M
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-81812132
Alternative Phone No	OFFICE-81812132

Vehicle Particulars

Manufacturer	TOYOTA
Model	SIENTA
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5111279474 (PREMIUM)
Cover Note Number	

Driver

Name of Driver	MOHD FADZIL BIN MASURI
NRIC No	SXXXX052C
Date Of Birth	16/03/1967
Occupation	OUTDOOR
Date Of Driving Pass	25/07/2001
Driving Experience	18 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-87761426
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 676A YISHUN RING ROAD #02-1904
 Postcode 761676
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? YES
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 2
 Passenger 1 NAME: : NELSON 90905333 (GOJEK CUSTOMER)
 GENDER: : MALE

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name YISHUN NORTH NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 31 YISHUN CENTRAL , POSTCODE: 768827 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: 1800-8529999 - FAX NO: 68522299
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER POLICE REPORT (ATTENDED BY: JAMES NG)

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBB5352S
 Vehicle Make/Model/Colour MERCEDES BENZ / SILVER
 Details Of Properties
 Vehicle Category COMMERCIAL VEHICLE
 Name of Driver
 NRIC/Passport Number
 Contact Number
 Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name	MOHD FADZIL BIN MASURI
Approximate Age	52
Injuries Sustain	NECK, HEAD AND SPINE SORENESS
Injured person in which vehicle?	SLV1467Y
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	BLK 676A YISHUN RING ROAD #02-1904
Postcode	761676

DETAILS OF INJURED PERSON 2

Name	NELSON
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SLV1467Y
Were seat belts worn?	YES
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) complying with requirements under any regulations, laws or court orders.



[Handwritten signature]

IDAC SUKSES (P) LTD
511 Bukit Batok Street, 23
Singapore 659549
Tel: 6560 3312 Fax: 6369 0722
Email: vacsb@vicom.com.sg

Policyholder's Signature
Date & Time:

15 FEB 2020

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:

NG WING KIN JAMES
admin.vac@vicom.com.sg

SKETCH PLAN

A: 5LV1467Y

B: GBB53525

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer
Police
Report

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time: 15 FEB 2020

Driver's Signature
(If driver is not the policyholder)
Date & Time:

ICAST (Insurance Claims Assessment & Settlement)
511 Orchard Road, #01-01
Singapore 238883
Tel: 6500 3342 Fax: 6500 6722
Email: vocblo@icast.com.sg

Reporting Centre Personnel's Signature
Name:

NG WING KIN JAMES
admin.vac@vicom.com.sg



Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/02/2020 17:25		Vide Report No.:		Station Diary No.: 128	
Informant's Particulars					
Name of Informant: MOHD FADZIL BIN MASURI			Address: APT BLK 676A YISHUN RING ROAD #02-1904 SINGAPORE 761676		
ID Type / ID No.: NRIC NO / S1806052C			Contact No.: Home/Office:		Mobile: 87761426
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 52	Date of Birth: 16/03/1967	Type of Informant: Driver		
Race: Malay		Language: English		Institution / School Name:	
Occupation: PRIVATE HIRE DRIVER			Driving Licence Information: Class: 2B,2A,3		Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 14/02/2020 10:35	Type of Location: Straight Road
Location: Along Road 1 PAN ISLAND EXPRESSWAY PIE TOWARDS CHANGI, AFTER TOA PAYOH LOR 2 EXIT 2				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control:		Traffic Volume: Heavy
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBB5352S	Van	MERCEDES BENZ		Silver	Slightly Damaged	0
SLV1467Y	Car	TOYOTA		Silver	Slightly Damaged	1

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLV1467Y	NTUC Income Insurance Co-Operative Limited	5094123104		



Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Name	MALE CHINESE IN HIS 50S	ID No.	NIL
Related Vehicle	GBB5352S (Van)	Contact No.	NIL
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	MOHD FADZIL BIN MASURI	ID No.	S1806052C
Related Vehicle	SLV1467Y (Car)	Contact No.	87761426
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
Passenger			
Name	NELSON	ID No.	NIL
Related Vehicle	SLV1467Y (Car)	Contact No.	90905333
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 14/02/2020 at about 1035hrs, I was driving on the centre lane with my private hire car, silver Toyota Sienta, plate number: SLV1467Y, along PIE towards Changi, after Toa Payoh Lor 2 exit 2. The traffic was slow and heavy. There was a black van in front of me driving at slow speed. The said van stopped and I also make a stop. Suddenly, a huge impact came from the rear of my car, the Mercedes Benz van, plate number, GBB5352S, driving behind me had hit into my rear. My GoJek passenger named, Nelson, Hp: 90905333 was not injured at the point of time and informed me that he was fine. I checked that the rear of my car was slightly damaged and the front of the van was also slightly damage.

The said van driver was a male Chinese in his 50s. He refused to exchanged particulars with me and



SINGAPORE
POLICE FORCE



T/20200214/2114

Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

3 of 4

Report No. T/20200214/2114

CONTINUATION OF REPORT

asked me to lodge a police report. I then left scene together with Nelson. Upon dropping him at his destination, I proceeded to Khoo Teck Puat Hospital for medical treatment as I felt giddy and abrasion at the back of my head. I was given 5 days MC for the said injury. Shortly, I received a phone call from my passenger, Nelson that he had went to National University Hospital for treatment due to the accident. He was advised by the GoJek company to lodge a police report on the matter.

There is in vehicle camera installed in my car but it was not in working condition and was not recording.




Police Station Of Origin:
Yishun North N.P.C
31 Yishun Central SINGAPORE 768827
Tel No: 1800-8529999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: L / Staff Sgt FRANCIS PEH JIAN HAO	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 14/02/2020 17:25
Officer In Charge Of Case: TP / AEIT / Sr Staff Sgt ONG YONG HOCK Contact No.: 65476436	Classification Of Case: 

Authentication Stamp
NP158

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	731M
Vehicle Details	
Vehicle No.:	SLV1467Y
Vehicle to be Exported:	No
Intended Deregistration Date:	19 Feb 2020
Vehicle Make:	TOYOTA
Vehicle Model:	SIENTA HYBRID 1.5G CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	1NZ8292693
Chassis No.:	NHP1707100324
Maximum Power Output:	73.0 kW (97 bhp)
Open Market Value:	\$24,541.00
Original Registration Date:	22 Dec 2017
First Registration Date:	22 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	21 Dec 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	21 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,339.00
COE Rebate Amount:	\$33,188.00
Total Rebate Amount:	\$36,938.00

The information contained herein is correct as at 19 Feb 2020

OK

Singapore Dollar Tumbles - After This Big Announcement

Many Singaporean Still Don't Know But Singapore is Facing Big Trouble Ahead qcrirect.com

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

2017 Mitsubishi L3000, Perfect For CDE Renewal.



2017 MITSUBISHI L3000, Perfect For CDE Renewal.
Clean Title, Clean Car, Clean Owner.
Call Alan Tan (9646 0261)
Direct Owner

HIN LUNG AUTO
30 years of car care
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

Post an Ad Advertiser Login Ways of Selling

Browse by Category

Sort by Date Posted 40 results/page

8 vehicles

Toyota Sienta

Advanced Search

Photo	Model	Price	Depreciation	Reg. Date	Eng. Cap.	Mileage	Veh. Type	Status
Search Selection Toyota Sienta Any Any 2017 Any Any Any Available								
	Toyota Sienta 1.5A G (OPC)	\$57,800	\$7,620 /yr	19-Jan-2017	1,496 cc	30,760 km	MPV	Available
Max Loan Amount Available As Advertised! 1 Owner Only! Meticulously Well Maintained Unit! Top Up \$12k For Normal Plate Conversion. Guaranteed Accident Free With Low Mileage Done! Drive & Small Like New In Original Paintwork With Clean & Neat Interior! Our Comp... Creative Auto Posted: 24-Jan-2020 Tags: 2017 Toyota Sienta, 2017 Toyota Sienta, Toyota Sienta, Sienta sienta, Toyota, Sienta, sienta, Used Toyota								
	Toyota Sienta 1.5A X	\$63,800	\$8,430 /yr	28-Feb-2017	1,496 cc	73,612 km	MPV	Available
Very Good Condition! 2017 Toyota Sienta 1.5E Cvt, 7 Seater, With Power Doors, DMV \$18798, CDE \$48451, Black Colour, Call Us Now! Think One Automobile & Trading Posted: 26-Dec-2019 Tags: 2017 Toyota Sienta, 2017 Toyota Sienta, Toyota Sienta, Sienta sienta, Toyota, Sienta, sienta, Used Toyota								
	Toyota Sienta 1.5A X	\$66,888	\$8,730 /yr	06-Apr-2017	1,496 cc	32,500 km	MPV	Available
No Price Gimmicks! Immediate Ownership Transfer Upon Collection Of Car! Sport Rims And Tyres! Black Interior Leather! Low Mileage! 2 Years Warranty On Engine And Gearbox! Free 1x Normal Servicing! Bank/In House Loan Available. Welcomed Trade In. Call Or Visit Us... Posted: 11-Feb-2020 Tags: 2017 Toyota Sienta, 2017 Toyota Sienta, Toyota Sienta, Sienta sienta, Toyota, Sienta, sienta, Used Toyota								
	Toyota Sienta 1.5A X	\$68,888	\$8,980 /yr	06-Apr-2017	1,496 cc	15,000 km	MPV	Available
Graded A by STA 100% Loan Approval At Lowest Interest Rate, Super Low Mileage Done At 7,000KM Yearly, Low Depreciation At \$8K Plus Yearly, STA Graded Quality Unit Only, High Paper And Body Value Which Benefits The Next Owner, Their Losses Is Your Gain, Road Tax Paid Till Agr... Posted: 07-Apr-2020 Tags: 2017 Toyota Sienta, 2017 Toyota Sienta, Toyota Sienta, Sienta sienta, Toyota, Sienta, sienta, Used Toyota								
	Fits Most Cars Which Have No Armrest Basic armrest suitable for cars without armrest. Installation to be done at YISHUN. More info about this product							
	Toyota Sienta 1.5A G	\$68,888	\$8,940 /yr	28-Apr-2017	1,496 cc	39,000 km	MPV	Available
Graded A by STA Currently The Only Graded A By STA, Twin Power Sliding Doors, LED Headlight, Keyless Entry, 1 Owner Toyota Sienta G Model For Sale, No Repairs Needed, Comes With 1 Year Engine And Gearbox Protection Shield, 80% Loan Of The Car Price Available, High Approval Rat... Posted: 13-Feb-2020 Tags: 2017 Toyota Sienta, 2017 Toyota Sienta, Toyota Sienta, Sienta sienta, Toyota, Sienta, sienta, Used Toyota								
	Toyota Sienta 1.5A X	\$66,888	\$8,550 /yr	12-Jun-2017	1,496 cc	26,400 km	MPV	Available
Immediate Ownership Transfer Upon Collection Of Car! New Rims And Tyres! 2 Years Warranty On Engine And Gearbox! Free 1 x Normal Servicing! Loan Available, Welcomed Trade-In. Call Or Visit Us Now To View The Car! Posted: 14-Feb-2020 Tags: 2017 Toyota Sienta, 2017 Toyota Sienta, Toyota Sienta, Sienta sienta, Toyota, Sienta, sienta, Used Toyota								
	Toyota Sienta 1.5A X	\$68,888	\$8,920 /yr	30-Jun-2017	1,496 cc	55,000 km	MPV	Available
Posted: 06-Feb-2020 Tags: 2017 Toyota Sienta, 2017 Toyota Sienta, Toyota Sienta, Sienta sienta, Toyota, Sienta, sienta, Used Toyota								
	Toyota Sienta Hybrid 1.5A X	\$86,998	\$8,880 /yr	14-Aug-2017	1,496 cc	-	MPV	Available
Fuel Type: Petrol-Electric Drive With Assurance! Genuine And Transparent Deal! Flexible Bank/In House 100% Loan Monthly Instalment \$1,180, All Our Commitment Cars Are Selling At The Most Reasonable Price With A Peace Of Mind! STA Inspection Welcome! View To Believe! 100% No... CarQuiz Singapore Posted: 09-Feb-2020 Tags: 2017 Toyota Sienta, 2017 Toyota Sienta, Toyota Sienta, Sienta sienta, Toyota, Sienta, sienta, Used Toyota								

Compare

Save this search criteria, to get email alerts whenever a match is found.

AC AUTOMOTIVE PTE LTD

1 BUKIT BATOK CRESCENT WCEGA PLAZA #05-36 S658064
 CONTACT: 8181 3556 EMAIL: ENQUIRY@ALTITUDELEASING.COM.SG

R95-9363 2266

with Part
 19/2/20
 L/S
 R/ AC S/L
 10 days
 6/3/2020

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

VEHICLE NO.: SLV1467Y
 CHASSIS NO.: NHP1707100324
 ENGINE NO.:
 MAKE: TOYOTA
 MODEL: SIENTA

Steve (CLKK)

REPLACEMENT OF DAMAGED PARTS

S/NO.	QTY	DESCRIPTION	UNIT (\$)	AMOUNT(\$)
1	1	REAR BUMPER / DD (Empire Supp, Lower LH, RH)	\$ 1,382.00	\$ 1,382.00
2	1	PANEL, BODY LOWER BACK (lower part trim) / CPN	\$ 380.00	\$ 380.00
3	1	QUARTER PANEL, REAR LOWER (Tailgate apron) / BK	\$ 296.00	\$ 296.00
4	1	REAR MEMBER SUB-ASSY / DD (X-Member)	\$ 555.00	\$ 555.00
5	1	REINFORCEMENT, REAR FLOOR PAN (floor floor trim) / CPN	\$ 250.00	\$ 250.00
6	1	PANEL SUB-ASSY, BODY LOWER BACK / CPN (floor trim)	\$ 1,328.00	\$ 1,328.00
7	1	MEMBER SUB-ASSY, REAR FLOOR REAR CROSS X MM	\$ 580.00	\$ 580.00
8	1	PAN, REAR FLOOR (floor floor) / DD	\$ 780.00	\$ 780.00
9	2	DAM, BACK WINDOW GLASS ADHESIVE / APC	\$ 48.00	\$ 96.00
10	1	WEATHERSTRIP, BACK DOOR / TN	\$ 280.00	\$ 280.00
11	2	MOULDING, BACK WINDOW / APC (gates moulding)	\$ 454.00	\$ 908.00
12	1	GLASS, BACK DOOR X MM	\$ 495.00	\$ 495.00
13	1	PANEL SUB-ASSY, BACK DOOR (Tailgate) / DD	\$ 1,982.00	\$ 1,982.00
14	1	BOARD ASSY, BACK DOOR TRIM (Tailgate trim) / CPN	\$ 382.00	\$ 382.00
15	1	BACK DOOR HINGE X MM	\$ 376.00	\$ 376.00
16	1	LOCK ASSY (Tailgate) / BT	\$ 832.00	\$ 832.00
17	1	END PANEL / DD	\$ 574.00	\$ 574.00
18	1	END PANEL INNER / DD	\$ 820.00	\$ 820.00
19	1	KEYLESS SENSOR / BK	\$ 240.00	\$ 240.00
20	1	TOYOTA PANEL (Tailgate) / APC	\$ 120.00	\$ 120.00
21	1	SIENTA WORDS (Tailgate) / APC	\$ 140.00	\$ 140.00
22	2	REAR PARKING SENSOR / Sport	\$ 187.00	\$ 374.00
23	1	REAR REVERSE PARKING CAMERA X MM	\$ 180.00	\$ 180.00
SUBTOTAL BEFORE DISCOUNT				\$ 13,350.00
PERCENTAGE DISCOUNT 25%				\$ 3,337.50
SUBTOTAL				\$ 10,012.50

1075 ✓
 207 ✓
 225 ✓
 182 ✓
 (LH RH) ✓
 572 ✓
 X
 49 ✓
 168 ✓
 X
 1186 ✓
 288 ✓
 X
 468 ✓
 544.60 ✓
 161.60 ✓
 60 ✓
 60 ✓
 200 ✓
 X
 7321.20
 -25%
 5499.90

Supp — Tail lamp LH & RH \$ 734 — CUT
 Tailgate lamp LH & RH \$ 786 — CUT
 Boot Side trim LH & RH \$ 800 — BK
 2320
 -25%
 1749

LABOUR CHARGES

24	1	TO PROVIDE TOWING CHARGES	\$ 60.00
25	1	TO FIX & DISMANTLE AFFECTED REAR	\$ 1,000.00
26	1	TO APPLY ANTI RUST COAT & AFFECTED AREA	\$ 120.00
27	1	CHECK WIRING	\$ 120.00
28	1	SPRAY PAINTING FOR AFFECTED PANEL	\$ 1,600.00
29	1	TO APPLY WATER PROOFING SEALER ON END PANELS	\$ 120.00
30	1	TO FIX REVERSE SENSOR ASSY	\$ 100.00
31	1	TO REMOVE/REINSTALL REAR TAILGATE WINDSCREEN	\$ 150.00
TOTAL LABOUR			\$ 3,270.00

50/
30/
1000/
30/
30/
50/
2250

TOTAL COST OF REPAIRS + LABOUR

\$ 13,282.50

P- 5492.90
 Supp- 1749
 L- 2250
 9480.90
 L/S- 7584.72
 = 7690

15022-50

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	17 Feb 2020		18 Feb 2020 16:57 Edit Adj Rpt	S\$7,600.00 Edit Estimates	S\$7,600.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by Insurer]							
Insured:	- Co. Reg. No.: -								
Main Claimant:	CLT LEASING PTE. LTD., Co. Reg. No.: 201717731M								
Vehicle Reg. No.:	SLV1467Y	Date of Loss:	14/02/2020 10:00 - :59 [25 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM20D200846	Policy/Cover Note No.:	DMCVSN30390219000						
Vehicle Reg. No. (Insured):	GB85352S	Policy No. (Claimant):	5111279474 (PREMIUM)						
		Excess:	S\$0.00						
Repairer:	- Not Applicable - (-)								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Cecilia Low - 63896530]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by CHEN TSUE YEE] ... [Final Rpt due 27/02/2020]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLV1467Y (SNM20D200846)
[GBB5352S]
TP
CLT LEASING PTE. LTD.
Feb 14 2020 10:00AM
[-]

Upload Documents Upload Photos Compose New Letter			View <input type="button" value="View in Browser"/>
Photos/Images			3 per page <input type="button" value="v"/> <input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail Print
1	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
2	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
3	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
4	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
5	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
6	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
7	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
8	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
9	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
10	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
11	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
12	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
13	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
14	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
15	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
16	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
17	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
18	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
19	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
20	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
21	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
22	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
23	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
24	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
25	19/02/20 20:09	Odometer Reading	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
26	19/02/20 20:09	Chassis Number	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
27	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
28	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
29	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
30	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
31	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
32	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
33	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
34	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
35	19/02/20 20:09	General View	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
36	05/03/20 18:28	Photographs of Damaged Parts	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
37	05/03/20 18:28	Photographs of Damaged Parts	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>
38	05/03/20 18:28	Photographs of Damaged Parts	<input checked="" type="checkbox"/> Load JPG <input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
39	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
40	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
41	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
42	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
43	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
44	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
45	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
46	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
47	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
48	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
49	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
50	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
51	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
52	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
53	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
54	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
55	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
56	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
57	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
58	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
59	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
60	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
61	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
62	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
63	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
64	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
65	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
66	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
67	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
68	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
69	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
70	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
71	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
72	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
73	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
74	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
75	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
76	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
77	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
78	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
79	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
80	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
81	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
82	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
83	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
84	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
85	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
86	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>
87	05/03/20 18:28	Photographs of Damaged Parts	 Load JPG	<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
89	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
90	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
91	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
92	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
93	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
94	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
95	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
96	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
97	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
98	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
99	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
100	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
101	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
102	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
103	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
104	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
105	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
106	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
107	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
108	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
109	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
110	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
111	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
112	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
113	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
114	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
115	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
116	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
117	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
118	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
119	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
120	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
121	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
122	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
123	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
124	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
125	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
126	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
127	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
128	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
129	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
130	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
131	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
132	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
133	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
134	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
135	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
136	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>
137	05/03/20 18:28	Photographs of Damaged Parts		<input checked="" type="checkbox"/>

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	05/03/20 18:28	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
139	05/03/20 18:28	Photographs of Damaged Parts		Load JPG <input checked="" type="checkbox"/>
140	09/03/20 18:04	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
141	09/03/20 18:04	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
142	09/03/20 18:04	After Repair Photo		Load JPG <input checked="" type="checkbox"/>

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	15/02/20 11:09	Accident Statement		Load HTM

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	15/02/20 11:08	Accident Photo		Load JPG <input checked="" type="checkbox"/>
2	15/02/20 11:08	Accident Photo		Load JPG <input checked="" type="checkbox"/>
3	15/02/20 11:08	Driving License		Load JPG <input checked="" type="checkbox"/>
4	15/02/20 11:08	Accident Photo		Load JPG <input checked="" type="checkbox"/>
5	15/02/20 11:08	Accident Photo		Load JPG <input checked="" type="checkbox"/>
6	15/02/20 11:08	Accident Photo		Load JPG <input checked="" type="checkbox"/>
7	15/02/20 11:08	Accident Photo		Load JPG <input checked="" type="checkbox"/>
8	15/02/20 11:08	Accident Photo		Load JPG <input checked="" type="checkbox"/>
9	15/02/20 11:08	Accident Photo		Load JPG <input checked="" type="checkbox"/>
10	15/02/20 11:08	Accident Photo		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	VAC (Bukit Batok)	Thumbnail	Print
1	15/02/20 11:04	Sketch Plan		Load TIF
2	15/02/20 11:04	Sketch Plan #2		Load TIF
3	15/02/20 11:04	Sketch Plan #3		Load TIF
4	15/02/20 11:04	Sketch Plan #4		Load TIF
5	15/02/20 11:04	Sketch Plan #5		Load TIF
6	15/02/20 11:04	Sketch Plan #6		Load TIF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20002837/EYF3E2

Date: 16/03/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSN30390219000

Claimant Vehicle No: SLV1467Y Insured Vehicle No: GBB5352S

Date of Loss: 14/02/2020 Nature of Claim: TP Claim No: SNM20D200846

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLV1467Y Engine No: 1NZ8292693

Make & Model: TOYOTA SIENTA, 1.5 (A) Chassis No: NHP1707100324

Reg. Date: 22/12/2017 (Man. Year: 2017) Odometer: 188312 km

Colour: Silver

Engine Capacity: 1498 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15

Front Left Side: Sincera 5 mm Rear Left Side: Sincera 5 mm

Front Right Side: Sincera 5 mm Rear Right Side: Sincera 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,752.50	7,230.90	4,521.60	38.47
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,270.00	2,250.00	1,020.00	31.19
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,022.50	9,480.90	5,541.60	36.89
Approved Total (Overridden) (S\$)		7,600.00		
Nett Amount (S\$)	15,022.50	7,600.00	7,422.50	49.41

INSPECTION

Date of Assignment: 18/02/2020

Date Inspected: 19/02/2020 Inspected At: ALTITUDE CAR LEASING
1 BUKIT BATOK CRESCENT
WCEGA PLAZA #05-38
SINGAPORE 658064

Estimated Period of Repair: 10.0 days

Adjuster: CHEN TSUE YEE

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 16 Mar 2020)	
Parts: M1-MPV	TOYOTA SIENTA 1.5 (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLV1467Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.		

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	1,382.00 FL	*1,075.00 FL
2	1		*PANEL, BODY LOWER BACK	Crushed	380.00 FL	*207.00 FL
3	1		*QUARTER PANEL, REAR LOWER	Broken	296.00 FL	*225.00 FL
4	1		*REAR MEMBER SUB-ASSY	Dented	555.00 FL	*182.00 FL
5	1		*REINFORCEMENT, REAR FLOOR PAN	Crushed	250.00 FL	*250.00 FL
6	1		*PANEL SUB-ASSY, BODY LOWER BACK	Crushed	1,328.00 FL	*572.00 FL
7	1		*MEMBER SUB-ASSY, REAR FLOOR REAR CROSS	Not Necessary	580.00 FL	*- FL
8	1		*PAN, REAR FLOOR	Dented	780.00 FL	*780.00 FL
9	2		*DAM, BACK WINDOW GLASS ADHESIVE	Necessary	96.00 FL	*40.00 FL
10	1		*WEATHERSTRIP, BACK DOOR	Torn	280.00 FL	*280.00 FL
11	2		*MOULDING, BACK WINDOW	Necessary	908.00 FL	*168.00 FL
12	1		*GLASS, BACK DOOR	Not Necessary	495.00 FL	*- FL
13	1		*PANEL SUB-ASSY, BACK DOOR	Dented	1,982.00 FL	*1,186.00 FL
14	1		*BOARD ASSY, BACK DOOR TRIM	Crushed	382.00 FL	*288.00 FL
15	1		*BACK DOOR HINGE	Not Necessary	376.00 FL	*- FL
16	1		*LOCK ASSY	Bent	832.00 FL	*468.00 FL
17	1		*END PANEL	Dented	574.00 FL	*574.00 FL
18	1		*END PANEL INNER	Dented	820.00 FL	*544.60 FL
19	1		*KEYLESS SENSOR	Broken	240.00 FL	*161.60 FL
20	1		*TOYOTA PANEL	Necessary	120.00 FL	*60.00 FL
21	1		*SIENTA WORDS	Necessary	140.00 FL	*60.00 FL
22	2		*REAR PARKING SENSOR	Shorted	374.00 FL	*200.00 FL
23	1		*REAR REVERSE PARKING CAMERA	Not Necessary	180.00 FL	*- FL
24	2		*TAILLAMP LH & RH	Cut	734.00 FL	*734.00 FL
25	2		*TAILGATE LAMP LH & RH	Cut	786.00 FL	*786.00 FL
26	2		*BOOT SIDE TRIM LH & RH	Broken	800.00 FL	*800.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	15,670.00	9,641.20
- List Item Discount on L Items 25.00/25.00% (S\$)	3,917.50	2,410.30
Total Parts (S\$)	11,752.50	7,230.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING CHARGES	New	60.00	60.00
2	TO FIX & DISMANTLE AFFECTED REAR	New	1,000.00	1,000.00
3	TO APPLY ANTI RUST COAT & AFFECTED AREA	New	120.00	50.00
4	CHECK WIRING	New	120.00	30.00
5	SPRAY PAINTING FOR AFFECTED PANEL	New	1,600.00	1,000.00
6	TO APPLY WATER PROOFING SEALER ON END PANELS	New	120.00	30.00
7	TO FIX REVERSE SENSOR ASSY	New	100.00	30.00
8	TO REMOVE / REINSTALL REAR TAILGATE WINDSCREEN	New	150.00	50.00
Gross Labour Cost (S\$)			3,270.00	2,250.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >