

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7996A

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

19 FEB 2020

PART

- 1 FRONT BUMPER
- 1 BRACKET, FRONT BUMPER EXTENSION MOUNTING
- 1 REINFORCEMENT, FRONT BUMPER
- 1 REINFORCEMENT, FRONT BUMPER, NO.2
- 1 COVER, FRONT BUMPER HOLE, RH
- 1 ABSORBER, FRONT BUMPER, LOWER
- 1 ABSORBER, FRONT BUMPER ENERGY
- 1 FRONT BUMPER SIDE RETAINER RH
- 1 COVER SUB-ASSY, ENGINE, NO.1
- 1 COVER SUB-ASSY, ENGINE UNDER, NO.2
- 1 EXTENSION, FRONT BUMPER, RH
- 1 FRONT LED LAMP (LOWER) RH
- 1 FRONT HEADLAMP RH
- 1 COMPUTER SUB-ASSY, HEADLAMP, RH NO.1
- 1 MOTOR, HEADLAMP LEVELING, RH
- 1 FRONT FENDER RH
- 1 LINER, FRONT FENDER, RH
- 1 EMBLEM, SIDE PANEL
- 1 PROTECTOR, FRONT FENDER SIDE PANEL, RH
- 1 SEAL, FENDER APRON MUDGUARD, RH
- 1 COVER SUB ASSY, FRONT PILLAR, UPR RH
- 1 GRILLE SUB-ASSY, RADIATOR
- 1 GRILLE, RADIATOR, LOWER NO.1
- 1 EMBLEM ASSY, ~~RADIATOR~~ GRILLE
- 1 FRONT BONNET
- 1 HINGE ASSY, HOOD, RH
- 1 LOCK ASSY, HOOD
- 1 BRACE, HOOD LOCK SUPPORT

AAD2002-108*Not Notion**Resurvey B4 paint***SHB 7996A**

JTDKB3FU903080363

TOYOTA

PRIUS

15.2.2020

ERGO

24/05/2019

LIST

\$	<i>Tn</i>	516.00	✓
\$	<i>Rn</i>	103.40	X
\$	<i>Rn</i>	716.60	X
\$	<i>Rn</i>	246.10	X
\$	<i>Rn</i>	29.30	X
\$	<i>Rn</i>	132.70	X
\$	<i>Rn</i>	79.60	X
\$	<i>CM</i>	80.10	✓
\$	<i>Rn</i>	472.40	X
\$	<i>Rn</i>	241.90	X
\$	<i>Rn</i>	120.10	X
\$	<i>CM</i>	951.40	✓
\$	<i>ngcm</i>	2,637.60	✓
\$	<i>Rn</i>	960.50	X
\$	<i>Rn</i>	487.50	X
\$	<i>Rn</i>	977.80	✓
\$	<i>CM</i>	206.70	✓
\$	<i>Rn</i>	54.60	✓
\$	<i>Rn</i>	93.90	X
\$	<i>Rn</i>	51.90	X
\$	<i>Rn</i>	100.40	X
\$	<i>Rn</i>	346.00	X
\$	<i>Rn</i>	170.10	X
\$	<i>Rn</i>	90.80	✓
\$	<i>Rn</i>	983.10	X
\$	<i>Rn</i>	58.90	X
\$	<i>Rn</i>	135.00	X
\$	<i>Rn</i>	78.30	X

Trans-cab Auto Services Pte Ltd**AAD2002-108**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7996A

1 COVER, RADIATOR SUPPORT OPENING	\$	SL	235.30	}	X
1 WIRE, ENGINE ROOM MAIN	\$	SL	7,323.90		
1 SUPPORT SUB-ASSY, RADIATOR, RH	\$	SL	245.10		
1 SUPPORT SUB ASSY, RADIATOR, UPPER	\$	SL	377.10		
1 SUPPORT SUB ASSY, RADIATOR, LOWER	\$	SL	409.90		
1 SUPPORT, RADIATOR, UPPER RH	\$	SL	78.90	}	X
1 TANK, RESERVE SEALED W/O CAP	\$	SL	151.40		
1 JAR ASSY, WINDSHIELD WASHER	\$	SL	219.10	}	X
1 INLET SUB ASSY, WASHER	\$	SL	67.00		
1 MOTOR AND PUMP ASSY, WINDSHIELD WASHER	\$	SL	292.40		X
1 APRON SUB-ASSY, FRONT FENDER, RH	\$	SL	979.40		X
1 APRON ASSY, FRONT FENDER, RH	\$	SL	176.80		X
1 MEMBER, FRONT APRON TO COWL SIDE, LOWER FRONT RH	\$	SL	62.80		X
1 MEMBER, FRONT APRON TO COWL SIDE, UPPER RH	\$	SL	110.00		X
1 BRACE SUB-ASSY, FENDER APRON, RH	\$	SL	292.50		X
1 MEMBER SUB-ASSY, FRONT SIDE, RH	\$	SL	2,397.60		X
1 MEMBER SUB-ASSY, FRONT SIDE, INNER RH	\$	SL	794.70		X
1 PLATE, FRONT SIDE MEMBER, OUTER RH	\$		292.10	}	PUC X
1 GUIDE, RADIATOR AIR, NO.3	\$		112.70		
1 GUIDE, RADIATOR AIR, NO.1 RH	\$		65.30		
1 SEAL, RADIATOR TO SUPPORT, NO.2	\$		29.60		
1 HORN ASSY, HIGH PITCHED	\$		134.80		
1 CONDENSER ASSY, COOLER	\$		1,783.20		
1 SHAFT ASSY, FRONT DRIVE, RH	\$		1,379.50		
1 ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 RH	\$		760.10		
1 JOINT ASSY, LOWER BALL, FRONT RH	\$		283.40		
1 KNUCKLE, STEERING, RH	\$		663.40		
1 LINK ASSY, FRONT STABILIZER, RH	\$		237.10		
1 BAR, STABILIZER, FRONT	\$		367.30		
1 FRONT SHOCK ABSORBER	\$		438.30		
1 SUPPORT SUB-ASSY, FRONT SUSPENSION, RH	\$		236.40		
1 GEAR ASSY, STEERING	\$		1,955.40		
1 CROSSMEMBER SUB-ASSY, FRONT SUSPENSION	\$		2,585.50		
1 REINFORCEMENT SUB-ASSY, SIDE RAIL, REAR RH	\$		133.30		
1 MIRROR ASSY, OUTER REAR VIEW, RH	\$		1,436.60		
1 MOULDING ASSY, BODY ROCKER PANEL, RH	\$		594.80		

Trans-cab Auto Services Pte Ltd**AAD2002-108**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7996A

1	BRACKET, FRONT BUMPER SIDE, RH	\$	59.30	} <i>SH X</i>
1	BRACKET, HEADLAMP, RH	\$	34.80	
1	PANEL SUB ASSY, FRONT DOOR, RH	\$	1,300.70	
1	HINGE ASSY, FRONT DOOR, UPPER RH	\$	97.50	
1	HINGE ASSY, FRONT DOOR, LOWER RH	\$	110.60	
1	CHECK ASSY, FRONT DOOR	\$	183.80	
1	WEATHERSTRIP, FRONT DOOR, RH	\$	231.30	
1	TAPE, BLACK OUT, NO.1 RH	\$	13.30	
1	TAPE, BLACK OUT, NO.2 RH	\$	43.50	
1	TAPE, BLACK OUT, NO.3 RH	\$	26.30	
1	WIRE, FRONT DOOR, RH	\$	532.80	

TOTAL	\$	41,459.30
25%	\$	10,364.83
	\$	31,094.48

Special Nett

1	FRONT WHEEL RIM	\$	<i>SH</i> 1,879.40	<i>X</i>
1	FRONT WHEEL RIM COVER	\$	<i>SH</i> 211.50	<i>X</i>
1	FRONT TYRE 195/65/15	\$	<i>SH</i> 350.00	<i>X</i>
1SET	CLIP, FRONT FENDER LINER	\$	<i>SH</i> 35.00	<i>✓</i>
1	FRONT NUMBER PLATE WITH MOULDING	\$	<i>SH</i> 200.00	<i>X</i>
1SET	BUMPER CLIP FRT	\$	<i>SH</i> 66.00	<i>—</i>
1SET	FRONT BUMPER RETAINER CLIP	\$	<i>SH</i> 35.00	} <i>X</i>
1	FRONT RH DOOR STICKER "Trans-Cab"	\$	<i>SH</i> 100.00	
1	WINDSCREEN SEALANT	\$	<i>SH</i> 253.80	
1	FRONT WINDSCREEN MOULDING	\$	<i>SH</i> 160.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	<i>SH</i> 100.00	
1	WINDSCREEN MOULDING CLIP	\$	<i>SH</i> 30.00	
1SET	ROCKER PANEL MOULDING CLIP	\$	<i>SH</i> 35.00	

TOTAL	\$	3,455.70
--------------	-----------	-----------------

TOTAL PARTS	\$	34,550.18
--------------------	-----------	------------------

LABOUR

Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.

\$ *SH* 380.00 *X*

Trans-cab Auto Services Pte Ltd**AAD2002-108**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7996A

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	500
Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	800
To transfer of Fender fittings, attachments and perform water seepage test.	\$	170.00	X
To transfer of Front Bumper fittings, attachments and perform water seepage test.	\$	170.00	X
To transfer of Bonnet fittings, attachments and perform water seepage test.	\$	170.00	X
To Rust-Proofing Of The Affected Areas.	\$	170.00	300
To Check Electrical Lighting Concerned.	\$	170.00	200
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	380.00	X
To check ABS and brake efficiency, final checking and testing.	\$	380.00	X
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	X
To dismantle and refit engine cross-member and engine mounting.	\$	380.00	X

Trans-cab Auto Services Pte Ltd**AAD2002-108**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7996A

To transfer of door fittings, attachments and perform water seepage test.

\$ *na* 170.00 X

To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.

\$ 380.00 X

To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.

\$ 380.00 X

TOTAL \$ 19,240.00**Over All Total \$ 53,790.18****(PART-BY-PART) Repair Days***25 days**4 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: